



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBC 3748S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRT FENDER	CRACKED	185.00	185.00
2	FRT FORKS @\$680.00	NOT NECESSARY	1,360.00	-
1	FRT STEM	NOT NECESSARY	285.00	-
1	FRT STEM BEARING	NOT NECESSARY	80.00	-
1	RH FRT SIGNAL LAMP	CRACKED	85.00	85.00
1	RH HAND BAR	NOT NECESSARY	135.00	-
1	RH HAND BAR GRIP	NOT NECESSARY	38.00	-
1	RH HAND BAR BALANCER	CUT	35.00	35.00
1	RH SIDE MIRROR	CUT	38.00	38.00
1	SET FAIRING	CUT	1,000.00	600.00
1	REAR FOOTREST	CUT	75.00	75.00
1	REAR FOOTREST BRACKET	CRACKED	195.00	195.00
1	REAR SWING ARM	BENT	385.00	385.00
1	SET REAR SWING ARM BUSHES	NECESSARY	100.00	50.00
1	REAR EXHAUST PIPE	TO REPAIR SEE LABOUR	1,200.00	-
1	FRT RH FOOTREST	CUT	350.00	80.00
1	REAR SWING ARM STUD	BENT	200.00	80.00
	LESS 10% DISCOUNT		-	-180.80
			5,746.00	1,627.20
	<b><u>LABOUR</u></b>			
	CHASSIS ALIGNMENT.		350.00	200.00
	SPRAY PAINT (ORIGINAL TO GREEN).		400.00	200.00
	LABOR. INCLUSIVE OF THE REPAIR OF REAR EXHAUST PIPE.		400.00	200.00
			1,150.00	600.00
	<b>GRAND TOTAL</b>		<b>6,896.00</b>	<b>2,227.20</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,750.00
---	--	--	----------

Report Ref No. CS/GAI20003609/Avd3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.