Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20003620/UBS3Q2

Date: 07/12/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant Insured Vehicle No: SHA7815U SLD1707A

Vehicle No:

Date of Loss: 05/03/2020 Nature of Claim: ΤP Claim No: MCT20030082

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLD1707A Reg No:

Make & Model: TOYOTA SIENTA, 1.5 G (A) Engine No: 2NR8603221 Reg. Date: 06/06/2016 (Man. Year: 2016) Chassis No: NSP1707027829 Colour: Odometer: 62399 km White

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15 Rear Left Side: Front Left Side: Yokohama 6 mm Yokohama 6 mm Front Right Side: Rear Right Side: Yokohama 6 mm Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,750.40	10,507.52	18,242.88	63.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,000.00	2,190.00	1,810.00	45.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,750.40	12,697.52	20,052.88	61.23
Approved Total (Overridden) (S\$)		10,000.00		
Nett Amount (S\$)	32,750.40	10,000.00	22,750.40	69.47
+ Car Rental (4.0 x S\$150.00/day) (S\$)		600.00		
Net	tt Liability (S\$)	10,600.00		

INSPECTION

Date of Assignment: 05/03/2020

Date Inspected: 05/03/2020 Inspected At: Choo Motor Spray Painter (HQ)

1 Kaki Bukit Avenue 6, #01-39

AutoBay @ Kaki Bukit Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA Manager: CHUA ZHEN LI Adjuster Report Page 2 of 5

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Jun 2020)

Parts: M1-MPV TOYOTA SIENTA 1.5 G (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLD1707A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented / Buckled	1,288.20 F	*822.10 FL
2	2		*BONNET HINGES	Bent	332.00 F	*210.00 FL
3	1		*BONNET INNER RUBBER	Not Necessary	45.00 F	*- FL
4	1		*BONNET LOCK	Twisted	205.00 F	*166.20 FL
5	1		*BONNET INSULATOR	Not Necessary	288.20 F	*- FL
6	1		*BONNET INSULATOR CLIPS	Not Necessary	50.00 F	*- FL
7	1		*FRONT BUMPER	Distorted / Torn	1,155.30 F	*679.00 FL
8	2		*FRONT BUMPER SIDE RETAINERS	Bent	133.00 F	*133.00 FL
9	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	288.00 F	*-FL
10	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
11	1		*FRONT BUMPER OUTER BLACK GARNISHS	O/S Grazed	630.20 F	*214.00 FL
12	1		*FRONT BUMPER FOG LAMPS	O/S Cracked	976.40 F	*355.10 FL
13	2		*FRONT BUMPER FOG LAMP BRACKETS	No such part	210.00 F	*-FL
14	1		*FRONT BUMPER REINFORCEMENT	Dented	665.10 F	*485.10 FL
15	1		*FRONT BUMPER GRILLE	Torn	605.10 F	*605.10 FL
16	1		*FRONT BUMPER GRILLE OUTER CHROME MOULDING	Cracked	489.30 F	*489.30 FL
17	1		*FRONT GRILLE INNER	No such part	350.00 F	*-FL
18	1		*FRONT LOGO	Necessary	85.00 F	*78.50 FL
19	1		*FRONT TOW COVER	Grazed	45.00 F	*32.00 FL
20	1		*FRONT BUMPER INNER TOP RUBBER	Necessary	88.20 F	*88.20 FL
21	1		*FRONT BUMPER UNDER COVER	Torn	366.20 F	*288.30 FL
22	1		*WIPER WASHER TANK	Serviceable	319.80 F	*-FL
23	1		*FRONT SUPPORT PANEL	Bent / Twisted	1,221.10 F	*745.10 FL
24	1		*FRONT BUMPER SPONGE	Torn	288.50 F	*128.50 FL
25	1		*FRONT BUMPER TOP RETAINER	Bent	299.30 F	*205.10 FL
26	1		*FRONT BUMPER INNER O/S GARNISH	Deformed	88.90 F	*88.90 FL
27	2		*HEADLAMPS LED	Holder Cracked	5,600.00 F	*5,600.00 FL
28	1		*AIR CON CONDENSER	Bent / Punctured	1,550.00 F	*1,125.10 FL
29	1		*RADIATOR	Bent / Punctured	1,880.10 F	*1,288.10 FL
30	1		*RADIATOR FAN ASSY	Not Necessary	971.10 F	*-FL
31	2		*FRONT FENDERS	Repair	1,238.20 F	*-FL
32	2		*FRONT FENDERS VVTI EMBLEMS	Not fitted	133.00 F	*-FL
33	2		*FRONT FENDER INNERSHIELDS	Not Necessary	410.20 F	*- FL
34	1		*AIR CLEANER BOX	Not Necessary	855.20 F	*-FL
35	1		*EXHAUST HEAT COVER	Not Necessary	232.50 F	*- FL
36	1		*INLET MANIFOLD	Not Necessary	1,800.00 F	*-FL
37	1		*ALTERNATOR	Not Necessary	1,995.10 F	*-FL
38	1		*FRONT CHASSIS MEMBER	Repair	1,050.00 F	*-FL
39	1		*FRONT LICENCE PLATE W/HOLDER	Broken / Missing	50.00 FS	*40.00 FS
	Report was unsubmitted during this print-out.					

Adjuster Report Page 4 of 5

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*BOL RADIATOR COOLAN	T Necessary	50.00 FS	*30.00 FS
41	1		*BOL AIR CON OIL	Necessary	50.00 FS	*30.00 FS
42	1		*WIPER GARNISH	Not Necessary	322.20 F	*- FL
F=Fra	inchise	part. S=S	pcNett. L=ListItemDisc. - List I	Sub Total (S\$) tem Discount on L Items 0.00/25.00% (S\$)	-	13,976.70 3,469.18
				Total Parts (S\$)	28,750.40	10,507.52
			Report wa	s unsubmitted during this print-out.		

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING	New	80.00	30.00
2	TO REFILL AIR CON GAS	New	120.00	100.00
3	TO SPRAY RUST PROOFING	New	120.00	60.00
4	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
5	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,800.00	1,000.00
6	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,000.00
	Gross Labo	ur Cost (S\$)	4,000.00	2,190.00
	Report was unsubmitted dur	ing this print-out		

< END OF ESTIMATES >