

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20003627/EGS3Q2

Date: 14/09/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
Claimant Vehicle No :	SLK4811A	Insured Vehicle No :	GBH206H
Date of Loss:	03/03/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0000587

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK4811A	Engine No:	HR12214766B
Make & Model:	NISSAN NOTE, 1.2 (A)	Chassis No:	JN1TAAE12Z0972566
Reg. Date:	18/01/2017 (Man. Year: 2016)	Odometer:	26528 km
Colour:	White		
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,890.30	1,811.78	3,078.52	62.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,433.00	2,470.00	1,963.00	44.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	9,323.30	4,281.78	5,041.52	54.07
+ GST 7.00/7.00% (\$\$)	652.63	299.72	352.91	54.08
Nett Amount (\$\$)	9,975.93	4,581.50	5,394.43	54.07
+ Loss of Use (5.0 x S\$50.00/day) (\$\$)		250.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		4,838.95		

INSPECTION

Date of Assignment:	04/03/2020	
Date Inspected:	05/03/2020 Inspected At:	Tan Chong Motor Sales Pte Ltd (Bukit Timah)
		911, Bukit Timah Road
		Singapore 589622
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Aug 2020)
Parts:	144	NISSAN NOTE 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK4811A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MOTOR ASSY -REGU LH REAR	Not Necessary	568.10 FN	*- FN
2	1		*REGULATOR -DOOR LH REAR	Not Necessary	96.20 FN	*- FN
3	1		*TAPE -RR DOOR ,LH	Necessary	19.50 FN	*19.50 FN
4	1		*TAPE -RR DOOR ,LH	Necessary	25.50 FN	*25.50 FN
5	1		*DOOR -REAR LH	Dented	919.60 FN	*919.60 FN
6	1		*STRIKER LH FRONT DOOR	Not Necessary	59.70 FN	*- FN
7	1		*LOCK & REMOTE C LH FRONT	Bent	189.50 FN	*189.50 FN
8	1		*GRIP-OUTSIDE LH FRONT	Cut	98.40 FN	*98.40 FN
9	1		*ESCUT-OUTSIDE HANDLE LH FRONT	Cut	19.50 FN	*19.50 FN
10	1		*MOTOR ASSY -REG LH FRONT	Not Necessary	568.10 FN	*- FN
11	1		*REGULATOR -DOOR LH FRONT	Not Necessary	137.30 FN	*- FN
12	1		*TAPE-FR DOOR ,LH	Necessary	19.50 FN	*19.50 FN
13	1		*TAPE-FR DOOR ,LH	Necessary	19.50 FN	*19.50 FN
14	1		*DOOR -FRONT LH	Dented	919.60 FN	*919.60 FN
15	1		*GASKET HANDLE OUTSIDE LH FRONT	Necessary	2.40 FS	*2.40 FS
16	1		*GASKET HANDLE DOOR LH FRONT	Necessary	4.90 FS	*4.90 FS
17	1		*BUSH SHOCK ABS	Not Necessary	16.20 FS	*- FS
18	1		*TUBE-DISTANCE	Not Necessary	12.80 FS	*- FS
19	1		*BUSH SHOCK ABS	Not Necessary	16.20 FS	*- FS
20	1		*BUMPER -SUSPENS	Not Necessary	91.30 FS	*- FS
21	1		*ABSORBER -SHOCK	Not Necessary	60.30 FS	*- FS
22	1		*SEAT SPRING UPPER	Not Necessary	22.90 FS	*- FS
23	1		*SEAT SPRING LOWER	Not Necessary	15.60 FS	*- FS
24	1		*BEAM	Not Necessary	1,018.10 FS	*- FS
25	1		*SPINDLE -REAR	Not Necessary	73.50 FS	*- FS
26	1		*A BRG RR WHEEL	Not Necessary	88.10 FS	*- FS
27	1		*185/65R15OE CONTI-CC5 LH REAR	Not Necessary	160.00 FS	*- FS
28	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
29	1		*ALLOY RIM LH REAR	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	5,622.30	2,257.90
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	732.00	446.12
Total Parts (\$\$)	4,890.30	1,811.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	New	120.00	120.00
2	TO RENEW REAR MULT LINK BEAM	New	240.00	0.00
3	REMOVE/REFIX WHOLE UNDERCARRIAGE MECHANICAL PARTS PER SIDE LH REAR	New	480.00	0.00
4	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	New	300.00	200.00
5	CHECK WHEEL ALIGNMENT ,ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE	New	103.00	0.00
6	REPAIR LH REAR FENDER ,LH CENTER PILLAR AND RENEW LH FRONT /REAR DOOR	New	1,500.00	975.00
7	S/PAINT LH REAR FENDER ,LH CENTER PILLAR ,LH FRONT /REAR DOOR	New	1,500.00	1,000.00
8	RENEW LH REAR S/RIM AND CONDUCT WHEEL BALANCING	New	15.00	0.00
9	TRANSFER LH FRONT /REAR DOOR MECHANICAL PARTS TO NEW DOOR	New	120.00	120.00
10	R/I REVERSE SENSOR TO ASSIST REPAIR	New	55.00	55.00
Gross Labour Cost (\$\$)			4,433.00	2,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >