



Your Ref: 20.27688

Date: 11<sup>th</sup> March 2020

Our Ref : CS3/ASM19007174/R1vd3e2-1

**M/s AXA Insurance Pte Ltd**

C/O: Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: JQN 1638**

**INSURED VEHICLE: SKN 3512R**

**ACCIDENT DATE: 22/04/2019**

We thank you for your instruction on 04/03/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of JQN 1638 from M/s C L Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicles SKN 3512R.
- c) Police Report of Vehicles JQN 1638 and SKN 3512R.
- d) Final Repair Bill of JQN 1638 from M/s Teamwork Garage Pte Ltd.
- e) Colour damaged vehicle photographs of JQN 1638.

Pre-Repair Inspection Date : 23/04/2019 at M/s Teamwork Garage Pte Ltd, 53 Ubi Avenue 1 #01-24, Singapore 408934.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: JQN 1638
Make & Model	: Yamaha 135LC
Year of Registration	: 2014
Engine Capacity	: 135 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.