

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20003634/QBS3Q2

**Date:** 03/11/2020

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100501737  
**Claimant**  
**Vehicle No :** SLM5551H **Insured Vehicle No :** SLG3233X  
Date of Loss: 03/03/2020 Nature of Claim: TP Claim No: 8950617109SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM5551H**  
Make & Model: HONDA VEZEL, 1.5 HYBRID X (A) Engine No: LEB5918335  
Reg. Date: 31/03/2017 (Man. Year: 2017) Chassis No: RU31218325  
Colour: Silver Odometer: 202506 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

#### CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
Front Left Side: Giti 5 mm Rear Left Side: Giti 5 mm  
Front Right Side: Giti 5 mm Rear Right Side: Giti 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,815.68	1,326.64	1,489.04	52.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,740.00	1,180.00	1,560.00	56.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,555.68</b>	<b>2,506.64</b>	<b>3,049.04</b>	<b>54.88</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,000.00</b>		
<b>(S\$)</b>	5,555.68	2,000.00	3,555.68	64.00
<b>+ GST 7.00/7.00% (S\$)</b>	388.90	140.00	248.90	64.00
<b>Nett Amount (S\$)</b>	<b>5,944.58</b>	<b>2,140.00</b>	<b>3,804.58</b>	<b>64.00</b>
<b>+ Loss of Use (5.0 x S\$70.00/day) (S\$)</b>		350.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,492.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,400.00</b>		

#### INSPECTION

Date of Assignment: 05/03/2020  
Date Inspected: 05/03/2020 Inspected At: Lion City Rentals Pte Ltd (HQ)  
1090 LOWER DELTA ROAD #05-12  
Singapore 169201  
Estimated Period of Repair: 3.0 days

---

**Adjuster:** OI SUN PIN

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,450.00 FL	*1,100.00 FL
2	1		*REAR TAILGATE BACK DOOR TRIM BOARD	Serviceable	580.00 FL	*- FL
3	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	86.80 FL	*86.80 FL
4	1		*REAR TAILGATE HONDA EMBLEM	Serviceable	81.30 FL	*- FL
5	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	84.00 FL	*84.00 FL
6	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	195.00 FL	*100.00 FL
7	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	155.00 FL	*- FL
8	1		*SET REAR BUMPER CLIPS	Serviceable	180.00 FS	*- FS
9	1		*SET END PANEL TOP GARNISH CLIPS	Serviceable	80.00 FS	*- FS
10	1		*REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
11	1		*WINDSCREEN SEALANT	Necessary	200.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,342.10</b>	<b>1,600.80</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	526.42	274.16
<b>Total Parts (\$\$)</b>	<b>2,815.68</b>	<b>1,326.64</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO LABOUR CHARGE FOR REMOVING REAR TAILGATE ,REAR END PANEL,REAR BUMPER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	900.00	500.00
2	TO RESPRAY REAR TAILGATE ,END PANEL AND REAR BUMPER	New	800.00	500.00
3	TO REMOVE AND INSTALL REAR TAILGATE GLASS	New	160.00	120.00
4	TO APPLY RUSTPROOFING ON ALL DAMAGED PARTS	New	180.00	30.00
5	TO CHECK WIRING SYSTEM	New	100.00	30.00
6	TO CONDUCT A STANDARD OF OPEARING PROCEDURES POST REPAIR SCAN TEST AS A REQUIREMENTS UPON COMPLETION OF COLLISION REPAIRS	New	300.00	0.00
7	TO DEACTIVATE AND ACTIVE HIGH VOLTAGE HYBRID BATTERY AS A SAFETY PRECAUTIONS	New	300.00	0.00
			<b>Gross Labour Cost (S\$)</b>	<b>1,180.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >