



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 6250K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u>	NECESSARY		
	SUNDRIES (SN)		40.00	40.00
			40.00	40.00
	<u>LABOUR</u>			
	TO REMOVE AND INSTALL REAR BUMPER AND REAR RIGHT FENDER ATTACHMENT INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY ACCIDENT.		1,700.00	850.00
	PAINTING REAR BUMPER AND REAR RIGHT FENDER.		1,923.00	885.00
	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT AND REAR SECTIONS FOR PROPER FUNCTION.		177.00	150.00
			3,800.00	1,885.00
GRAND TOTAL			3,840.00	1,925.00
RECOMMENDED COST OF REPAIRS				1,925.00

Report Ref No. CS4/MSG20003636/Dtf3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.