

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 7/P % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 3MC 6250K Yr Regn: July 2018Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 116D C.C. 1496Colour: Black A/C: Insured / Std / NI / NASp. Reading: 13390 T/Radio: Insured / Std / NI / NAEng/No: 32305238 B37D15AC/No: WBAIV720505*G87653Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R16R: " "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bridgestone

Front

Rear

R/Bal. S mm R/Bal. S mmL/Bal. S mm L/Bal. S mmD.O.A. 29/04/2019 D.O.I. 20/08/2019Survey held at PML Alexandria

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/8 Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MSG SKN 1352 Z

PART BY PART \$1925, 3DAYS (RED:1915:49%)

INVESTIGATION PLUS SURVEY

EMAIL REPORT TO HUEY NI

EMAIL: HueyNi_Eng@sg.msg-asia.com

Date/Time, File Pass to?



Preli. Report

1) 2/6/2020



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S+RS, SI

Photos

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$800



Weekend (\$

Report Format :

Lump Sum / L.B.I: (\$ 1925 P/P)

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

30 APR 2019

Estimate No. : b1 51043
Date Estimated : 30/04/2019
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Melati Tani
383 Tanglin Road
#04-05
Singapore
Singapore 247966

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMC6250K	5G87653	13/07/2018	116d	0

DESCRIPTION

To remove and install rear bumper and rear right fender attachment including to knock out dented area caused by accident.

VALUE
1,200.00

850.00

Painting rear bumper and rear right fender.

1,823.00

885.00

To check electrical wiring system at the front and rear sections for proper function

177.00

150.00

Sundries.

40.00

✓

Total Labour 1: 3,840.00

20/08/2019 @ 1430hrs 1925.00

not actual

P/Part. 3 days.

yan

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



acknowledged by Repairer

Signature:

Date:

Labour 1	:	3,840.00
Parts	:	0.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	268.80
Grand Total	:	4,108.80

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 51043**
Date Estimated : **30/04/2019**
Prepared By : **Gary Poh Chai Hoon**

- ESTIMATE REPAIR FOR -

Melati Tani
383 Tanglin Road
#04-05
Singapore
Singapore 247966

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMC6250K	WBA1V720505G876	13/07/2018	116d	0

DESCRIPTION	ACCOUNT:		
	ORIGINAL PRICE	DISC. %	NETT
To make good rear right fender and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.	850.00	0	850.00
To respray rear right fender.	885.00	0	885.00
To check electrical wiring system at the front and rear sections for proper function	150.00	0	150.00
Sundries.	40.00	0	40.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
				#
				#
				#

Total Labour :	1,925.00
Total Parts :	0.00
Total Labour & Parts :	1,925.00
GST @7%:	134.75
Grand Total :	2,059.75

LOSS OF USE = \$60 X 3 DAYS
GIA SEARCH FEE - \$2.00