



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2004655  
INV Date 30/06/2020  
Reference CC4/FCI20003639/Uea3q2  
Code FCI2



#### PROFESSIONAL SERVICE FEE

Vehicle No. SMP 463J  
Insured Veh. SHC 212U  
Claim No. D20001302MFSH  
Policy No. D-20094921MFSH  
Accident Date 02/03/2020  
Inspection Date 05/03/2020

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 600.00        |
| <b>Subtotal</b>                | <b>600.00</b> |
| <b>GST (7%)</b>                | <b>42.00</b>  |
| <b>Grand Total</b>             | <b>642.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20003639/Uea3q2

36 ROBINSON ROAD  
#16-01 CITY HOUSES SINGAPORE 068877

Date : 30-06-2020



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

|                     |                |                       |            |
|---------------------|----------------|-----------------------|------------|
| <b>Insured Veh.</b> | SHC 212U       | <b>Veh. Inspected</b> | SMP 463J   |
| <b>Policy No.</b>   | D-20094921MFSH | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | D20001302MFSH  | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  | MERINA CHIA    | <b>Assign Date</b>    | 04/03/2020 |

### 2. Vehicle Particulars & Condition

|                         |                          |                     |            |
|-------------------------|--------------------------|---------------------|------------|
| <b>Make &amp; Model</b> | HONDA SHUTTLE HYBRID (A) | <b>c.c</b>          | 1496       |
| <b>Engine No.</b>       | HIDDEN                   | <b>Year of Reg.</b> | 2019       |
| <b>Chassis No.</b>      | GP72004126               | <b>Colour</b>       | GREY       |
| <b>Odometer</b>         | 52036                    | <b>Steering</b>     | IN ORDER   |
| <b>Brakes</b>           | IN ORDER                 | <b>Modification</b> | SPORTS RIM |
| <b>General</b>          | GOOD                     |                     |            |

### 3. Conditions of Tyres

|                       |             |             |                |
|-----------------------|-------------|-------------|----------------|
|                       | <b>Size</b> | <b>Make</b> | <b>Balance</b> |
| <b>R/H Front Tyre</b> | 185/60 R15  | KAPSEN      | 7 mm           |
| <b>L/H Front Tyre</b> | 185/60 R15  | KAPSEN      | 7 mm           |
| <b>R/H Rear Tyre</b>  | 185/60 R15  | YOKOHAMA    | 7 mm           |
| <b>L/H Rear Tyre</b>  | 185/60 R15  | YOKOHAMA    | 7 mm           |

### 4. Description of Damages

|                                                                            |
|----------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS. |
|----------------------------------------------------------------------------|

### 5. General Information

|                       |                                                                                                           |                        |            |
|-----------------------|-----------------------------------------------------------------------------------------------------------|------------------------|------------|
| <b>Accident Date</b>  | 02/03/2020                                                                                                | <b>Inspection Date</b> | 05/03/2020 |
| <b>Survey held at</b> | RICO 60 AUTO SERVICES PTE LTD<br>8 KAKI BUKIT AVENUE 4<br>#02-24 PREMIER @ KAKI BUKIT<br>SINGAPORE 415875 |                        |            |

### 5a. Remarks

|                                                                                                                                           |
|-------------------------------------------------------------------------------------------------------------------------------------------|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|-------------------------------------------------------------------------------------------------------------------------------------------|

### 5b. Estimate Days of Repair

|                                     |                       |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | <b>5 Working Days</b> |
|-------------------------------------|-----------------------|



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 463J

| Qty | Description of Parts                    | Condition            | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|-----------------------------------------|----------------------|----------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>      |                      |                            |                   |
| 1   | REAR WINDSCREEN MOULDING                | NECESSARY            | 163.00                     | 78.00             |
| 1   | TAILGATE                                | BADLY DENTED         | 1,393.00                   | 1,131.10          |
| 1   | TAILGATE SPOILER LAMP                   | NOT NECESSARY        | 198.00                     | -                 |
| 1   | TAILGATE WIPER                          | NOT NECESSARY        | 95.60                      | -                 |
| 1   | TAILGATE WIPER MOTOR                    | NOT NECESSARY        | 490.00                     | -                 |
| 1   | TAILGATE WIPER MOTOR COVER              | NOT NECESSARY        | 98.00                      | -                 |
| 1   | TAILGATE LOGO (HONDA)                   | NECESSARY            | 54.00                      | 40.90             |
| 1   | TAILGATE EMBLEM (SHUTTLE)               | NECESSARY            | 62.00                      | 62.00             |
| 1   | TAILGATE EMBLEM (HYBRID)                | NECESSARY            | 70.00                      | 70.00             |
| 1   | TAILGATE HANDLE CHROME                  | NOT NECESSARY        | 421.00                     | -                 |
| 2   | TAILGATE HANDLE NUMBER PLATE LAMP (L+R) | NOT NECESSARY        | 121.00                     | -                 |
| 1   | TAILGATE HANDLE SWITCH                  | NOT NECESSARY        | 329.00                     | -                 |
| 2   | TAILGATE LAMP (L+R)                     | NOT NECESSARY        | 796.00                     | -                 |
| 1   | TAILGATE LOCK                           | TWISTED / SHORTED    | 269.00                     | 196.20            |
| 1   | TAILGATE LOCK CATCH                     | NOT NECESSARY        | 91.00                      | -                 |
| 1   | TAILGATE INNER BOARD                    | DEFORMED / CRACKED   | 412.00                     | 243.80            |
| 1   | TAILGATE INNER HANDLE                   | NOT NECESSARY        | 63.00                      | -                 |
| 1   | TAILGATE WEATHERSTRIP                   | TORN                 | 209.00                     | 132.60            |
| 2   | TAIL LAMP(L+R)                          | NOT NECESSARY        | 1,042.00                   | -                 |
| 2   | TAIL LAMP PANEL (L+R)                   | NOT NECESSARY        | 440.00                     | -                 |
| 1   | REAR BUMPER                             | DENTED / DEFORMED    | 1,181.00                   | 936.50            |
| 2   | REAR BUMPER RETAINER (L+R)              | NOT NECESSARY        | 122.00                     | -                 |
| 2   | REAR BUMPER BRACKET (L+R)               | NOT NECESSARY        | 198.00                     | -                 |
| 1   | REAR BUMPER SPONGE                      | NO SUCH PARTS        | 210.00                     | -                 |
| 2   | REAR BUMPER REFLECTOR (L+R)             | NOT NECESSARY        | 130.00                     | -                 |
| 2   | REAR BUMPER REFLECTOR GARNISH (L+R)     | NOT NECESSARY        | 108.00                     | -                 |
| 1   | REAR BUMPER TOW COVER                   | NOT NECESSARY        | 45.00                      | -                 |
| 2   | REAR FENDER (L+R)                       | TO REPAIR SEE LABOUR | 2,022.00                   | -                 |

Report Ref No. CC4/FCI20003639/Uea3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                      | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------------|----------------------|---------------------------|-------------------|
| 2   | REAR FENDER QUARTER WINDOW MOULDING (L+R) | NOT NECESSARY        | 212.00                    | -                 |
| 2   | REAR FENDER INNER TRIM TOP (L+R)          | NOT NECESSARY        | 228.00                    | -                 |
| 2   | REAR FENDER INNER TRIM LOWER (L+R)        | NOT NECESSARY        | 979.00                    | -                 |
| 2   | REAR FENDER COWLING (L+R)                 | NOT NECESSARY        | 168.00                    | -                 |
| 1   | END PANEL                                 | BADLY DENTED         | 1,082.00                  | 546.10            |
| 1   | END PANEL TOP GARNISH                     | TORN                 | 561.00                    | 166.80            |
| 1   | FLOOR PANEL                               | TO REPAIR SEE LABOUR | 1,980.00                  | -                 |
| 1   | FLOOR PANEL TOP BOARD                     | NOT NECESSARY        | 261.00                    | -                 |
| 2   | FLOOR PANEL SIDE GARNISH (L+R)            | NOT NECESSARY        | 1,171.00                  | -                 |
| 1   | FLOOR PANEL ACCESSORY BOX CENTER TRAY     | TORN / CRACKED       | 306.00                    | 306.00            |
| 2   | FLOOR PANEL ACCESSORY BOX (L+R)           | NOT NECESSARY        | 562.00                    | -                 |
| 1   | EXHAUST PIPE                              | NOT NECESSARY        | 795.00                    | -                 |
| 1   | EXHAUST GASKET                            | NOT NECESSARY        | 56.00                     | -                 |
| 2   | EXHAUST BRACKET (L+R)                     | NOT NECESSARY        | 211.00                    | -                 |
| 1   | EXHAUST HEAT SHIELD                       | NOT NECESSARY        | 269.00                    | -                 |
|     | LESS 25% DISCOUNT                         |                      | -3,934.72                 | -782.00           |
|     |                                           |                      | 15,738.88                 | 3,128.00          |
| 4   | SET REAR BUMPER REVERSE SENSOR (SN)       | CRACKED              | 1,452.00                  | 200.00            |
|     | LESS 25% DISCOUNT                         |                      | -290.40                   | -                 |
|     |                                           |                      | 1,161.60                  | 200.00            |
|     | <b><u>SPECIAL NETT ITEMS</u></b>          |                      |                           |                   |
| 1   | REAR WINDSCREEN SEALANT (SN)              | NECESSARY            | 120.00                    | 40.00             |
| 1   | TAILGATE WIPER BLADE (SN)                 | NOT NECESSARY        | 120.00                    | -                 |
| 10  | TAILGATE INNER BOARD CLIPS (SN)           | NECESSARY            | 100.00                    | 40.00             |
| 1   | REAR CARPLATE (SN)                        | NOT NECESSARY        | 200.00                    | -                 |
| 1   | REAR CARPLATE FRAME (SN)                  | NOT NECESSARY        | 120.00                    | -                 |
| 1   | REVERSE CAMERA (SN)                       | SHORTED              | 950.00                    | 380.00            |
| 4   | TAIL LAMP CLIPS (SN)                      | NOT NECESSARY        | 80.00                     | -                 |
| 10  | REAR BUMPER CLIPS (SN)                    | NECESSARY            | 100.00                    | 40.00             |
| 1   | REAR FENDER QUARTER WINDOW SEALANT (SN)   | NOT NECESSARY        | 120.00                    | -                 |
| 20  | REAR FENDER INNER TRIM CLIPS (SN)         | NOT NECESSARY        | 200.00                    | -                 |

Report Ref No. CC4/FCI20003639/Uea3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty                                                                         | Description of Parts                                                                                                   | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| 20                                                                          | REAR FENDER COWLING CLIPS (SN)                                                                                         | NOT NECESSARY | 200.00                    | -                 |
| 1                                                                           | END PANEL SEALANT (SN)                                                                                                 | NECESSARY     | 120.00                    | 50.00             |
| 10                                                                          | END PANEL TOP GARNISH CLIPS (SN)                                                                                       | NOT NECESSARY | 100.00                    | -                 |
| 1                                                                           | SPARE WHEEL PANEL SEALANT (SN)                                                                                         | NOT NECESSARY | 120.00                    | -                 |
|                                                                             |                                                                                                                        |               | 2,650.00                  | 550.00            |
|                                                                             | <b>LABOUR</b>                                                                                                          |               |                           |                   |
|                                                                             | TO RNR ACCIDENT DAMAGE PARTS ,CUT /WELD ,KNOCK & REALIGN.INCLUSIVE OF THE REPAIR OF FLOOR PANEL AND REAR FENDER (L+R). |               | 3,600.00                  | 600.00            |
|                                                                             | TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.                                                                           |               | 3,000.00                  | 900.00            |
|                                                                             | TO RUST PROOF ACCIDENT AFFECTED AREA.                                                                                  |               | 250.00                    | 60.00             |
|                                                                             | TO RNR REAR WINDSCREEN .                                                                                               |               | 400.00                    | 120.00            |
|                                                                             | TO RNR REAR FENDER QUARTER WINDSCREEN.                                                                                 | NOT NECESSARY | 400.00                    | -                 |
|                                                                             | TO RNR REAR BOOT MECHANISM .                                                                                           |               | 400.00                    | 60.00             |
|                                                                             | TO RNR UPHOLSTERY GARNISH AND ATTACHMENT PARTS.                                                                        |               | 400.00                    | 80.00             |
|                                                                             | TO RNR REVERSE SENSOR & CHECK FUNCTION .                                                                               |               | 120.00                    | 50.00             |
|                                                                             | TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS.                                                                            | NOT NECESSARY | 250.00                    | -                 |
|                                                                             | TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION .                                                                         |               | 120.00                    | 30.00             |
|                                                                             | TO CHECK WIRING LAYOUT AND TAILGATE LAMP FUNCTION .                                                                    | NOT NECESSARY | 120.00                    | -                 |
|                                                                             | TO DO WATER LEAK TEST.                                                                                                 | NOT NECESSARY | 80.00                     | -                 |
|                                                                             | TO RNR FUEL TANK TO ASSIST WORK LOAD.                                                                                  | NOT NECESSARY | 250.00                    | -                 |
|                                                                             |                                                                                                                        |               | 9,390.00                  | 1,900.00          |
| <b>GRAND TOTAL</b>                                                          |                                                                                                                        |               | <b>28,940.48</b>          | <b>5,778.00</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                                                        |               |                           | <b>4,600.00</b>   |

Report Ref No. CC4/FCI20003639/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SMP 463J

### INSPECTION







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd


S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMP 463J

RE-INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

