

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Aug 2019		27 Aug 2019 15:42 Edit Adj Rpt	S\$10,600.00 Edit Estimates	S\$10,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: TEO LAY HAR (ZHANG LIXIA) , ID: S8740675Z, Tel: +6591895386, Email: NOEMAIL									
Main Claimant: GIM TIAN LOGISTICS PTE LTD , Co. Reg. No.: 199400038D									
Vehicle Reg. No.: XE3025Z		Date of Loss: 18/08/2019 11:00 - :59 [26 Months and 6 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / MSC/V/19-001013		Policy/Cover Note No.: MSCN:72184560(TPFT) (TP, Fire & Theft) Coverage: 27/06/2019 - 26/06/2020							
Vehicle Reg. No. (Insured): FBN280K		Policy No. (Claimant): Excess:							
Repairer: - Not Applicable - (-)									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 06/03/2020]									
Driver/Custodian (Insured): TEO LAY HAR (ZHANG LIXIA) (31 / Female) , NRIC: S8740675Z, Tel: +6591895386 Email: NOEMAIL									
Adj Asg. Remarks: on WP. Manual assigned to LKK, please call Ah Long 9691 0909 to arrange location. Heavy vehicle. He can't confirm workshop name with MSIG now. Manual assigned to LKK via email on 27/08/19.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
MSIG_SG (04/03/2020): Report Send Back Alerts - XE3025Z (TP)									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*XE3025Z (MSC/V/19-001013)
[FBN280K]
TP
GIM TIAN LOGISTICS PTE LTD
Aug 18 2019 11:00AM
[TEO LAY HAR (ZHANG LIXIA)]

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Video

1 per page ☐

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	16/01/20 09:38	Video - Accident		Load MP4	

Assessment Reports

1 per page ☐

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	27/08/19 13:18	Accident Statement From: SC - Reg. No: FBN280K, Claimant: TEO LAY HAR (ZHANG LIXIA)		Load HTM	

Photos/Images

3 per page ☐

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/09/19 10:32	General View		Load JPG	☒
2	03/09/19 10:32	General View		Load JPG	☒
3	03/09/19 10:32	General View		Load JPG	☒
4	03/09/19 10:32	General View		Load JPG	☒
5	03/09/19 10:32	General View		Load JPG	☒
6	03/09/19 10:32	General View		Load JPG	☒
7	03/09/19 10:32	General View		Load JPG	☒
8	03/09/19 10:32	General View		Load JPG	☒
9	03/09/19 10:32	General View		Load JPG	☒
10	03/09/19 10:32	General View		Load JPG	☒
11	03/09/19 10:32	General View		Load JPG	☒
12	03/09/19 10:32	General View		Load JPG	☒
13	03/09/19 10:32	General View		Load JPG	☒
14	03/09/19 10:32	General View		Load JPG	☒
15	03/09/19 10:32	General View		Load JPG	☒
16	03/09/19 10:32	General View		Load JPG	☒
17	03/09/19 10:32	General View		Load JPG	☒
18	03/09/19 10:32	General View		Load JPG	☒
19	03/09/19 10:32	General View		Load JPG	☒
20	03/09/19 10:32	General View		Load JPG	☒
21	03/09/19 10:32	General View		Load JPG	☒
22	03/09/19 10:32	General View		Load JPG	☒
23	03/09/19 10:32	General View		Load JPG	☒
24	03/09/19 10:32	General View		Load JPG	☒
25	03/09/19 10:32	General View		Load JPG	☒
26	03/09/19 10:32	General View		Load JPG	☒
27	03/09/19 10:32	General View		Load JPG	☒
28	03/09/19 10:32	General View		Load JPG	☒
29	03/09/19 10:32	General View		Load JPG	☒
30	03/09/19 10:32	General View		Load JPG	☒
31	03/09/19 10:32	General View		Load JPG	☒
32	03/09/19 10:32	General View		Load JPG	☒
33	03/09/19 10:32	General View		Load JPG	☒
34	03/09/19 10:33	Chassis Number		Load JPG	☒

Video				1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
35	03/09/19 10:33	Odometer Reading	1	Load JPG	✓

Documentation				1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	27/08/19 13:19	SHD9516D E-filed GIA report From:TP - Reg. No: SHD9516D, Claimant: TRANS-CAB SERVICES PTE LTD	1	Load PDF	
2	27/08/19 13:19	PRI	1	Load PDF	
3	27/08/19 15:16	email to workshop	1	Load PDF	
4	27/08/19 15:16	email liab	1	Load PDF	
5	11/02/20 16:11	Survey report & photos	1	Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail	Print
1	27/08/19 15:38	Survey Request - Manual Assigned	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/04/20 11:01	PRS INVOICE	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/MSG19015103/GSF3S2-1**Date:** 16/04/2020REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSCN:72184560(TPFT)

Claimant Vehicle No : XE3025Z **Insured Vehicle No :** FBN280K

Date of Loss: 18/08/2019 Nature of Claim: TP Claim No: MSC/V/19-001013

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XE3025Z**

Make & Model: HINO FS1EKM10027, 12.9 D (M) Engine No: E13CWA11553

Reg. Date: 12/06/2017 (Man. Year: 2017) Chassis No: FS1EKM10033

Colour: White/Yellow Odometer: 49741 km

Engine Capacity: 12913 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D/D)

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6/6/6/6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6/6/6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,700.00	9,700.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	900.00	300.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	10,900.00	10,600.00	300.00	2.75

INSPECTION

Date of Assignment: 27/08/2019

Date Inspected: 02/09/2019 Inspected At:

BRADDELL ROAD OPEN CARPARK
Repairer: ENG SOON HUAT ENGINEERING
WORKS

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG**Manager:** Hiew May Fung*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Apr 2020)		
Parts:	N/A	HINO FS1EKM10027 12.9 D (M) (Model not available in database)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for XE3025Z)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*10400A MODULE A ENERGY ABSORBER	Buckled / Cut	9,500.00 F	*9,500.00 F
2	1		*TAIL LAMP WITH BRACKET (LEFT)	Bent / Cracked	200.00 F	*200.00 F
Total Parts (S\$)						9,700.00
						9,700.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	FULL LABOUR COAT, DISMANTLING, REMOVING, INSTALLATION, REPAIRING, RE-ALIGNMENT.	New	1,200.00	900.00
Gross Labour Cost (\$)			1,200.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >