



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCQ 5599G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RADIATOR GRILLE T5 S (SN)	CRACKED	893.60	804.24
1	BUMPER COVER FRT SV9 (SN)	DEFORMED	1,789.50	1,610.55
1	BUMPER SPOILER FRT T (SN)	TO REPAIR SEE LABOUR	502.80	-
1	BUMPER FOAM FRT SV9 (SN)	NOT NECESSARY	393.40	-
1	BUMPER BRACKET LHF S (SN)	NOT NECESSARY	37.70	-
1	BUMPER BRACKET RHF S (SN)	NOT NECESSARY	37.70	-
1	HINGE WASHER LH T6 S (SN)	NOT NECESSARY	53.70	-
1	HINGE WASHER T6 S90 (SN)	NOT NECESSARY	53.70	-
1	HINGE BRACKET WASHER (SN)	NOT NECESSARY	65.60	-
1	HINGE BRACKET WASHER (SN)	NOT NECESSARY	53.70	-
1	BRACKET (SN)	NOT NECESSARY	128.20	-
1	BRACKET (SN)	NOT NECESSARY	128.20	-
1	BUMPER BRACKET LHF S (SN)	NOT NECESSARY	53.70	-
1	BUMPER BRACKET RHF S (SN)	NOT NECESSARY	156.20	-
1	BUMPER BRACKET FRT C (SN)	NOT NECESSARY	156.20	-
1	RADIATOR GRILLE T5 S (SN)	REPEATED	893.60	-
1	BRACKET (SN)	NOT NECESSARY	50.70	-
1	TOW COVER FRT SV90 1 (SN)	NOT NECESSARY	75.40	-
1	BUMPER BRACKET LHF S (SN)	NOT NECESSARY	151.20	-
1	BUMPER BRACKET RHF S (SN)	NOT NECESSARY	151.10	-
1	PARK HOLDER LH SV90 (SN)	NECESSARY	62.40	56.16
1	PARK HOLDER RH SV90 (SN)	NECESSARY	62.40	56.16
1	DECOR FRAME COVER XC (SN)	NOT NECESSARY	20.50	-
1	BUMPER COVER LH T5 S (SN)	NOT NECESSARY	93.80	-
1	BUMPER COVER RH T5 S (SN)	NOT NECESSARY	93.80	-
1	FRONT DECOR FRAME TR (SN)	NOT NECESSARY	114.00	-
1	FRONT DECOR FRAME TR (SN)	NOT NECESSARY	114.00	-
1	PARK HOLDER CTR LH S (SN)	NECESSARY	48.20	43.38
1	PARK HOLDER CTR RH S (SN)	NECESSARY	42.20	37.98
1	BUMPER GRILLE LOWER (SN)	NOT NECESSARY	232.70	-
1	BUMPER GRILLE LH S90 (SN)	NOT NECESSARY	266.10	-
1	BUMPER GRILLE RH S90 (SN)	NOT NECESSARY	266.10	-
10	CLIP CHROME MOULDING (SN)	NECESSARY	47.00	43.20



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
10	BUMPER CLIP S80 07 (SN)	NECESSARY	49.00	44.10
1	BUMPER RAIL (BEAM) F(SN)	NOT NECESSARY	1,260.80	-
10	BUMPER CLIP 8X8 ,5 (SN)	NOT NECESSARY	55.00	-
10	SIX PT SOCKET SCREW (SN)	NOT NECESSARY	78.00	-
2	EXTERIOR ADHESIVE GL (SN)	NOT NECESSARY	290.00	-
			9,021.90	2,695.77
	LABOUR			
	TO REPLACE FRONT BUMPER ,FRT BRACKET ,FRT GRILLE ,ETC.INCLUSIVE OF THE REPAIR OF BUMPER SPOILER FRT T.		2,400.00	800.00
	TO INSTALL FRONT NUMBER PLATE INCLUDE HOLDER.		60.00	60.00
	TO PUTTY SPRAY PAINT ON FRT BUMPER ,ETC.		1,400.00	700.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		495.00	495.00
			4,355.00	2,055.00
GRAND TOTAL			13,376.90	4,750.77
RECOMMENDED COST OF REPAIRS				4,750.77

Report Ref No. CC4/FCI20003644/T1ka3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.