



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2004983
INV Date 16/07/2020
Reference CC4/FCI20003656/T1ea3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. GBE 3993P
Insured Veh. SHA 5207M
Claim No. D20001286MFSH
Policy No. D-20094922MFSH
Accident Date 02/03/2020
Inspection Date 05/03/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20003656/T1ea3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 16-07-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 5207M	Veh. Inspected	GBE 3993P
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20001286MFSH	Excess (\$)	0.00
Assign From		Assign Date	05/03/2020

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV350	c.c	2488
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JN1MC2E26Z0005382	Colour	SILVER
Odometer	175807	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	MAXXIS	6 mm
L/H Front Tyre	195 R15	MAXXIS	6 mm
R/H Rear Tyre	195 R15	MAXXIS	6 mm
L/H Rear Tyre	195 R15	MAXXIS	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	02/03/2020	Inspection Date	05/03/2020
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 3993P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	727.60	669.20
1	REAR BUMPER SIDE HOLDER	NOT NECESSARY	45.00	-
1	REAR BUMPER STEP PLATE	BENT	187.22	187.22
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	825.70	-
2	REAR EXHAUST MOUNTING	NOT NECESSARY	30.00	-
1	FLOOR PANEL TOP BEAM	NOT NECESSARY	350.28	-
1	END PANEL OUTER	BENT	284.74	284.74
1	END PANEL INNER	TO REPAIR SEE LABOUR	530.84	-
1	TAILLAMP LH	CRACKED	208.72	208.72
1	TAILLAMP RH	NOT NECESSARY	208.72	-
1	TAILGATE	BENT	2,206.47	2,038.25
1	TAILGATE EMBLEM LOGO	NECESSARY	52.44	52.44
1	TAILGATE EMBLEM -NV350	NECESSARY	89.01	89.01
1	TAILGATE EMBLEM -URVAN	NECESSARY	52.44	52.44
1	TAILGATE CHROME GARNISH	NOT NECESSARY	510.02	-
2	TAILGATE ABSORBER	NOT NECESSARY	402.50	-
1	TAILGATE WEATHERSTRIP	CUT	109.25	109.25
1	TAILGATE LOCK	BENT	323.80	266.20
1	TAILGATE LOCK STRIKER	BENT	34.60	34.60
2	TAILGATE HINGE	TO REPAIR SEE LABOUR	138.00	-
1	TAILGATE INNER TRIM	NOT NECESSARY	150.65	-
	LESS 10% DISCOUNT		-746.80	-399.21
			6,721.20	3,592.86
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	40.00	30.00
1	SET REAR REVERSE SENSOR (SN)	NOT WORKING	300.00	200.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	150.00	40.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	JOINT SEALANT (SN)	NECESSARY	150.00	40.00
			640.00	310.00
	LABOUR			
	CHECK REAR WIRING AND LIGHTING SYSTEM.		60.00	30.00
	REMOVE AND REFIT REAR LINING ,TRIM AND GARNISH .		200.00	60.00
	REMOVE AND RENEW REAR REVERSE SENSOR .		150.00	30.00
	REMOVE AND STRAIGHTEN REAR EXHAUST .		150.00	60.00
	REMOVE AND REFIT REAR WINDSCREEN .		150.00	120.00
	TRANSFER PARTS ,ATTACHMENT FROM OLD TAILGATE TO NEW.		200.00	60.00
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF REAR EXHAUST SILENCER ,END PANEL INNER AND TAILGATE HINGE .		1,200.00	700.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,400.00	800.00
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	40.00
	REMOVE AND RENEW STICKER ON AFFECTED AREAS.		120.00	60.00
			3,780.00	1,960.00
GRAND TOTAL			11,141.20	5,862.86
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,700.00

Report Ref No. CC4/FCI20003656/T1ea3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBE 3993P

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBE 3993P

RE-INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

