

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20003660/AEA3Q2

Date: 08/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994199

Claimant
Vehicle No : SJC5030X **Insured Vehicle No :** SLT9301A

Date of Loss: 01/03/2020 Nature of Claim: TP Claim No: 2028211996SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJC5030X	Engine No:	R18A12801453
Make & Model:	HONDA STREAM, 1.8 L SUNROOF (A)	Chassis No:	JHMRN68408S201453
Reg. Date:	21/02/2008 (Man. Year: 2007)	Odometer:	263336 km
Colour:	White		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,613.44	4,345.60	5,267.84	54.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,770.00	1,910.00	1,860.00	49.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,383.44	6,255.60	7,127.84	53.26
Approved Total (Overridden) (\$\$)		5,000.00		
(\$\$)	13,383.44	5,000.00	8,383.44	62.64
+ GST 7.00/7.00% (\$\$)	936.84	350.00	586.84	62.64
Nett Amount (\$\$)	14,320.28	5,350.00	8,970.28	62.64
+ Car Rental (8.0 x S\$120.00/day) (\$\$)		960.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		6,317.45		

INSPECTION

Date of Assignment: 05/03/2020

Date Inspected: 05/03/2020 Inspected At: SK Automobile Pte Ltd (HQ)
23 Kaki Bukit Avenue 4, #03-01 Vicom
Inspection Centre
Singapore 415933

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Distorted	1,448.00 FL	*878.00 FL
2	2		*FRONT DOOR HINGE RH	Not Necessary	282.00 FL	*- FL
3	1		*FRONT DOOR INNER TRIM RH	Cracked	498.00 FL	*498.00 FL
4	1		*FRONT DOOR WEATHERSTRIP RH	Cut	198.00 FL	*198.00 FL
5	1		*FRONT DOOR REGULATOR RH	Damaged	389.50 FL	*389.50 FL
6	1		*FRONT DOOR POWER WINDOW MOTOR RH	Not Necessary	698.00 FL	*- FL
7	1		*FRONT DOOR OUTER MOULDING RH	Not Necessary	130.60 FL	*- FL
8	1		*FRONT DOOR OUTER HANDLE RH	Damaged	154.00 FL	*154.00 FL
9	1		*FRONT DOOR BLACK STICKER RH	Necessary	120.00 FS	*80.00 FS
10	1		*FRONT DOOR INNER LOCK RH	Damaged	315.00 FL	*315.00 FL
11	1		*FRONT DOOR INNER STEP GARNISH RH	Not Necessary	125.00 FL	*- FL
12	1		*ROCKER PANEL RH	Repair	984.00 FL	*- FL
13	1		*CENTER PILLER	Dented	689.00 FL	*689.00 FL
14	1		*CENTER PILLER INNER TRIM	Not Necessary	358.00 FL	*- FL
15	1		*SIDE MIRROR LH	Not Necessary	598.00 FL	*- FL
16	1		*REAR DOOR RH	Distorted	1,652.00 FL	*870.00 FL
17	2		*REAR DOOR HINGE RH	Bent	378.00 FL	*80.00 FL
18	1		*REAR DOOR REGULATOR RH	Damaged	389.50 FL	*389.50 FL
19	1		*REAR DOOR POWER WINDOW MOTOR RH	Not Necessary	548.00 FL	*- FL
20	1		*REAR DOOR INNER TRIM RH	Cracked	498.00 FL	*498.00 FL
21	1		*REAR DOOR WEATHERSTRIP RH	Cut	198.00 FL	*198.00 FL
22	1		*FRONT DOOR CHECKER RH	Not Necessary	148.80 FL	*- FL
23	1		*REAR DOOR WEATHERSTRIP RH	Repeated	185.60 FL	*- FL
24	1		*REAR DOOR GLASS FRAME GARNISH RH	Not Necessary	121.80 FL	*- FL
25	1		*REAR DOOR OUTER MOULDING RH	Not Necessary	161.90 FL	*- FL
26	1		*REAR DOOR OUTER HANDLE RH	Not Necessary	130.60 FL	*- FL
27	1		*REAR DOOR BLACK STICKER RH	Necessary	120.00 FS	*80.00 FS
28	1		*SET FRONT DOOR INNER TRIM CLIPS	Necessary	60.00 FS	*30.00 FS
29	1		*FRONT DOOR INNER STEP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
30	1		*ROCKER PANEL SEALANT RH	Not Necessary	60.00 FS	*- FS
31	1		*CENTER PILLAR SEALANT RH	Not Necessary	60.00 FS	*- FS
32	1		*SET CENTER PILLAR INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
33	1		*SET REAR DOOR INNER TRIM CLIPS	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **11,869.30** **5,377.00**
- List Item Discount on L Items 20.00/20.00% (\$\$) 2,255.86 1,031.40

Total Parts (\$\$) **9,613.44** **4,345.60**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CUT OFF AND REPLACE FRONT SUPPORT PANEL,RESTRUCTURE FRONT CRASH MANAGEMENT COMPONENT AND RENEW OTHER DAMAGE PARTS	New	1,500.00	900.00
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA	New	1,800.00	850.00
3	ADJUST AND FOCUS FRONT LIGHTING SYSTEM PERFORM HEADLAMP ADJUSTMENT TO POSITION	New	80.00	0.00
4	TRANFER FRONT AND REAR DOOR MECHANISM	New	120.00	80.00
5	TRANFER FRONT AND FRONT DOOR MECHANISM	New	120.00	80.00
6	WHEEL ALIGNMENT	New	150.00	0.00
Gross Labour Cost (\$\$)			3,770.00	1,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >