



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2005965
INV Date 31/08/2020
Reference CC4/LPC20003661/Eka3s2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SLE 590U
Insured Veh. GBG 7408B
Claim No. 19/20/20/VC05/023132
Policy No. Z19VC05002220
Accident Date 29/02/2020
Inspection Date 06/03/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC20003661/Eka3s2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 31-08-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 7408B	Veh. Inspected	SLE 590U
Policy No.	Z19VC05002220	Coverage (\$)	0.00
Claim No.	19/20/20/VC05/023132	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	04/03/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA ODYSSEY	c.c	2356
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JHMRC1890GC204289	Colour	PURPLE
Odometer	080106	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	MICHELIN	5 mm
L/H Front Tyre	215/55 R17	MICHELIN	5 mm
R/H Rear Tyre	215/55 R17	MICHELIN	5 mm
L/H Rear Tyre	215/55 R17	MICHELIN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/02/2020	Inspection Date	06/03/2020
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 590U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
4	VPC REAR SENSORS (SN)	BROKEN	320.00	320.00
1	NUMBER PLATE WITH CASING - L (SN)	NOT NECESSARY	45.00	-
1	TAILLIGHT ASSYR. (SN)	NOT NECESSARY	644.92	-
1	TAILLIGHT ASSYL. (SN)	NOT NECESSARY	644.92	-
1	LIGHT ASSYR.LID (SN)	BROKEN	297.15	297.15
1	LIGHT ASSYL.LID (SN)	BROKEN	297.15	297.15
1	GARNISH ASSYRR.LICENCE (SN)	NOT NECESSARY	177.30	-
1	TAILGATE COMP (SN)	DENTED	823.95	823.95
1	WEATHERSTRIP TAILGATE (SN)	CRUSHED	90.37	90.37
1	MOLDING ASSYRR LICENCE GARN (SN)	BROKEN	135.07	135.07
1	GARNISH ASSYTAILGATE SPOILER (SN)	NOT NECESSARY	472.72	-
6	CLIPTAILGATE SPOILER (SN)	NOT NECESSARY	11.25	-
1	EMBLEMH (SN)	NECESSARY	20.25	20.25
1	FACERR.BUMPER (SN)	DENTED	437.32	437.32
1	REFLECTOR ASSYR.RR. (SN)	NOT NECESSARY	34.87	-
1	REFLECTOR ASSYL/RR. (SN)	NOT NECESSARY	34.87	-
1	FACER.RR.BUMPER GARNISH (RH) (SN)	CRUSHED	59.10	59.10
1	FACEL.RR.BUMPER GARNISH (SN)	NOT NECESSARY	59.10	-
1	SPOILER ASSYR.RR.SIDE (SN)	NOT NECESSARY	87.82	-
1	SPOILER ASSYL.RR.SIDE (SN)	NOT NECESSARY	87.82	-
1	SPACERR.RR.BUMPER SIDE (SN)	BROKEN	14.70	14.70
1	SPACERL.RR.BUMPER SIDE (SN)	BROKEN	14.70	14.70
7	CLIP, BUMPER (SN)	NECESSARY	12.07	12.07
1	PANEL COMP, RR. (SN)	DENTED	354.60	354.60
1	PAN SET3RD SEAT (SN)	DENTED	260.02	260.02
3	OILSHEET (SN)	NOT NECESSARY	93.82	-
1	LINING ASSY TAILGATE LOWER (SN)	NOT NECESSARY	158.70	-
1	POCKET TAILGATE LINING PULL (SN)	NOT NECESSARY	8.25	-
1	LINING COMPR.RR.SIDE (SN)	NOT NECESSARY	605.17	-
1	LINING ASSY RR.PANEL (SN)	CRUSHED	79.72	79.72
1	COMP LIDTOOL (SN)	NOT NECESSARY	47.25	-

Report Ref No. CC4/LPC20003661/Eka3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LINING COMPL.RR.SIDE (SN)	NOT NECESSARY	587.55	-
1	GLASS SET,RR.WINDSHIELD (SN)	BROKEN	777.97	777.97
2	MOLDINGRR.WINDSHIELD SIDE (SN)	NECESSARY	27.75	27.75
1	MOLDINGR.RR.WINDSHIELD CORNER (SN)	NECESSARY	12.97	12.97
1	MOLDINGL.RR.WINDSHIELD CORNER (SN)	NECESSARY	12.97	12.97
4	SPACERRR.W/SHIELD (SN)	NECESSARY	12.00	12.00
1	RUBBER AWINDSHIELD DAM (SN)	NECESSARY	2.85	2.85
2	DAMPERSTD 5X5 (SN)	NECESSARY	13.05	13.05
1	CAPPVOT (SN)	NECESSARY	3.75	3.75
2	WINDSCREEN SEALANT (SN)	NECESSARY	120.00	120.00
1	SOLAR FILM ON REAR WINDSCREEN (SN)	NECESSARY	300.00	300.00
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
1	SEALANT FOR REAR END PANEL (SN)	NECESSARY	100.00	100.00
1	SEALANT FOR REAR FLOOR PANEL (SN)	NECESSARY	100.00	100.00
1	SEALANT FOR TAILGATE (SN)	NECESSARY	100.00	100.00
1	WINDSCREEN DAM KIT. (SN)	NECESSARY	100.00	100.00
			8,800.81	4,929.48
	LABOUR			
	REMOVE & RENEW REVERSE SENSORS-4 PCS.		140.00	140.00
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		100.00	100.00
	REMOVE & INSTALL SPEAKER BOARD TRUNK.		380.00	380.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &		420.00	420.00
	REMOVE & INSTALL RR.WINDSCREEN.		680.00	680.00
	CUT OFF & RENEW RR PANEL.		6,500.00	5,200.00
	SPRAY PAINTING ON REPAIRED OR RELACED AREAS.		4,160.00	3,120.00
	REMOVE UPHOLSTERY SHATTERED GLASSES.		650.00	325.00
	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA.		650.00	580.00
	RESET VEHICLE SMART ENTRY SYSTEM.		650.00	580.00
			14,330.00	11,525.00
	GRAND TOTAL		23,130.81	16,454.48

Report Ref No. CC4/LPC20003661/Eka3s2



RECOMMENDED COST OF REPAIRS			16,454.48
-----------------------------	--	--	-----------

Report Ref No. CC4/LPC20003661/Eka3s2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLE 590U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

