Our Ref.

: RSS/1910-7504 (AASG)(PD)

Your Ref.

W: Natalie Ng

E: natalie_ng@rssolomon.com

12 December 2019

AIG ASIA PACIFIC INSURANCE PTE LTD

No. 78 Shenton Way #07-16 Lippo Centre Singapore 079120 Attn: Motor Claim Dept

Dear Sirs.



By PDX: [8181]
WITHOUT PREJUDICE



ACCIDENT INVOLVING SFH9090S & SLM4539B ALONG CENTRAL EXPRESSWAY TOWARDS SELETAR EXPRESSWAY ON 26TH JANUARY 2019 AT ABOUT 1545 HRS

We act for Soh Mui Ling Josephine, the administratrix of the estate of late Ho Wan Sing, the registered owner of vehicle registration no. SFH9090S, and refer to the above-captioned matter.

2. We are instructed that you are the insurers of vehicle registration no. SLM4539B at the material time. We are further instructed that the aforesaid accident was caused solely by your insured and/or insured driver's negligence in her/his driving, controlling and/or management of the said vehicle. As a result of the accident, our Client's vehicle was damaged and she has been put to loss and expense, particulars of which are as follows: -

(a) Cost of Repair	\$ 62,800.00
(b) Vehicle Repair Parts and Accessories	\$ 480.00
(c) Loss of use for 152 working days at \$240.00 per day	\$ 36,480.00
(i.e. including two days for Pre-repair survey)	
(d) Survey report fee	\$ 2,250.00
(e) GIA report & search fees	\$ 29.00
(f) LTA search fee	\$ 7.49
(g) Costs	\$ 900.00
(h) Transport, Xerox, postages & Other Incidentals	\$ 50.00
Total:	\$ 102,996.49

- 3. We enclose herewith copies of the following documents in support of our Client's claim: -
 - (a) Final Repair Bill dated 1st October 2019 from Auto Assist;
 - (b) Survey Report with Invoice No. TP19010029 from Automax Survey;
 - (c) Invoice No. 10074 dated 2nd July 2019 by Archperformance SG Pte Ltd for payment of vehicle repair parts and accessories with NETS receipt;
 - (d) GIA and Police Report lodged by our Client's driver;
 - (e) GIA and Police Report lodged by your insured driver with payment advice for search and report fees;
 - (f) LTA search result with payment advice;

...2

Our Ref.

: RSS/1910-7504 (AASG)(PD)

Your Ref.

W: Natalie Ng

E : natalie_ng@rssolomon.com

12 December 2019



PAGE 2

- (g) 123 coloured photographs depicting damages to our Client's vehicle registration No. SFH9090S:
- (h) Death Certificate No. 271845F of the late Ho Wan Sing;
- (i) Grant of Letter of Administration issued on 13th March 2019 for the estate of Ho Wan Sing; and
- (j) The administratrix NRIC No. S1469342D for the estate of late of Ho Wan Sing.
- 4. **TAKE NOTICE** that unless we receive your acknowledgement of receipt to this letter and enclosures within fourteen (14) days from the date hereof, our Client will have no alternative but to commence proceedings against your insured and/or its driver without further notice to you.

Yours faithfully,

R. S. SOLOMON LLC

ADVOCATES & SOLICITORS

Encl.

Cc: LCRF PTE. LTD.
& CHUA MENG LEE

Both of 1090 Lower Delta Road #05-12

Singapore 169201

BY CERTIFICATE OF POSTING WITHOUT PREJUDICE

Note to insured and/or the driver: No enclosures have been provided to you; should you require copies of the afore-mentioned enclosures, please contact our office.

TAKE NOTICE that if you have a counterclaim against our Client arising out of the above-captioned accident, you are required to send us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of you receiving this letter.

AUTO ASSIST

Block 3014 Ubi Road 1 #01-288 Singapore 408702 Tel No.: +65 9746 9644

Date: 1st October 2019

Invoice No.: AASG/SFH9090S/26012019

Messrs: Soh Mui Ling Josephine, the Administratrix of the estate of late Ho Wan Sing

Vehicle No.: SFH9090S

Amount

FINAL REPAIR COST (LUMP SUM)

\$62,800.00

Total:

\$ 62,800.00

DOLLARS SGD SIXTY TWO THOUSAND EIGHT HUNDRED ONLY

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879 Email : automaxsurvey@gmail.com

Registration No. 53110062J

Billing To: Ho Wan Sing

c/o Auto Assist

Blk 3014 #01-288

Ubi Road 1

Singapore 408702

Vehicle no: SFH9090S

Invoice no.: TP19010029

Date: 01 Oct 2019

Model: MERCEDES BENZ C180

TEM	DESCRIPTION		Α	MOUNT
1	Date of Inspection: 29 Jan 2019 Copies of the inspection / survey report Correspondence, postages and etc.		\$	2,250.00
2	Photography Services Develop photographs Storage of digital photographs			
3.	To submit report by hand.			
4.	Charges on photocopies, posting, faxes and others incidental works entrusted.	·		
5	Transportation Charges			
6	Reinspection Charges			
		TOTAL :	\$	2,250.00

Notes :

1. ___ All cheque payment should be "crossed" and made payable to "Automax Survey".

2/ Please contact us if there are further enquiries on the invoice.

Official Stamp

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110 Mobile: 9855 6879 Email: automaxsurvey@gmail.com Registration No. 53110062J

Report Ref: TP19010029

Date:

01 Oct 2019

Ho Wan Sing c/o Auto Assist BIk 3014 #01-288 Ubi Road 1 Singapore 408702

THIRD PARTY SURVEY **ACCIDENT OCCCURED ON 26 Jan 2019**

Workshop Name and Address

Auto Assist Blk 3014 #01-288 Ubi Road 1 Singapore 408702

As per your instruction dated

29 Jan 2019

with regard to the above matter.

SFH9090S

We have carried out a physicial inspection on the said

We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Engine No: 27491030061670 Registration No: SFH9090S

: MERCEDES BENZ C180 Model Year / Capacity: Nov 2013 / 1799 cc

Mileage: 156 285 km Colour : Meatllic Black

Chassis No : WDD2043312G132358

2. TYRES CONDITION

	Size	<u>Made</u>	<u>Balance</u>	Rim
FRONT O/S:	205/40/R18	Bridgestone	9.00 mm	Sport
REAR O/S:	205/40/R18	Bridgestone	9.00 mm	Sport
FRONT N/S:	205/40/R18	Bridgestone	9.00 mm	Sport
REAR N/S:	205/40/R18	Bridgestone	9.00 mm	Sport

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the <u>front and rear</u> portion(s). For more detail of the damages, please see photograph attached.

- 4. Estimated normal period of repair: 150 working days to complete
- 5. In accordance to your instruction, we have <u>Not Authorised</u> repair to the vehicle and the survey done on a <u>"Without Prejudice"</u> basis. We hope that this report will be of assistance to you in dealing with the matter.
- 6. Should you discover any discrepancy in the report, please kindly notify us within 1 week, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comprarison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number: SFH9090S

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)		Our Revised Estimation (S\$)
			 (04)	_	(04)
	List Items				
1 pc	Front bumper	bent	\$ 2,250.00	\$	2,250.00
1 pc	Front bumper side retainer	bent	\$ 88.00	\$	88.00
1 pc	Front bumper side bracket	bent	\$ 64.50	\$	64,50
1 pc	Front bumper reinforcement	dent/distorted	\$ 678.85	\$	678.85
10 pcs	Front bumper clips	necessary	\$ 129.00	\$	129.00
	Front bumper sponge	deformed	\$ 286.60	\$	286.60
-	Front bumper day light	electronically shocked	\$ 710.40	\$	710.40
-	Front bumper air grille garnish	deformed	\$ 224.50	\$	224.50
-	Front bumper chrome moulding	damaged	\$ 270.00	\$	270.00
1 pc	Front bumper beam	distorted	\$ 289.75	\$	289.75
1 pc	Front grille	cracked	\$ 658.80	\$	658.80
1 pc	Front grille chrome	cracked	\$ 182.40	\$	182.40
1 pc	Front grille badge	damaged	\$ 88.00	\$	88.00
6 pcs	Front grille clips	necessary	\$ 60.00	\$	60.00
1 pc	Air cleaner inlet duct	bent	\$ 343.50	\$	343.50
1 pc	Engine under cover	damaged	\$ 519.70	\$	519.70
1 pc	Cold air induction	damaged	\$ 100.00	\$	100.00
1 pc	Engine mounting	wraped	\$ 430.90	\$	430.90
1 pc	Engine under mounting	deformed	\$ 369.60	\$	369.60
1 pc	Air Bag Control Unit	electronically shocked	\$ 2,394.10	\$	2,394.10
1 pc	Steering wheel assy	cracked	\$ 3,027.40	\$	3,027.40
1 pc	ABS assembly	electronically shocked	\$ 2,181.60	\$	2,181.60
1 pc	Oil cooler assy	dented	\$ 1,750.00	\$	1,750.00
1 pc	Air cond condensor	damaged	\$ 1,829.40	\$	1,829.40
	Air cond condensor top mounting	bent	\$ 88.00	\$	88.00
	Air cond condensor bottom mounting	bent	\$ 88.00	\$	88.00
1 pc	Air cond liquid pipe	bent	\$ 170.20	\$	170.20
1 pc	Air cord suction pipe	bent	\$ 117.90	\$	117.90
1 pc	Air cond discharge pipe	bent	\$ 251.50	\$	251.50
1 pc	Air cond fan blade	bent	\$ 155.50	\$	155.50
	Air cond fan motor		\$ 394.50	\$	394.50
		damaged	185.00		
1 pc	Air cond fan cowling	bent	\$	\$	185.00
1 pc	Radiator assembly Radiator top mounting	damaged	\$ 1,507.40	\$	1,507.40
	Radiator top mounting Radiator bottom mounting	bent	\$ 88.00	\$	88.00
	•	distorted	\$ 88.00	\$	88.00
1 pc	Radiator top hose Radiator bottom hose	deformed deformed	\$ 98.00	\$	98.00
1 pc	Radiator bottom nose		\$ 74.00	\$	74.00
1 pc		damaged	\$ 172.50	\$	172.50
	Headlamp brookst	cracked	\$ 4,824.00	\$	4,824.00
	Headlamp bracket	distorted	\$ 358.00	\$	358.00
1 pc	Bonnet Badgo	bent	\$ 2,803.75	\$	2,803.75
1 pc	Bonnet bings	necessary	\$ 115.60	\$	115.60
	Bonnet hinge	bent	\$ 416.00	\$	416.00
2 pcs	Bonnet stopper	deformed	\$ 112.00	\$	112.00
1 pc	Bonnet lock Bonnet lock cable	distorted	\$ 185.00	\$	185.00
1 pc		bent	\$ 83.50	\$	83.50
∠ pcs	Bonnet inner rubber beading	deformed	\$ 55.60	\$	55.60

			e.	00.00	4	00.00
-	Bonnet inner rubber beading clips	necessary	\$	90.00	\$	90.00
	Bonnet insulator	damaged	\$	175.40	\$	175.40
	Bonnet insulator clips	necessary	\$	80.00	\$	80.00
	Bonnet inner rubber RH & LH	deformed	\$	40.00	\$	40.00
•	Bonnet stand clips	necessary	\$	25.00	\$	25.00
	Front fender	bent	\$	3,171.80	\$	3,171.80
	Front fender splash shield	bent	\$	890.20	\$	890.20
2 pcs	Front fender 1/4 garnish	dislodge	\$	310.00	\$	310.00
8 pcs	Front fender splash shield clips	necessary	\$	160.00	\$	160.00
1 pc	Engine top rod mounting	distorted	\$	227.80	\$	227.80
1 pc	Gearbox mounting	deformed	\$	254.10	\$	254.10
1 pc	Alternator assembly	damaged	\$	1,584.40	\$	1,584.40
1 pc	Air cond compressor	damaged	\$	1,179.20	\$	1,179.20
1 pc	Horn Assy (Acc)	electronically shocked	\$	83.80	\$	83.80
1 pc	Fuse Box	dent/distorted	\$	325.70	\$	325.70
1 pc	Fuse Box Top Cover	wraped/deformed	\$	159.20	\$	159.20
1 pc	Throttle body	maulfunction	\$	1,171.40	\$	1,171.40
1 pc	Throttle body gasket	necessary	\$	108.60	\$	108.60
1 pc	Intake mainfold	dent/distorted	\$	1,752.40	\$	1,752.40
1 pc	Intake mainfold gasket	necessary	\$	107.80	\$	107.80
-	Front support panel	dent/distorted	\$	1,457.80	\$	1,457.80
	Fog lamp cover (side)	necessary	\$	44.40	\$	44.40
-	Fog lamp bracket	distorted	\$	32.00	\$	32.00
	Front number plate garnish	necessary	\$	85.00	\$	85.00
•	Rear bumper	bend/deformed	\$	1,518.80	\$	1,518.80
	Rear bumper side retainer	bent	\$	90.00	\$	90.00
	Rear bumper side attachment	bent	\$	116.00	\$	116.00
	Rear bumper side retainer riverts	necessary	\$	90.00	\$	90.00
	Rear bumper clips	necessary	\$	120.00	\$	120.00
	Rear bumper inner center pad garnish	deformed	\$	204.00	\$	204.00
•		deformed	\$	162.00	\$	162.00
1 pc	Rear bumper sponge	damaged	\$	222.00	\$	222.00
	Rear bumper chrome (center)	deformed	\$	382.00	\$	382.00
	Rear bumper chrome (side)	wraped/deformed	\$	348.80	\$	348.80
	Rear bumper lower garnish	bent	\$	562.80	\$	562.80
1 pc	Rear bumper reinforcement		\$	1,737.20	\$	1,737.20
1 pc	Boot lid	bent distorted		294.50	\$	294.50
1 pc	Boot lid lock		\$	115.00		115.00
1 pc	Boot lid lock striker	bent	\$	87.60	\$ \$	87.60
1 pc	Boot lid lock cable	bent	\$			14.00
2 pcs	Boot lid stopper	deformed	\$	14.00	\$	
1 pc	Boot lid weatherstrip	deformed	\$	97.60	\$	97.60
	Boot lid hinge	distorted	\$	97.20	\$	97.20
	Boot lid reflactor	cracked	\$	291.80	\$	291.80
2 pcs	Boot lid reflactor sealant	necessary	\$	29.20	\$	29.20
1 pc	Boot lid badge	bent	\$	126.70	\$	126.70
1 pc	Boot lid insulator	damaged	\$	133.70	\$	133.70
	Boot lid insulator clips	necessary	\$	80.00	\$	80.00
2 pcs	Boot lid washer	damaged	\$	20.00	\$	20.00
1 pc	Boot lid lock snap	damaged	\$	40.00	\$	40.00
1 pc	Boot lid lock silencer	damaged	\$	83.80	\$	83.80
1 pc	Boot lid key cylinder	distorted	\$	97.20	\$	97.20
	Tail lamp	cracked	\$	993.00	\$	993.00
	Tail lamp top garnish	distorted	\$	222.00	\$	222.00
	Tail lamp sealant	necessary	\$	120.00	\$	120.00
	Tail lamp clips	necessary	\$	40.00	\$	40.00
	Tail lamp base panel	damaged	\$	420.00	\$	420.00

2 pcs	Rear fender		bent/distorted	\$ 4,852.00	\$ 4,852.00
2 pcs	Rear fender lower extention panel		bent/distorted	\$ 632.00	\$ 632.00
2 pcs	Rear fender protector		deformed	\$ 560.00	\$ 560.00
6 pcs	Rear fender protector clips		necessary	\$ 60.00	\$ 60.00
2 pcs	rear fender glass moulding		necessary	\$ 380.00	\$ 380.00
8 pcs	Rear fender glass clips		necessary	\$ 80.00	\$ 80.00
2 pcs	Rear fender splash shield		distorted	\$ 280.00	\$ 280.00
8 pcs	Rear fender splash shield clips		necessary	\$ 90.00	\$ 90.00
2 pcs	Rear fender inner trim board		bent/distorted	\$ 580.00	\$ 580.00
8 pcs	Rear fender inner trim board clips		necessary	\$ 120.00	\$ 120.00
1 pc	Rear end panel		bent/distorted	\$ 691.00	\$ 691.00
1 pc	Fuel tank breathe tank		bent/distorted	\$ 149.00	\$ 149.00
2 pcs	Floor panel under cover		distorted	\$ 650.00	\$ 650.00
1 pc	Rear boot inner board cover		deformed	\$ 280.00	\$ 280.00
2 pcs	Rear sub chassis frame member		damaged	\$ 1,167.00	\$ 1,167.00
2 pcs	Rear number plate lamp		cracked	\$ 76.00	\$ 76.00
1 pc	Rear number plate lamp garnish		necessary	\$ 121.60	\$ 121.60
			Parts Sub-Total	\$ 64,600.45	\$ 64,600.45
		Discount	10.00%	\$ 6,460.05	\$ 6,460.05
				\$ 58.140.41	\$ 58.140.41

Vehicle Number: SFH9090S

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
	Special Nett Items			
1 pc	Battery	damaged	\$ 420.00	\$ 220.00
1 set	Reverse sensor	electronically shocked	\$ 380.00	\$ 350.00
2 pcs	Number plate casing	bent	\$ 120.00	\$ 120.00
1 pc	Rear windscreen glass sealant	necessary	\$ 120.00	\$ 120.00
1 pc	Front number plate	damaged	\$ 65.00	\$ 65.00
1 pc	Rear number plate	damaged	\$ 65.00	\$ 65.00
1 set	Engine harness	electronically shocked	\$ 4,850.00	\$ 4,850.00
		Special Nett Sub-Total	\$ 6,020.00	\$ 5,790.00
		Spare Parts Total	\$ 64,160.41	\$ 63,930.41

LABOUR COST

S/No	JOB DESCRIPTIONS		Norkshop Estimation (S\$)	Our Revised Estimation (S\$)	
	Spare PartsTotal c/f	\$	64,160.41	\$ 63,930.41	
1	Towing 2 trips	\$	280.00	\$ 280.00	
2	To check and reconnect snap wiring	\$	250.00	\$ 240.00	
3	To tuff coat affected areas	\$	300.00	\$ 280.00	
4	To remove and replace interior upholstery	\$	300.00	\$ 280.00	
5	To remove and refix rear windscreen glass	\$	180.00	\$ 150.00	
6	To remove and replace rear exhaust silencer and straighten exhaust centre pipe	\$	280.00	\$ 250.00	
7	To adjust chassis alignment on Car O Liner	\$	380.00	\$ 350.00	
8	To remove and replace air cond condensor, piping vacuum and top up gas	\$	180.00	\$ 150.00	
9	To remove and replace radiator, hoses, fan and top up coolant	\$	180.00	\$ 150.00	
10	To remove and replace reverse sensor	\$	180.00	\$ 150.00	
11	To remove and replace exhaust catalytic converters, alternator, air cond compressor, air cleaner box and etc	\$	380.00	\$ 350.00	
12	To respray affected areas	\$	2,800.00	\$ 2,600.00	
13	To renew damaged parts, straighten and repair front and rear chassis member, rear & front fender, front door and aligned all parts.	\$	2,800.00	\$ 2,600.00	
14	To reprogram electical module system	\$	580.00	\$ 550.00	
15	To remove and replace steerng wheel and air bag sesnor	\$	500.00	\$ 450.00	
16	To remove and replace engine mounting	\$	250.00	\$ 240.00	
17	To remove & refix fuel tank assy to assist repairs.	\$	200.00	\$ 180.00	
18	To remove & replace wire harness complete	\$	800.00	\$ 700.00	