



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

INV No. AC2004539
INV Date 24/06/2020
Reference CS/AGI20003685/Asf3n2
Code AGI



PROFESSIONAL SERVICE FEE

Vehicle No. SLK 4473S
Insured Veh. SJP 9747S
Claim No. C10005804
Policy No.
Accident Date 04/03/2020
Inspection Date 10/03/2020

Description	Total
Survey Inspection	350.00
Digital Photographs	
Transportation	
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20003685/Asf3n2

(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Date : 24-06-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJP 9747S	Veh. Inspected	SLK 4473S
Policy No.		Coverage (\$)	0.00
Claim No.	C10005804	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	06/03/2020

2. Vehicle Particulars & Condition

Make & Model	OPEL ASTRA	c.c	999
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	W0LBE8EA2H8037542	Colour	GREY
Odometer	39993	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm
L/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/03/2020	Inspection Date	10/03/2020
Survey held at	1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUNTH WING) SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 4473S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT BUMPER	DEFORMED	1,500.00	1,500.00
1	FRT BUMPER SIDE RETAINER LH,GUIDE	NOT NECESSARY	60.00	-
1	FRT BUMPER SIDE BRACKET LH	NOT NECESSARY	58.00	-
1	FRT BUMPER TOW COVER	NOT NECESSARY	40.00	-
1	FRT BUMPER CLIP SET,RIVET	NECESSARY	40.00	40.00
1	LH HEADLAMP	CUT	820.00	820.00
1	FRT FENDER LH	NOT NECESSARY	740.00	-
1	FRT UPPER GRILLE	NOT NECESSARY	420.00	-
1	FRT LOWER GRILLE	NOT NECESSARY	210.00	-
1	FRT EMBLEM	NOT NECESSARY	120.00	-
1	FRT LH FOG LAMP	NOT NECESSARY	320.00	-
1	FRT LH FOG LAMP COVER	NOT NECESSARY	110.00	-
4	FRT BUMPER PARKING SENSOR	NOT NECESSARY	420.00	-
4	FRT BUMPER PARKING SENSOR SEAL	NOT NECESSARY	40.00	-
1	FRT BUMPER PARKING SENSOR WIRE HARNESS	NOT NECESSARY	618.00	-
1	FRT FENDER INNERSHIELD LH	NOT NECESSARY	180.00	-
1	FRT ENGINE UNDER DUST COVER LH	NOT NECESSARY	80.00	-
1	FRT BUMPER UNDER DUST COVER	NOT NECESSARY	190.00	-
	LESS 10% DISCOUNT		-596.60	-236.00
			5,369.40	2,124.00
<u>SPECIAL NETT ITEMS</u>				
1	FRT NUMBER PLATE (SN)	NOT NECESSARY	40.00	-
			40.00	-
<u>LABOUR</u>				
	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION,TO PANEL BEATING,RESHAPE,STRAIGHTEN, ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS.		2,800.00	650.00
	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA.(FRT BUMPER,LHF FENDER).		1,850.00	550.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		40.00	40.00

Report Ref No. CS/AGI20003685/Asf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT 4 WHEEL ALIGNMENT.	NOT NECESSARY	50.00	-
			4,740.00	1,240.00
GRAND TOTAL			10,149.40	3,364.00
RECOMMENDED COST OF REPAIRS				3,364.00

Report Ref No. CS/AGI20003685/Asf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLK 4473S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

