

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CC3/AIG20003694/EYF3E2**Date:** 13/07/2020**REFERENCE**

Insured/Claimant:	GUNARAVI RAJENDRAN	Policy No:	2100398005-05
Date of Loss:	05/03/2020	Nature of Claim:	OD Claim No: 4466567296SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SDA8777L</b>		
Make & Model:	AUDI A4, 1.8 TFSI MU (EU6) (A)	Engine No:	CJE091344
Reg. Date:	31/12/2014 (Man. Year: 2014)	Chassis No:	WAUZZZ8K7FA056816
Colour:	Grey	Odometer:	107394 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$70,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/55 R16	Rear Tyre Size:	225/55 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,920.00	1,972.48	6,947.52	77.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,002.00	2,902.00	2,100.00	41.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>13,922.00</b>	<b>4,874.48</b>	<b>9,047.52</b>	<b>64.99</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	974.54	341.21	633.33	64.99
<b>Nett Amount (\$\$)</b>	<b>14,896.54</b>	<b>5,215.69</b>	<b>9,680.85</b>	<b>64.99</b>

**INSPECTION**

Date of Assignment:	06/03/2020	
Date Inspected:	06/03/2020	Inspected At: 24 BENOI SECTOR
		Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	5.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** YVONNE WONG YIN CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	2,169.00 FS	*1,735.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	244.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	215.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	127.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	Not Necessary	183.00 FS	*- FS
6	1		*FRONT BUMPER SUPPORT ELEMENT - UPPER	Not Necessary	56.00 FS	*- FS
7	1		*FRONT BUMPER VENT GRILLE - RH	Not Necessary	127.00 FS	*- FS
8	1		*FRONT WHEEL SPOILER - RH	Not Necessary	48.00 FS	*- FS
9	1		*FRONT BUMPER GUIDE SECTION - RH	Broken	34.00 FS	*27.12 FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	117.00 FS	*- FS
11	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	828.00 FS	*- FS
12	2		*FRONT BUMPER SUPPORT	Broken	24.00 FS	*18.72 FS
13	1		*FRONT FENDER - RH	Repair	932.00 FS	*- FS
14	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	54.00 FS	*- FS
15	1		*FRONT FENDER BRACKET - RH FRONT	Not Necessary	50.00 FS	*- FS
16	1		*DEFORMATION ELEMENT - RH REAR	Not Necessary	46.00 FS	*- FS
17	1		*FRONT FENDER BRACE - RH LOWER	Not Necessary	112.00 FS	*- FS
18	1		*STONE CHIP GUARD	Not Necessary	69.00 FS	*- FS
19	1		*ADHESIVE TAPE	Not Necessary	52.00 FS	*- FS
20	1		*WHEEL HOUSING LINER - RH	Not Necessary	226.00 FS	*- FS
21	1		*WHEEL HOUSING LINER ATTACHMENT PARTS - RH	Necessary	42.00 FS	*33.44 FS
22	1		*HEADLIGHT MOUNTING - RH	Not Necessary	112.00 FS	*- FS
23	1		*HEADLAMP BRACKET - RH	Not Necessary	100.00 FS	*- FS
24	1		*HEADLIGHT - RH	Not Necessary	2,208.00 FS	*- FS
25	1		*HALOGEN FOG LAMP - RH	Not Necessary	247.00 FS	*- FS
26	1		*LIFT CYLINDER - RH	Broken	198.00 FS	*158.00 FS
27	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**      **8,920.00**      **1,972.48**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,450.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>5,002.00</b>	<b>2,902.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >