

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20003697/APA3Q2

Date: 20/11/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNCV2018-00000628

Claimant
Vehicle No : SLR7906D **Insured Vehicle No :** SLJ1697M

Date of Loss: 05/03/2020 Nature of Claim: TP Claim No: 1202000011630

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR7906D		
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Engine No:	LEB5954290
Reg. Date:	28/08/2017 (Man. Year: 2017)	Chassis No:	RU31254273
Colour:	Black	Odometer:	199185 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,741.68	3,519.28	222.40	5.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,960.00	890.00	1,070.00	54.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,701.68	4,409.28	1,292.40	22.67
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	5,701.68	3,500.00	2,201.68	38.61
+ GST 7.00/7.00% (S\$)	399.12	245.00	154.12	38.61
Nett Amount (S\$)	6,100.80	3,745.00	2,355.80	38.61
+ Car Rental (5.0 x S\$62.95/day) (S\$)		314.75		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,067.20		

INSPECTION

Date of Assignment: 05/03/2020

Date Inspected: 06/03/2020 Inspected At:

N-51 Automotive Pte Ltd (HQ)
BLK 2 KAKI BUKIT, #01-17/18 KAKI
BUKIT AUTOHUB
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jun 2020)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR7906D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR AXLE	Bent	1,650.00 FL	*1,650.00 FL
2	1		*REAR LH DOOR	Dented	930.60 FL	*930.60 FL
3	1		*REAR LH DOOR BLACK TAPE	Necessary	35.00 FL	*35.00 FL
4	1		*REAR LH DOOR TRANSPARENT	Necessary	35.00 FL	*35.00 FL
5	1		*REAR LH DOOR WEATHERSTRIP	Not Necessary	98.00 FL	*- FL
6	1		*REAR LH DOOR WEATHERSTRIP (LOWER)	Not Necessary	65.00 FL	*- FL
7	1		*REAR LH DOOR WEATHERSTRIP (VERTICAL)	Not Necessary	65.00 FL	*- FL
8	1		*REAR LH FENDER ARCH GARNISH	Cut	195.00 FL	*195.00 FL
9	1		*REAR LH SPORT RIM	Cut	850.00 FL	*850.00 FL
10	1		*REAR LH WHEEL BEARING	Damaged	263.50 FL	*263.50 FL
11	1		*ROCKER GARNISH LH	Deformed	377.50 FL	*377.50 FL
12	1		*SET REAR LH FENDER ARCH GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS
13	1		*SET ROCKER GARNISH CLIPS LH	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,654.60	4,386.60
- List Item Discount on L Items 20.00/20.00% (S\$)	912.92	867.32
Total Parts (S\$)	3,741.68	3,519.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,CHARGE REAR SUSPENSION PARTS ,AXLE CARRIAGE ,ABSORBER ,LOWER ARM ,TOP ARM,TRAILING ARM ,KNUCKLE ARM ,WHEEL BEARING ,BEARING HUB AND ETC	New	380.00	280.00
2	TO ROAD TEST DRIVING CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM	New	120.00	80.00
3	TO TRANSFER DOOR GLASS ,REGULATOR GEAR ,MOTOR ,RAILING ,CHANNEL ,TRIM BOARD ,MECHANISM LOCK AND HANDLE	New	80.00	80.00
4	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	800.00	200.00
5	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND REALIGN BODY STRUCTURE ,BODY ALIGNMENT AND DAMAGED CONSISTENT TO THE ACCIDENT	New	500.00	250.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	0.00
Gross Labour Cost (\$\$)			1,960.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >