

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20003699/UES3Q2

Date: 15/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800031913

Claimant
Vehicle No : SLR983B **Insured Vehicle No :** SLX4788R

Date of Loss: 06/03/2020 Nature of Claim: TP Claim No: 2223551118SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR983B	Engine No:	P520454276
Make & Model:	MAZDA 3, 1.5 SEDAN EU6 (A)	Chassis No:	JM6BN22A8H0161993
Reg. Date:	31/07/2017 (Man. Year: 2017)	Odometer:	33540 km
Colour:	Brown		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,105.00	9,651.84	18,453.16	65.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,900.00	2,870.00	2,030.00	41.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	33,005.00	12,521.84	20,483.16	62.06
Approved Total (Overridden) (\$\$)		10,000.00		
(\$\$)	33,005.00	10,000.00	23,005.00	69.70
+ GST 7.00/7.00% (\$\$)	2,310.35	700.00	1,610.35	69.70
Nett Amount (\$\$)	35,315.35	10,700.00	24,615.35	69.70
+ Loss of Use (7.0 x S\$60.00/day) (\$\$)		420.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		11,122.00		

INSPECTION

Date of Assignment: 06/03/2020

Date Inspected: 06/03/2020 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	1,255.20 F	*- FL
2	1		*BOOTLID REAR LOGO	Not Necessary	65.80 F	*- FL
3	1		*BOOTLID INNER LOCK	Not Necessary	288.20 F	*- FL
4	1		*BOOTLID WEATHERSTRIP	Twisted	291.40 F	*188.20 FL
5	1		*REAR BUMPER	Dented / Deformed	1,215.30 F	*1,074.80 FL
6	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	111.20 F	*- FL
7	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
8	1		*REAR BUMPER REINFORCEMENT	Dented	745.20 F	*537.30 FL
9	2		*REAR BUMPER REFLECTORS	Not Necessary	210.00 F	*- FL
10	1		*REAR END PANEL	Dented	635.00 F	*530.40 FL
11	1		*REAR END PANEL TOP GARNISH	Twisted	366.50 F	*214.50 FL
12	1		*REAR FLOOR PANEL	Repair	1,420.20 F	*- FL
13	1		*REAR FLOOR PANEL TOP SPONGE	Torn	488.50 F	*425.50 FL
14	2		*TAILLAMPS	Cracked	2,102.00 F	*1,830.00 FL
15	2		*REAR FENDER INNER TRIMS	Not Necessary	776.00 F	*- FL
16	1		*FRONT BUMPER	Dented / Torn	1,285.30 F	*1,031.70 FL
17	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	181.00 F	*- FL
18	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
19	1		*FRONT BUMPER REINFORCEMENT	Dented	751.00 F	*444.50 FL
20	1		*FRONT BUMPER REINFORCEMENT GARNISH	Torn	188.20 F	*92.20 FL
21	2		*FRONT BUMPER INNER BRACKETS	Torn	121.00 F	*70.00 FL
22	2		*FRONT BUMPER LOWER COVERS	Missing	70.00 F	*30.00 FL
23	1		*FRONT GRILLE LOGO	Scratched	105.00 F	*44.20 FL
24	1		*FRONT GRILLE TOP GARNISH	Dented / Deformed	385.00 F	*335.00 FL
25	1		*FRONT GRILLE INNER BRACKET	No such part	121.00 F	*- FL
26	2		*HEADLAMPS	Cracked	6,500.00 F	*2,141.00 FL
27	1		*FRONT SUPPORT PANEL	Repair	705.00 F	*- FL
28	1		*AIR CON CONDENSER	Not Necessary	1,019.00 F	*- FL
29	1		*RADIATOR	Not Necessary	1,465.00 F	*- FL
30	1		*FRONT GRILLE OUTER MOULDING	Cracked	288.00 F	*288.00 FL
31	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
32	1		*REAR BUMPER LOWER SKIRTING	Cracked	1,200.00 FS	*800.00 FS
33	1		*SET REAR BUMPER CARBON SIDE GARNISH	Not Necessary	600.00 FS	*- FS
34	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
35	1		*FRONT LICENCE PLATE W/HOLDER	Cracked	50.00 FS	*40.00 FS
36	1		*FRONT AXELA EMBLEM	Necessary	120.00 FS	*60.00 FS
37	1		*FRONT GRILLE SPORT	Cracked	1,050.00 FS	*750.00 FS
38	1		*FRONT BUMPER LOWER SKIRTING	Repair	1,200.00 FS	*- FS
39	1		*SET HEADLAMP CARBON GARNISH	Necessary	300.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 28,105.00 11,527.30
- List Item Discount on L Items 0.00/20.00% (\$\$) 0.00 1,875.46

Total Parts (\$\$) 28,105.00 9,651.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO MOUNT VEHICLE ON CAR O-LINE	New	380.00	0.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO SPRAY RUST PROOFING	New	120.00	30.00
6	TO REFILL AIR CON GAS	New	120.00	0.00
7	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,800.00	1,200.00
8	TO PUTTY & SPRAY PAINTING	New	2,200.00	1,480.00
Gross Labour Cost (S\$)			4,900.00	2,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >