

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20003700/UPS3Q2**Date:** 17/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994310
Claimant Vehicle No :	GBC9585E	Insured Vehicle No :	SLD5452H
Date of Loss:	02/03/2020	Nature of Claim:	TP
		Claim No:	9017579162SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC9585E	Engine No:	198A30007002524
Make & Model:	FIAT DOBLO, 1.3 D SX Cargo (M)	Chassis No:	ZFA26300006106228
Reg. Date:	17/03/2014 (Man. Year: 2014)	Odometer:	113958 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Lassa 6 mm	Rear Left Side:	Lassa 6 mm
Front Right Side:	Lassa 6 mm	Rear Right Side:	Lassa 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,992.30	1,237.07	755.23	37.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,070.00	770.00	300.00	28.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,062.30	2,007.07	1,055.23	34.46
Approved Total (Overridden) (S\$)		1,600.00		
Nett Amount (S\$)	3,062.30	1,600.00	1,462.30	47.75
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,847.45		
Global Sum Settlement (S\$)		1,800.00		

INSPECTION

Date of Assignment:	06/03/2020	
Date Inspected:	06/03/2020 Inspected At:	Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	627.00 F	*627.00 FL
2	1		*REAR BUMPER CLIPS (1SET)	Necessary	50.00 F	*50.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	475.30 F	*475.30 FL
4	1		*END PANEL	Repair	620.00 F	*- FL
5	1		*REAR BUMPER REVERSE SENSOR (1 SET)	Shorted	220.00 FS	*200.00 FS
					F=Franchise part. S=SpcNett. L=ListItemDisc.	
					Sub Total (\$)	1,992.30 1,352.30
					- List Item Discount on L Items 0.00/10.00% (\$)	0.00 115.23
					Total Parts (\$)	1,992.30 1,237.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUCTION	New	50.00	20.00
2	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR	New	120.00	50.00
3	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	400.00	300.00
4	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA	New	500.00	400.00
Gross Labour Cost (\$)			1,070.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >