

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20003701/T1EA3Q2

Date: 23/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900016387

Claimant
Vehicle No : SLZ3194A **Insured Vehicle No :** SDJ9869B

Date of Loss: 28/02/2020 Nature of Claim: TP Claim No: 0126664521SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ3194A		
Make & Model:	HONDA STREAM, 1.8 L RSZ (A)	Engine No:	R18A13850326
Reg. Date:	04/05/2009 (Man. Year: 2009)	Chassis No:	JHMRN68809C200327
Colour:	Black	Odometer:	279319 km
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,130.80	4,668.64	3,462.16	42.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	2,390.00	1,140.00	32.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,660.80	7,058.64	4,602.16	39.47
Approved Total (Overridden) (\$\$)		5,600.00		
(\$\$)	11,660.80	5,600.00	6,060.80	51.98
+ GST 7.00/7.00% (\$\$)	816.26	392.00	424.26	51.98
Nett Amount (\$\$)	12,477.06	5,992.00	6,485.06	51.98
+ Loss of Use (7.0 x S\$80.00/day) (\$\$)		560.00		
+ Doc/Search Fee (\$\$)		36.45		
Nett Liability (\$\$)		6,588.45		
Global Sum Settlement (\$\$)		6,580.00		

INSPECTION

Date of Assignment: 06/03/2020

Date Inspected: 06/03/2020 Inspected At:

BLK 8 SIN MING INDUSTRIAL
ESTATE SECTOR C #01-68
SINGAPORE 575643
Repairer: Em-1 Auto Pte Ltd (sin Ming)
(HQ)

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	986.00 FL	*986.00 FL
2	1		*TAILGATE BADGE	Necessary	62.00 FL	*62.00 FL
3	1		*TAILGATE EMBLEM RSZ	Necessary	62.00 FL	*62.00 FL
4	1		*TAILGATE EMBLEM STREAM	Necessary	58.00 FL	*58.00 FL
5	1		*TAILGATE OUTER GARNISH	Cracked	329.50 FL	*329.50 FL
6	1		*SET TAILGATE OUTER GARNISH CLIPS	Necessary	30.00 FL	*20.00 FL
7	1		*TAILGATE WINDSCREEN MOULDING	Necessary	92.80 FL	*92.80 FL
8	1		*SET TAILGATE WINDSCREEN CLIPS	Necessary	20.00 FL	*20.00 FL
9	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FL	*60.00 FL
10	2		*TAILGATE STOPPER	Not Necessary	36.00 FL	*- FL
11	1		*TAILGATE POCKET HANDLE	Deformed	46.20 FL	*46.20 FL
12	1		*TAILGATE INNER TRIM	Cracked	326.20 FL	*326.20 FL
13	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	40.00 FL	*40.00 FL
14	1		*TAILGATE INNER LOCK	Bent	292.50 FL	*292.50 FL
15	1		*TAILGATE WIPER MOTOR	Not Necessary	356.50 FL	*- FL
16	1		*TAILGATE LOCK CATCH	Not Necessary	46.00 FL	*- FL
17	1		*TAILGATE WEATHERSTRIP	Torn	192.60 FL	*192.60 FL
18	2		*TAILGATE ABSORBER	Not Necessary	290.00 FL	*- FL
19	2		*TAILGATE HINGES	Not Necessary	104.00 FL	*- FL
20	1		*REAR BUMPER	Deformed	623.90 FL	*623.90 FL
21	2		*REAR BUMPER SIDE RETAINERS	Deformed	76.00 FL	*76.00 FL
22	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
23	2		*REAR BUMPER DAMPERS	Not Necessary	104.00 FL	*- FL
24	1		*TAILLAMPS	N/S Not Necessary / O/S Cut	684.00 FL	*342.00 FL
25	1		*TAILLAMPS INNER SEALER	N/SNot Necessary /O/SNecessary	60.00 FL	*30.00 FL
26	1		*SET TAILLAMPS CLIPS	N/SNot Necessary /O/SNecessary	50.00 FL	*25.00 FL
27	1		*TAILLAMPS BOTTOM GARNISH	N/S Not Necessary /O/SDeformed	96.00 FL	*48.00 FL
28	1		*END PANEL (OUTER)	Bent	425.00 FL	*425.00 FL
29	1		*END PANEL (INNER)	Bent	279.60 FL	*279.60 FL
30	1		*END PANEL TOP TRIM	Deformed	121.50 FL	*121.50 FL
31	1		*SET END PANEL TOP TRIM CLIPS	Necessary	30.00 FL	*20.00 FL
32	1		*REAR FLOOR PANEL	Repair	858.00 FL	*- FL
33	1		*REAR FLOOR PANEL TOP SIDE BOARD	N/S Not Necessary /O/S Cracked	330.00 FL	*165.00 FL
34	1		*REAR FENDER INNER TRIM	O/S Cracked	464.00 FL	*232.00 FL
35	1		*SET REAR FENDER INNER TRIM CLIPS	O/S Necessary	60.00 FL	*30.00 FL
36	1		*SPARE TYRE CARRIER	Repair	275.00 FL	*- FL
37	1		*SPARE TYRE CARRIER BOLT	Not Necessary	38.00 FL	*- FL
38	1		*SPARE TYRE CARRIER NUT	Not Necessary	36.00 FL	*- FL
39	1		*REAR EXHAUT SILENCER	Repair	594.50 FL	*- FL
40	2		*REAR EXHAUT MOUNTINGS	Not Necessary	72.00 FL	*- FL
41	1		*REAR EXHAUST GASKET	Not Necessary	46.00 FL	*- FL
42	1		*REAR EXHAUST HEAT PLATE	Not Necessary	97.20 FL	*- FL
43	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
44	1		*SET BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*40.00 FS
45	1		*SET REAR FLOOR PANEL INSULATOR PAD	Necessary	150.00 FS	*80.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	4		*REVERSE SENSOR	Not Working	450.00 FS	*250.00 FS
47	1		*REAR NUMBER PLATE	Cut	50.00 FS	*30.00 FS
48	1		*REAR EXHAUST CHROME PIPE	Bent	180.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,911.00	5,675.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,780.20	1,007.16

Total Parts (\$\$)	8,130.80	4,668.64
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,600.00	1,000.00
2	SPRAY PAINTING	New	1,200.00	1,000.00
3	CHECK WIRING	New	50.00	30.00
4	ANTI RUST	New	120.00	30.00
5	REMOVE AND INSTALL REAR WINDSCREEN	New	140.00	120.00
6	REMOVE AND INSTALL TAILGATE PARTS	New	90.00	60.00
7	REMOVE AND INSTALL REVERSE SENSOR	New	90.00	30.00
8	REMOVE AND INSTALL REAR EXHAUST SILENCER	New	120.00	60.00
9	REMOVE AND INSTALL CARPET AND SEAT	New	120.00	60.00
Gross Labour Cost (\$)			3,530.00	2,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >