

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20003709/GKA3Q2

Date: 09/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700021801
Claimant
Vehicle No : SMJ6060E **Insured Vehicle No :** SKN1955J
 Date of Loss: 04/03/2020 Nature of Claim: TP Claim No: 7940327745SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMJ6060E**
 Make & Model: VOLKSWAGEN GOLF, 1.4 TSI (A7) (5G13GZ) Engine No: CZC409132
 (A)
 Reg. Date: 05/04/2016 (Man. Year: 2015) Chassis No: VVWZZZAUZGW059093
 Colour: Red Odometer: 68716 km
 Engine Capacity: 1395 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,622.78	2,129.24	493.54	18.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,520.00	2,540.00	3,980.00	61.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,142.78	4,669.24	4,473.54	48.93
+ GST 7.00/7.00% (S\$)	639.99	326.85	313.14	48.93
Nett Amount (S\$)	9,782.77	4,996.09	4,786.68	48.93
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,178.09		

INSPECTION

Date of Assignment: 11/03/2020
 Date Inspected: 11/03/2020 Inspected At: 1 KAMPONG AMPAT OFF
 MACPHERSON
 Repairer: Volkswagen Group
 Singapore Pte Ltd (tuas) (HQ)
 Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR RHR	Buckled	1,987.16 FS	*1,987.16 FS
2	1		*DOOR SEAL OUTER RHR	Necessary	100.68 FS	*100.68 FS
3	1		*SOUND ABSORBER LAMINATED	Necessary	41.40 FS	*41.40 FS
4	1		*DOOR HINGE RHR UPPER	Not Necessary	129.72 FS	* - FS
5	1		*DOOR HINGE RHR LOWER	Not Necessary	129.72 FS	* - FS
6	1		*GLASS CHANNEL BLACK	Not Necessary	234.10 FS	* - FS
Total Parts (S\$)					2,622.78	2,129.24

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	0.00
3	LABOUR	New	2,520.00	840.00
4	SPRAY PAINTING	New	2,400.00	800.00
5	TRANSFER DOOR MECHANISM	New	840.00	420.00
			Gross Labour Cost (\$)	2,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >