

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20003710/KGA3N2

Date: 20/05/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MFL0002083_01
Claimant Vehicle No :	GBJ4520M	Insured Vehicle No :	GBH7133M
Date of Loss:	04/03/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0000584

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ4520M		
Make & Model:	FIAT NEW DOBLO SX, 1.6 MJ E6 GLA (A)	Engine No:	263A80008156910
Reg. Date:	23/04/2019 (Man. Year: 2017)	Chassis No:	ZFA26300006H36730
Colour:	Metallic Dark Grey	Odometer:	18491 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,993.42	4,839.01	5,154.41	51.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,200.00	3,620.00	2,580.00	41.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,193.42	8,459.01	7,734.41	47.76
+ GST 7.00/7.00% (S\$)	1,133.54	592.13	541.41	47.76
Nett Amount (S\$)	17,326.96	9,051.14	8,275.82	47.76
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,658.59		

INSPECTION

Date of Assignment: 09/03/2020

Date Inspected: 09/03/2020 Inspected At:

Goldbell Engineering Pte Ltd (Ang Mo Kio)
Blk 5035 Ang Mo Kio Industrial Park 2,
#01-345
Singapore 569538

Repairer : Motorviva Pte Ltd

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Apr 2020)	
Parts:	N/A	FIAT NEW DOBLO SX 1.6 MJ E6 GLA (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ4520M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BACK DOOR LH	Bent	1,796.48 F	*1,796.48 FL
2	1	*REAR BACK DOOR RH	Bent	1,790.71 F	*1,790.71 FL
3	1	*REAR BACK DOOR PANEL LH	Not Necessary	243.39 F	*- FL
4	1	*REAR BACK DOOR PANEL RH	Not Necessary	173.32 F	*- FL
5	1	*REAR BACK DOOR PANEL CLIPS (40%)	Not Necessary	120.00 F	*- FL
6	1	*REAR BACK DOOR LH HINGE BOTTOM	Not Necessary	146.72 F	*- FL
7	1	*REAR BACK DOOR LH HINGE TOP	Not Necessary	146.72 F	*- FL
8	1	*REAR BACK DOOR RH HINGE BOTTOM	Repair	146.72 F	*- FL
9	1	*REAR BACK DOOR RH HINGE TOP	Repair	146.72 F	*- FL
10	1	*REAR BACK DOOR LOCK LH	Not Necessary	178.55 F	*- FL
11	1	*REAR BACK DOOR CATCH RH	Not Necessary	72.72 F	*- FL
12	1	*REAR BACK DOOR LOCK RH	Not Necessary	230.23 F	*- FL
13	1	*REAR BACK DOOR CATCH LH	Not Necessary	115.67 F	*- FL
14	1	*REAR BACK DOOR MOULDING	Not Necessary	344.85 F	*- FL
15	1	*REAR BACK DOOR MOULDING UPPER	Not Necessary	85.16 F	*- FL
16	1	*REAR BACK DOOR MOULDING CENTER	Not Necessary	206.26 F	*- FL
17	1	*REAR BACK DOOR STEP	Not Necessary	84.60 F	*- FL
18	1	*REAR BACK DOOR HANDLE LH	Serviceable	300.96 F	*- FL
19	1	*REAR BACK DOOR HANDLE RH	Serviceable	82.93 F	*- FL
20	1	*REAR EMBLEM -FIAT	Necessary	75.68 F	*75.68 FL
21	1	*REAR WOLDING -PROFESSIONAL	Necessary	103.94 F	*103.94 FL
22	1	*REAR WOLDING -DOBLO	Necessary	65.34 F	*65.34 FL
23	1	*REAR WOLDING -MAXI	Necessary	40.36 F	*40.36 FL
24	1	*REAR WOLDING -10S	Necessary	47.47 F	*47.47 FL
25	1	*REAR WOLDING -MULTIJET2	Necessary	69.60 F	*69.60 FL
26	1	*TAILLAMP LH	Serviceable	417.55 F	*- FL
27	1	*TAILLAMP RH	Serviceable	417.55 F	*- FL
28	1	*REAR BUMPER	Bent	596.75 F	*596.75 FL
29	1	*REAR BUMPER RETAINER LH	Serviceable	26.75 F	*- FL
30	1	*REAR BUMPER RETAINER RH	Distorted	26.75 F	*26.75 FL
31	1	*REAR BUMPER REINFORCEMENT	Bent	258.04 F	*258.04 FL
32	1	*REAR BUMPER SEAL GASKET	Not Necessary	60.01 F	*- FL
33	1	*REAR BUMPER END PANEL	Not Necessary	312.95 F	*- FL
34	1	*REAR BUMPER REFLECTOR LH	Serviceable	21.07 F	*- FL
35	1	*REAR BUMPER REFLECTOR RH	Serviceable	21.07 F	*- FL
36	1	*REAR BUMPER TOWING COVER	Serviceable	14.83 F	*- FL
37	10	*REAR BUMPER SCREWS	Necessary	50.00 F	*50.00 FL
38	1	*WINDSCREEN SEALANT	Necessary	120.00 FS	*80.00 FS
39	1	*REAR VEHICLE NUMBER PLATE WITH CHASING	Serviceable	35.00 FS	*- FS
40	1	*REVERSE SENSOR	Dented	350.00 FS	*200.00 FS
41	1	*STICKER -COMPANY LOGO	Necessary	400.00 FS	*100.00 FS
42	1	*STICKER -SPEED LIMIT (70KM/H)	Necessary	25.00 FS	*15.00 FS
43	1	*STICKER -6 PAX	Necessary	25.00 FS	*15.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					9,993.42	5,331.12
- List Item Discount on L Items 0.00/10.00% (S\$)					0.00	492.11
Total Parts (S\$)					9,993.42	4,839.01

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REFIX & REPAIR AFFECTED DAMAGED PARTS .INCLUDING KNOCK OUT ,WELD AND STRAIGHTEN ON THE AFFECTED PARTS	New	2,800.00	1,800.00
2	TO REMOVE AND REFIX BOTH REAR DOOR WINDSCREEN	New	200.00	160.00
3	TO TRANSFER DOOR COMPARTMENT,LOCK AND MECHANISM ETC	New	500.00	240.00
4	TO TRANSFER ,CHECK ,RECONNECT ALL NECESSARY WIRING SYSTEM AND CHECK FUNCTIONALLY	New	200.00	20.00
5	TO SAND DOWN ,PUTTY,CLEAN ,WASH,POLISH AND SPRAY INTERIOR AND EXTERIOR BOTH REAR BACK DOOR ,REAR BUMPER AND END PANEL TO ORIGINAL COLOURS	New	2,500.00	1,400.00
Gross Labour Cost (\$\$)			6,200.00	3,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >