

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20003712/QQF3Q2

**Date:** 29/10/2020

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSN30213119000	
Claimant Vehicle No : SLQ9406Y	Insured Vehicle No : GBF8436T	
Date of Loss: 03/03/2020	Nature of Claim: TP	Claim No: SNM20D201152/C02/TAYHP

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLQ9406Y</b>		
Make & Model:	VOLKSWAGEN SCIROCCO R, 2.0 L AT 137RX3 (A)	Engine No:	CAW065446
Reg. Date:	31/08/2009 (Man. Year: 2009)	Chassis No:	WVWZZZ13ZAV403391
Colour:	Green	Odometer:	209325 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	235/35 R19	Rear Tyre Size:	235/35 R19
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,437.16	2,087.60	8,349.56	80.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,350.00	880.00	3,470.00	79.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,787.16</b>	<b>2,967.60</b>	<b>11,819.56</b>	<b>79.93</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,350.00</b>		
<b>Nett Amount (S\$)</b>	<b>14,787.16</b>	<b>2,350.00</b>	<b>12,437.16</b>	<b>84.11</b>

### INSPECTION

Date of Assignment:	06/03/2020	
Date Inspected:	09/03/2020 Inspected At:	1st Auto Pro (HQ) 51 Ubi Avenue 1, #05-02 Paya Ubi Industrial Park Singapore 408933
Estimated Period of Repair:	3.0 days	

**Adjuster:** OI SUN PIN

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 28 Oct 2020)
<b>Parts:</b>	M1-COUPE	VOLKSWAGEN SCIROCCO R 2.0 L AT 137RX3 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLQ9406Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Serviceable	1,625.00 FL	*- FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	173.00 FL	*- FL
3	1		*FRONT BUMPER BRACKET	Serviceable	85.20 FL	*- FL
4	1		*FRONT FENDER LH	Crumpled	922.60 FL	*650.00 FL
5	1		*FRONT FENDER INNER SHIELD LH	Cracked	840.00 FL	*200.00 FL
6	1		*FRONT KNUCKLE ARM LH	Serviceable	395.00 FL	*- FL
7	1		*FRONT LOWER ARM LH	Serviceable	345.00 FL	*- FL
8	1		*FRONT SHOCK ABSORBER LH	Serviceable	277.00 FL	*- FL
9	1		*FRONT WHEEL BEARING LH	Serviceable	365.00 FL	*- FL
10	1		*FRONT SIDE MIRROR COVER LH	Scratched	304.00 FL	*250.00 FL
11	1		*FRONT SIDE MIRROR SIGNAL LAMP LH	Scratched	214.00 FL	*214.00 FL
12	1		*FRONT DOOR LH	Repair	1,879.00 FL	*- FL
13	1		*FRONT DOOR HANDLE LH	Scratched	307.00 FL	*250.00 FL
14	1		*FRONT DOOR HINGE LH	Serviceable	241.00 FL	*- FL
15	1		*HEADLAMP LH	Serviceable	1,522.60 FL	*- FL
16	1		*HEADLAMP BRACKET LH	Serviceable	257.00 FL	*- FL
17	1		*FRONT RIM LH	Scratched	1,500.00 FS	*650.00 FS
18	1		*FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
19	1		*FRONT FENDER INNER SHIELD CLIPS	Serviceable	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>11,412.40</b>	<b>2,244.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	975.24	156.40
<b>Total Parts (\$)</b>	<b>10,437.16</b>	<b>2,087.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	CHECK WIRING AND LIGHTING SYSTEM	New	150.00	30.00
2	TO TRANSFER OLD BUMPER ATTACHMENT TO NEW	New	150.00	0.00
3	WRAPPING ON FRONT FENDER LH	New	1,000.00	0.00
4	WRAPPING ON FRONT SIDE MIRROR LH	New	250.00	0.00
5	WRAPPING ON FRONT DOOR HANDLE LH	New	200.00	0.00
6	PANEL BEATING ON AFFECTED AREA	New	1,500.00	600.00
7	SPRAY PAINTING ON AFFECTED AREA	New	1,000.00	220.00
8	APPLY ANTI RUST ON AFFECTED AREA	New	100.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,350.00</b>	<b>880.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**