

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI20003735/T1SF3E2

**Date:** 22/01/2021

### REFERENCE

Insured/Claimant: BEAN FOOD CULTURE Policy No: DMCVSN3074451900

Date of Loss: 24/02/2020 Nature of Claim: OD Claim No: SNM20D201060/YN9495B/TKL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YN9495B**  
Make & Model: MITSUBISHI CANTER, 3.0 D FEB21 (M) Engine No: 4P10B83256  
Reg. Date: 14/10/2015 (Man. Year: 2015) Chassis No: FEB21EA10533  
Colour: White Odometer: 0 km  
Engine Capacity: 2998 cc  
Market Value/New Car Price: S\$40,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/85 R15 Rear Tyre Size: 195/85 R15 (D)  
Front Left Side: Kenda 6 mm Rear Left Side: Kenda 6/6 mm  
Front Right Side: Kenda 6 mm Rear Right Side: Kenda 6/6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,303.00	19,998.00	14,305.00	41.70
Miscellaneous Items	7,186.00	5,136.00	2,050.00	28.53
Paintwork Materials	431.23	424.49	6.74	1.56
Labour	2,087.40	1,814.40	273.00	13.08
Paintwork Labour	1,117.20	1,100.40	16.80	1.50
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>45,124.83</b>	<b>28,473.29</b>	<b>16,651.54</b>	<b>36.90</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>22,750.00</b>		
<b>- Excess (S\$)</b>	0.00	450.00	-450.00	
<b>(S\$)</b>	45,124.83	22,300.00	22,824.83	50.58
<b>+ GST 7.00/7.00% (S\$)</b>	3,158.74	1,561.00	1,597.74	50.58
<b>Nett Amount (S\$)</b>	<b>48,283.57</b>	<b>23,861.00</b>	<b>24,422.57</b>	<b>50.58</b>

### INSPECTION

Date of Assignment: 09/03/2020 Present Location: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)  
Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)  
Date Inspected: 09/03/2020 Inspected At: Blk 3 Pioneer Road North, #01-18  
Singapore 628457  
Estimated Period of Repair: 28.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 22 Jan 2021)	
Parts:	N/A	mitsubishi canter 3.0 d feb21 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN9495B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SPARE PARTS		34,303.00 F	*19,998.00 F
F=Franchise part.						
Total Parts (S\$)					34,303.00	19,998.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Materials</u>				
1	1	TOTAL PAINT/MATERIAL	431.23	424.49
<u>Miscellaneous Items</u>				
2	1	SPARE PARTS SPECIAL NETT	7,186.00	5,136.00
Sub Total (S\$)			7,617.23	5,560.49

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TOTAL PAINTWORK	New	1,117.20	1,100.40
<u>Labour Items</u>				
2	TOTAL PANEL/MECHANICAL	New	2,087.40	1,814.40
Gross Labour Cost (S\$)			3,204.60	2,914.80

Report was unsubmitted during this print-out.

< END OF ESTIMATES >