Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CC4/AIG20003736/QBA3Q2 Our File No:

Date: 14/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800005236-01 Claimant SLP442G

Insured Vehicle No: FBK7588T Vehicle No:

Date of Loss: TP 24/12/2019 Nature of Claim: Claim No: 0888343278SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLP442G Reg No:

Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZRS049581

Reg. Date: 25/05/2017 (Man. Year: 2017) Chassis No: JTDKB3FU203559160

Colour: Odometer: 0 km Silver

Engine Capacity: 1798 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Firenza 5 mm Rear Left Side: Firenza 5 mm Front Right Side: Rear Right Side: Firenza 5 mm Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	924.60	924.60	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	650.00	550.00	100.00	15.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,574.60	1,474.60	100.00	6.35
Approved Total (Overridden) (S\$)		1,200.00		
(S\$)	1,574.60	1,200.00	374.60	23.79
+ GST 7.00/7.00% (S\$)	110.22	84.00	26.22	23.79
Nett Amount (S\$)	1,684.82	1,284.00	400.82	23.79
+ Loss of Use (3.0 x S	+ Loss of Use (3.0 x S\$80.00/day) (S\$)			
+ Doc/	+ Doc/Search Fee (S\$) Nett Liability (S\$)			
N				
Global Sum Settlement (S\$)		1,500.00		

INSPECTION

Date of Assignment: 06/03/2020

06/03/2020 Inspected At: Lion City Rentals Pte Ltd (HQ) Date Inspected:

60 Jalan Lam Huat, #04-01 Carros

Singapore 737869

Estimated Period of Repair: 2.0 days Adjuster Report Page 2 of 4

Adjuster: OI SUN PIN Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*F/L DOOR MIRROR	Cracked	1,232.80 FL	*1,232.80 FL
F=Fra	anchise	part. L=ListItemI	Disc.			
				Sub Total (S\$)	1,232.80	1,232.80
			- List Item Discount on L It	tems 25.00/25.00% (S\$)	308.20	308.20
				Total Parts (S\$)	924.60	924.60
			Report was uns	submitted during this print-o	ut.	

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO LABOUR CHARGE FOR REPAIR FRONT DOOR	New	250.00	250.00
2	TO RESPAY FRONT DOOR AND F/L DOOR MIRROR	New	400.00	300.00
	Gross Labour Cost (S\$)		650.00	550.00
	Report was unsubmitted du	uring this print-out.		

< END OF ESTIMATES >