

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## **TAX INVOICE**

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE

SINGAPORE 068877

INV No. AC2004742

INV Date 06/07/2020

Reference CC4/FCI20003740/Uba3q2

Code FCI2

## **PROFESSIONAL SERVICE FEE**

Vehicle No. YP 5071G

Insured Veh. SHC 8568R

Claim No. D20000538MFSH

Policy No. D-20094922MFSH

Accident Date 20/01/2020

Inspection Date 09/03/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Affiliated to Federation Internationale Des Experts En Automobile								
MS F	FIRST CAPITAL INSURANCE LTD Ref: CC4/FCl20003740/Uba3q2							
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 06-07-2020 Code: FCI2						
1.	1. Policy Particulars :- THIRD PARTY CLAIM							
	Insured Veh.	SHC 8568R	Veh. Inspected	YP 5071G				
	Policy No.	D-20094922MFSH	Coverage (\$)	0.00				
	Claim No.	D20000538MFSH	Excess (\$)	0.00				
	Assign From	RACHEL WU	Assign Date	09/03/2020				
2.	2. Vehicle Particulars & Condition							
	Make & Model	MITSUBISHI CANTER FEB21 (M)	c.c	2998				
	Engine No.	HIDDEN	Year of Reg.	2016				
	Chassis No.	FEB21EA20831	Colour	WHITE				
	Odometer	64260	Steering	IN ORDER				
	Brakes	IN ORDER	Modification	NIL				
	General	GOOD						
3.		Condition	ons of Tyres					
		Size	Make	Balance				
	R/H Front Tyre	195 R15	AUSTONE	6 mm				
	L/H Front Tyre	195 R15	AUSTONE	6 mm				
	R/H Rear Tyre	195 R15 (D)	AUSTONE	6/6 mm				
	L/H Rear Tyre	195 R15 (D)	AUSTONE	6/6 mm				
4.		Description	on of Damages					
	THE VEHICLE SU	STAINED DAMAGES AT THE O/S	REAR PORTION.					
	DAMAGES SEE D	ETAILS.						
5.		General	Information					
	Accident Date	20/01/2020	Inspection Date	09/03/2020				
	Survey held at	rey held at LIU'S BROTHER AUTO ENGINEERING WORKSHOP						
	1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883							
5a.		Re	emarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.							
5b.	5b. Estimate Days of Repair							
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days							



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

650.00

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 5071G

RECOMMENDED COST OF REPAIRS

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR			
	LABOR FOR PANEL BEATING REAR CARGO BOX PANEL.		500.00	250.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA.		500.00	400.00
			1,000.00	650.00
	GRAND TOTAL		1,000.00	650.00

Report Ref No. CC4/FCI20003740/Uba3q2

CHUA KANG SENG

Licensed Appraiser




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

# PHOTOGRAPHS FOR VEHICLE NO. YP 5071G

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

RE-INSPECTION









