

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Mar 2020 Edit Reg		06 Mar 2020 00:00 Edit Adj Rpt	S\$12,700.00 Edit Estimates	S\$12,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by adjuster]						
Insured: COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R									
Main Claimant: TRANS-CAB SERVICES PTE LTD									
Vehicle Reg. No.: SHD514T		Date of Loss: 04/03/2020 00:00 - :59 [57 Months and 25 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / MCT20030075		Policy/Cover Note No.: MCOM0015							
Vehicle Reg. No. (Insured): SHC8943R		Policy No. (Claimant): VFX/P1680520							
		Excess:							
Repairer: Trans-cab Auto Services Pte Ltd () No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]									
Claimant's Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 20/03/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
- III_SG (27/05/2020): Alert - Adj Mandate Approved (S\$16465.79) - SHD514T - Claim Handler: Sundari Nag... - III_SG (16/03/2020): Alert - Adj Mandate Approved (S\$0.00) - SHD514T - Claim Handler: Sundari Nagaraj...									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHD514T (MCT20030075)**
[SHC8943R]
TP
TRANS-CAB SERVICES PTE LTD
Mar 4 2020 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Trans-cab Auto Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	23/09/20 15:13	Video - Accident-IV	 Load MP4	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/03/20 07:26	General View	 Load JPG	☒
2	16/03/20 07:26	General View	 Load JPG	☒
3	16/03/20 07:26	General View	 Load JPG	☒
4	16/03/20 07:26	General View	 Load JPG	☒
5	16/03/20 07:26	General View	 Load JPG	☒
6	16/03/20 07:26	General View	 Load JPG	☒
7	16/03/20 07:26	General View	 Load JPG	☒
8	16/03/20 07:26	General View	 Load JPG	☒
9	16/03/20 07:26	General View	 Load JPG	☒
10	16/03/20 07:26	General View	 Load JPG	☒
11	16/03/20 07:26	General View	 Load JPG	☒
12	16/03/20 07:26	General View	 Load JPG	☒
13	16/03/20 07:26	General View	 Load JPG	☒
14	16/03/20 07:26	General View	 Load JPG	☒
15	16/03/20 07:26	General View	 Load JPG	☒
16	16/03/20 07:26	General View	 Load JPG	☒
17	16/03/20 07:26	General View	 Load JPG	☒
18	16/03/20 07:26	General View	 Load JPG	☒
19	16/03/20 07:26	General View	 Load JPG	☒
20	16/03/20 07:26	General View	 Load JPG	☒
21	16/03/20 07:26	General View	 Load JPG	☒
22	16/03/20 07:26	General View	 Load JPG	☒
23	16/03/20 07:26	General View	 Load JPG	☒
24	16/03/20 07:26	General View	 Load JPG	☒
25	16/03/20 07:26	General View	 Load JPG	☒
26	16/03/20 07:26	General View	 Load JPG	☒
27	16/03/20 07:26	General View	 Load JPG	☒
28	16/03/20 07:26	General View	 Load JPG	☒
29	16/03/20 07:26	General View	 Load JPG	☒
30	16/03/20 07:26	General View	 Load JPG	☒
31	16/03/20 07:26	Odometer Reading	 Load JPG	☒
32	16/03/20 07:26	Chassis Number	 Load JPG	☒
33	16/03/20 07:26	General View	 Load JPG	☒
34	16/03/20 07:26	General View	 Load JPG	☒
35	16/03/20 07:26	General View	 Load JPG	☒
36	16/03/20 07:26	General View	 Load JPG	☒
37	16/03/20 07:26	General View	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
38	16/03/20 07:26	General View	 Load JPG	☒
39	22/05/20 14:58	Photo After Spray	 Load JPG	☒
40	22/05/20 14:58	Photo After Spray	 Load JPG	☒
41	22/05/20 14:58	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/03/20 15:06	TP ESTIMATE - MARKED	 Load PDF	
2	23/03/20 16:13	TP GIA REPORT	 Load PDF	
3	22/05/20 14:58	LOD	 Load PDF	
4	22/05/20 14:58	Authorisation to Act	 Load PDF	
5	22/05/20 14:58	Workshop Invoice	 Load PDF	
6	22/05/20 14:58	Rental Rate & Mileage	 Load PDF	
7	01/10/20 15:30	DISCHARGE VOUCHER	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	12/03/20 08:38	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/III20003745/KPA3S2**Date:** 01/10/2020REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SHD514T	Insured Vehicle No :	SHC8943R
Date of Loss:	04/03/2020	Nature of Claim:	TP
		Claim No:	MCT20030075

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD514T		
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C002555
Reg. Date:	08/05/2015 (Man. Year: 2015)	Chassis No:	VF1ABL15AUC281572
Colour:	Metallic White/Red	Odometer:	748901 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 8 mm	Rear Left Side:	Firenza 7 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Firenza 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	66,475.47	19,843.36	46,632.11	70.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	26,390.00	5,060.00	21,330.00	80.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	92,865.47	24,903.36	67,962.11	73.18
Approved Total (Overridden) (\$\$)		12,700.00		
(\$\$)	92,865.47	12,700.00	80,165.47	86.32
+ GST 7.00/7.00% (\$\$)	6,500.58	889.00	5,611.58	86.32
Nett Amount (\$\$)	99,366.05	13,589.00	85,777.05	86.32
+ Loss of Use (21.0 x S\$40.00/day) (\$\$)		840.00		
+ Car Rental (21.0 x S\$96.99/day) (\$\$)		2,036.79		
Nett Liability (\$\$)		16,465.79		
Global Sum Settlement (\$\$)		16,350.00		

INSPECTION

Date of Assignment:	06/03/2020		
Date Inspected:	06/03/2020	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	18.0 days		

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Oct 2020)

Parts: 143 RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD514T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Bent / Cracked	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Cracked	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Cracked	98.10 FL	*98.10 FL
4	1		*BUMPER BRACKET SIDE RH REAR	Distorted	82.10 FL	*82.10 FL
5	1		*BUMPER RETAINER RH REAR	Distorted	59.80 FL	*59.80 FL
6	1		*BUMPER REFLECTOR RH	Cracked	16.60 FL	*16.60 FL
7	1		*BUMPER BRACKET SIDE LH REAR	Distorted	80.80 FL	*80.80 FL
8	1		*BUMPER RETAINER LH REAR	Cracked	54.20 FL	*54.20 FL
9	1		*BUMPER REFLECTOR LH	Broken	16.60 FL	*16.60 FL
10	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Bent	114.50 FL	*114.50 FL
12	1		*BUMPER BEAM BRACKET RH REAR	Bent	100.90 FL	*100.90 FL
13	1		*BUMPER BLOCK LH REAR	No such part	75.70 FL	*- FL
14	1		*BUMPER BLOCK RH REAR	No such part	76.50 FL	*- FL
15	1		*BUMPER HARNESS REAR	Torn	301.10 FL	*301.10 FL
16	1		*BOOT REAR	Bent	1,677.20 FL	*1,677.20 FL
17	1		*BOOT FINISHER	Serviceable	344.70 FL	*- FL
18	1		*BOOT REFLECTOR LAMP LH	Cracked	277.70 FL	*277.70 FL
19	1		*BOOT REFLECTOR LAMP RH	Cracked	277.70 FL	*277.70 FL
20	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	*82.40 FL
21	1		*BOOT BADGE	Necessary	95.80 FL	*95.80 FL
22	1		*BOOT STRUT LH	Serviceable	145.10 FL	*- FL
23	1		*BOOT STRUT RH	Serviceable	145.10 FL	*- FL
24	1		*BOOT HINGE LH	Repair	254.20 FL	*- FL
25	1		*BOOT HINGE RH	Repair	253.80 FL	*- FL
26	1		*BOOT INNER TRIM BOARD	Serviceable	611.00 FL	*- FL
27	1		*BOOT SWITCH	Serviceable	113.00 FL	*- FL
28	1		*BOOT LOCK	Dented	246.60 FL	*246.60 FL
29	1		*BOOT LOCK CATCH	Distorted	41.70 FL	*41.70 FL
30	2		*LICENCE PLATE LAMP	Serviceable	26.30 FL	*- FL
31	2		*BOOT RUBBER PLUG	Serviceable	139.30 FL	*- FL
32	1		*BOOT LOCK LINKAGE	Serviceable	20.60 FL	*- FL
33	1		*BOOT LOCK LINKAGE HOLDER	Serviceable	99.50 FL	*- FL
34	1		*FENDER PANEL REAR LH	Buckled	1,933.20 FL	*1,933.20 FL
35	1		*WHEELARCH REAR LH	Cracked	181.60 FL	*181.60 FL
36	1		*FENDER PANEL INNER TRIM REAR LH	Deformed	671.45 FL	*671.45 FL
37	1		*FENDER PANEL REAR RH	Buckled	1,933.20 FL	*1,933.20 FL
38	1		*WHEELARCH REAR RH	Cracked	275.40 FL	*275.40 FL
39	1		*FENDER PANEL INNER TRIM REAR RH	Deformed	671.45 FL	*671.45 FL
40	1		*AIR VENT	Serviceable	59.40 FL	*- FL
41	1		*TAILLAMP RH	Cracked	401.40 FL	*401.40 FL
42	1		*TAILLAMP PANEL RH	Bent	401.40 FL	*401.40 FL
43	1		*TAILLAMP LH	Cracked	401.40 FL	*401.40 FL
44	1		*TAILLAMP PANEL LH	Bent	401.40 FL	*401.40 FL
45	1		*PARKING COMPUTER	Not Necessary	480.90 FL	*- FL
46	1		*OUTER PANEL REAR (END PANEL)	Bent	745.80 FL	*745.80 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*OUTER PANEL REAR (END PANEL) TRIM	Dented	404.56 FL	*404.56 FL
48	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Bent / Buckled	1,229.40 FL	*1,229.40 FL
49	1		*SPARE WHEEL PANEL TRIM	Deformed	612.21 FL	*612.21 FL
50	1		*SPARE TYRE BOARD	Serviceable	680.90 FL	*- FL
51	1		*SPARE WHEEL PANEL BRACKET LH L70Y	Repair	70.60 FL	*- FL
52	1		*SPARE WHEEL PANEL BRACKET RH L70Y	Repair	69.20 FL	*- FL
53	1		*EXHAUST REAR	Bent	5,263.60 FL	*5,263.60 FL
54	1		*EXHAUST CAP REAR	Dented	125.40 FL	*125.40 FL
55	1		*CHASSIS PANEL REAR LH	Repair	2,192.40 FL	*- FL
56	1		*FENDER PANEL INNER REAR LH L70Y	Repair	1,241.60 FL	*- FL
57	1		*FENDER INNER BOARD LH L70Y	Serviceable	561.40 FL	*- FL
58	1		*FENDER WHEEL HOUSING PANEL REAR LH	Repair	4,682.09 FL	*- FL
59	1		*CHASSIS PANEL REAR RH	Repair	2,192.40 FL	*- FL
60	1		*FENDER PANEL INNER REAR RH L70Y	Repair	952.50 FL	*- FL
61	1		*FENDER INNER BOARD RH L70Y	Repair	561.40 FL	*- FL
62	1		*FENDER WHEEL HOUSING PANEL REAR RH	Repair	4,682.09 FL	*- FL
63	1		*FUEL FLAP	Serviceable	244.70 FL	*- FL
64	1		*FUEL TANK FILLER NECK	Serviceable	473.10 FL	*- FL
65	1		*FUEL TANK CAP	Serviceable	136.90 FL	*- FL
66	1		*FUEL TANK PUMP	Serviceable	1,266.53 FL	*- FL
67	1		*FUEL PIPE SHORT	Serviceable	611.80 FL	*- FL
68	1		*FUEL PIPE LONG	Serviceable	1,148.12 FL	*- FL
69	1		*TUBE FILLER	Serviceable	297.19 FL	*- FL
70	1		*KNUCKLE ARM REAR RH L70Y	Serviceable	472.10 FL	*- FL
71	1		*ABS SENSOR REAR RH L70Y	Serviceable	190.50 FL	*- FL
72	1		*LOWER ARM REAR RH L70Y	Serviceable	543.50 FL	*- FL
73	1		*AXLE SPRING ARM RH	Serviceable	220.60 FL	*- FL
74	1		*ABSORBER REAR RH	Serviceable	217.30 FL	*- FL
75	1		*ABSORBER DUST COVER REAR RH	Serviceable	47.10 FL	*- FL
76	1		*ABSORBER MOUNTING REAR RH	Serviceable	49.40 FL	*- FL
77	1		*KNUCKLE HUB + BEARING RH	Serviceable	272.30 FL	*- FL
78	1		*SUBFRAME ARM REAR RH	Serviceable	198.33 FL	*- FL
79	1		*RODE - LONG REAR RH	Serviceable	120.16 FL	*- FL
80	1		*STABILIZER LINK REAR RH	Serviceable	55.20 FL	*- FL
81	1		*BRAKE CALIPER REAR RH	Serviceable	659.10 FL	*- FL
82	1		*BRAKE CALIPER BRACKET REAR LH/RH	Serviceable	384.00 FL	*- FL
83	1		*STABILIZER BAR REAR	Serviceable	427.90 FL	*- FL
84	1		*REAR AXLE L70Y	Serviceable	3,469.00 FL	*- FL
85	1		*BRAKE DISC REAR L70Y	Serviceable	266.50 FL	*- FL
86	1		*WHEEL HUB NUT L70Y	Serviceable	41.80 FL	*- FL
87	1		*WHEEL HUB CAP L70Y	Serviceable	30.50 FL	*- FL
88	1		*KNUCKLE ARM REAR LH L70Y	Serviceable	472.10 FL	*- FL
89	1		*ABS SENSOR REAR LH L70Y	Serviceable	190.50 FL	*- FL
90	1		*LOWER ARM REAR LH L70Y	Serviceable	543.50 FL	*- FL
91	1		*AXLE SPRING ARM LH	Serviceable	220.60 FL	*- FL
92	1		*ABSORBER REAR LH	Serviceable	217.30 FL	*- FL
93	1		*ABSORBER DUST COVER REAR LH	Serviceable	47.10 FL	*- FL
94	1		*ABSORBER MOUNTING REAR LH	Serviceable	49.40 FL	*- FL
95	1		*KNUCKLE HUB + BEARING LH	Serviceable	272.30 FL	*- FL
96	1		*SUBFRAME ARM REAR LH	Serviceable	198.33 FL	*- FL
97	1		*RODE - LONG REAR LH	Serviceable	120.16 FL	*- FL
98	1		*STABILIZER LINK REAR LH	Serviceable	55.20 FL	*- FL
99	1		*BRAKE CALIPER REAR LH	Serviceable	659.10 FL	*- FL
100	1		*EXTENSION - RR LH SIDE MEMBER	Repair	247.69 FL	*- FL
101	1		*EXTENSION - RR RH SIDE MEMB	Repair	245.79 FL	*- FL
102	1		*DOOR PANEL REAR RH	Repair	758.70 FL	*- FL
103	1		*DOOR LOCK REAR RH L70Y	Repair	467.30 FL	*- FL
104	1		*DOOR FINISHER REAR RH	Serviceable	206.40 FL	*- FL
105	1		*DOOR WEATHERSTRIP REAR RH	Serviceable	311.60 FL	*- FL
106	1		*DOOR SEAL REAR RH L70Y	Serviceable	119.80 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
107	1		*DOOR CATCH REAR RH	Serviceable	73.70 FL	*- FL
108	1		*ROCKER PANEL INNER GARNISH RH	Serviceable	466.51 FL	*- FL
109	1		*ROCKER PANEL INNER RH	Repair	1,024.79 FL	*- FL
110	1		*ROCKER PANEL OUTER RH	Repair	1,184.99 FL	*- FL
111	1		*ROCKER PANEL CENTER RH	Repair	990.25 FL	*- FL
112	1		*ROOF SIDE PANEL OUTER RH	Repair	704.21 FL	*- FL
113	1		*ROOF TOP CHANNEL MOLDING RH	Serviceable	291.27 FL	*- FL
114	1		*ROOF SIDE PANEL OUTER LH	Repair	704.21 FL	*- FL
115	1		*ROOF TOP CHANNEL MOLDING LH	Serviceable	291.27 FL	*- FL
116	1		*DOOR PANEL REAR LH	Repair	758.70 FL	*- FL
117	1		*DOOR LOCK REAR LH L70Y	Repair	468.20 FL	*- FL
118	1		*DOOR CATCH REAR LH	Serviceable	73.70 FL	*- FL
119	1		*DOOR FINISHER REAR LH	Serviceable	230.30 FL	*- FL
120	1		*DOOR WEATHERSTRIP REAR LH L70Y	Serviceable	240.50 FL	*- FL
121	1		*DOOR SEAL REAR LH	Serviceable	119.40 FL	*- FL
122	1		*ROCKER PANEL INNER GARNISH LH	Serviceable	466.51 FL	*- FL
123	1		*ROCKER PANEL INNER LH	Repair	1,024.79 FL	*- FL
124	1		*SET PARKING AID	Torn	700.00 FS	*400.00 FS
125	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
126	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
127	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
128	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
129	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
130	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
131	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
132	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
133	1		*EXHAUST MOUNTING REAR	Serviceable	16.00 FS	*- FS
134	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
135	1		*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
136	1		*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
137	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
138	1		*SET FENDER WHEELARCH REAR RH CLIP	Necessary	35.00 FS	*35.00 FS
139	1		*SET FENDER WHEELARCH REAR LH CLIP	Necessary	35.00 FS	*35.00 FS
140	1		*FENDER INNER TRIM CLIP LH	Necessary	28.00 FS	*28.00 FS
141	1		*FENDER INNER TRIM CLIP RH	Necessary	28.00 FS	*28.00 FS
142	1		*TAILLAMP CLIP RH	Necessary	5.00 FS	*5.00 FS
143	1		*TAILLAMP CLIP LH	Necessary	5.00 FS	*5.00 FS
144	1		*WINDSCREEN MOULDING	Necessary	160.00 FS	*160.00 FS
145	1		*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	100.00 FS	*30.00 FS
146	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
147	1		*SPARE TYRE	Serviceable	330.00 FS	*- FS
148	1		*RIGHT REAR TYRE	Serviceable	330.00 FS	*- FS
149	1		*RIGHT REAR TYRE RIM	Serviceable	380.00 FS	*- FS
150	1		*RIGHT LEFT TYRE	Serviceable	330.00 FS	*- FS
151	1		*RIGHT LEFT TYRE RIM	Serviceable	380.00 FS	*- FS
152	1		*EXHAUST BRACKET REAR	Serviceable	24.80 FS	*- FS
153	1		*REAR RH DOOR STICKER 6555-3333	Not Necessary	100.00 FS	*- FS
154	1		*REAR LH DOOR STICKER 6555-3333	Not Necessary	100.00 FS	*- FS
155	1		*REAR BUMPER PROTECTOR	Serviceable	100.00 FS	*- FS
156	1		*SET REAR LICENCE PLATE WITH HOLDER	Dented	100.00 FS	*45.00 FS
157	2		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
158	1		*BOOT WEATHERSTRIP (@ \$178.50 DISC 50%)	Cut	160.38 FS	*89.10 FS
159	1		*ROCKER PANEL OUTER LH	Repair	1,184.99 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	73,382.92	21,923.17
- List Item Discount on L Items 10.00/10.00% (\$\$)	6,907.45	2,079.81
Total Parts (\$\$)	66,475.47	19,843.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	9,900.00	1,540.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	9,900.00	2,400.00
3	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	New	170.00	80.00
4	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	350.00	120.00
5	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	60.00
6	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	150.00
7	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
9	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }	New	170.00	80.00
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING. }	New	380.00	0.00
11	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	New	170.00	0.00
12	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
13	TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	60.00
14	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
15	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.	New	170.00	120.00
16	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	60.00
17	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	New	380.00	250.00
18	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	New	170.00	0.00
19	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	30.00
20	TOWING FEES.	New	150.00	50.00
21	TO TRANSFER DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	350.00	0.00
22	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	New	380.00	0.00
23	TO DROP DIESEL TANK PIPES, HOSES AND RENEW THE NECESSARY PARTS AND FINAL CHECKING AND TESTING FOR LEAK.	New	440.00	0.00
24	TO DISMANTLE AND REFIT REAR AXLE ASSY, REMOVE AND RENEWAL OF PARTS, FINAL CHECKING AND TESTING.	New	380.00	0.00
25	TO PULL AND JACK OUT CHASSIS FRAME, CAR BODY PILLARS AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	New	380.00	0.00
26	TO CHECK ABS AND BRAKE EFFICIENCY, FINAL CHECKING AND TESTING.	New	380.00	0.00
27	TO DROP DIESEL TANK, PIPES, HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING.	New	380.00	60.00
Gross Labour Cost (\$\$)			26,390.00	5,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >