

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20003750/QBA3Q2

Date: 11/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900010576

Claimant
Vehicle No : SLK8782Z **Insured Vehicle No :** SKS9710U

Date of Loss: 06/03/2020 Nature of Claim: TP Claim No: 9057424782SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK8782Z		
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Engine No:	L15B4406596
Reg. Date:	02/02/2017 (Man. Year: 2016)	Chassis No:	RU11206596
Colour:	Green	Odometer:	0 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,788.00	2,367.60	420.40	15.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	750.00	250.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,788.00	3,117.60	670.40	17.70
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	3,788.00	2,500.00	1,288.00	34.00
+ GST 7.00/7.00% (S\$)	265.16	175.00	90.16	34.00
Nett Amount (S\$)	4,053.16	2,675.00	1,378.16	34.00
+ Loss of Use (5.0 x S\$70.00/day) (S\$)		350.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,027.00		
Global Sum Settlement (S\$)		2,900.00		

INSPECTION

Date of Assignment: 09/03/2020

Date Inspected: 09/03/2020 Inspected At:

Lion City Rentals Pte Ltd (HQ)
60 Jalan Lam Huat, #04-01 Carros
Centre
Singapore 737869

Estimated Period of Repair: 3.0 days

Adjuster: OI SUN PIN**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Crumpled	955.00 FL	*850.00 FL
2	1		*F/L FENDER WHEEL ARCH MOULDING	Scratched	300.00 FL	*192.00 FL
3	1		*F/L HEADLAMPASSY (LED)	Cracked	2,100.00 FL	*1,850.00 FL
4	1		*RETAINER LH	Cracked	30.00 FL	*30.00 FL
5	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,465.00	2,952.00
- List Item Discount on L Items 20.00/20.00% (\$)	677.00	584.40

Total Parts (\$)	2,788.00	2,367.60
-------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO LABOUR CHARGE FOR REMOVING FRONT BUMPER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PART FENDER	New	500.00	350.00
2	TO RESPRAY FRONT BUMPER AND F/L FENDER WHEEL ARC MOULDING	New	500.00	400.00
Gross Labour Cost (\$\$)			1,000.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >