

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG20003762/KPS3Q2  
**Date:** 19/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800053346-01
<b>Claimant Vehicle No :</b>	SHD5145S	<b>Insured Vehicle No :</b>	SKB7802R
Date of Loss:	04/03/2020	Nature of Claim:	TP
		Claim No:	2581255055SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHD5145S</b>		
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Engine No:	2ZR2B81006
Reg. Date:	12/12/2018 (Man. Year: 2018)	Chassis No:	JTDKB3FU403077418
Colour:	Metallic Pearl White/Red	Odometer:	125375 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	18,402.15	4,167.65	14,234.50	77.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,100.00	890.00	14,210.00	94.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>33,502.15</b>	<b>5,057.65</b>	<b>28,444.50</b>	<b>84.90</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,345.15</b>	<b>354.04</b>	<b>1,991.11</b>	<b>84.90</b>

<b>Nett Amount (S\$)</b>	<b>35,847.30</b>	<b>5,411.69</b>	<b>30,435.61</b>	<b>84.90</b>
<b>+ Loss of Use (4.0 x S\$50.00/day) (S\$)</b>		200.00		
<b>+ Car Rental (4.0 x S\$112.35/day) (S\$)</b>		449.40		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>6,068.54</b>		
<b>Global Sum Settlement (S\$)</b>		<b>6,050.00</b>		

INSPECTION

Date of Assignment: 06/03/2020

Date Inspected: 06/03/2020

Estimated Period of Repair: 2.0 days

Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)  
2, Ang Mo Kio Street 63  
Singapore 569111

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Cracked	516.00 FL	*516.00 FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	82.30 FL	*82.30 FL
3	1		*REINFORCEMENT ,FRONT BUMPER	Repair	716.60 FL	*- FL
4	1		*REINFORCEMENT ,FRONT BUMPER ,NO.2	Serviceable	246.10 FL	*- FL
5	1		*ABSORBER ,FRONT BUMPER ,LOWER	Serviceable	132.70 FL	*- FL
6	1		*ABSORBER ,FRONT BUMPER ,ENERGY	Serviceable	79.60 FL	*- FL
7	1		*COVER SUB-ASSY ,ENGINE UNDER ,NO.2	Serviceable	241.90 FL	*- FL
8	1		*COVER ,ENGINE UNDER ,NO.1	Serviceable	472.40 FL	*- FL
9	1		*COVER ,FRONT BUMPER ,HOLE ,LH	Serviceable	29.30 FL	*- FL
10	1		*EXTENSION ,FRONT BUMPER ,LH	Serviceable	120.10 FL	*- FL
11	1		*FRONT LED LAMP (LOWER) LH	Mtg Cracked	951.40 FL	*951.40 FL
12	1		*FRONT HEADLAMP LH	Cracked	2,637.60 FL	*2,637.60 FL
13	1		*COMPUTER SUB-ASSY ,HEADLAMP ,LH NO.1	Serviceable	960.50 FL	*- FL
14	1		*MOTOR ,HEADLAMP LEVELING ,LH	Serviceable	487.50 FL	*- FL
15	1		*FRONT FENDER LH	Buckled	977.80 FL	*977.80 FL
16	1		*LINER ,FRONT FENDER ,LH	Cracked	202.50 FL	*202.50 FL
17	1		*COVER SUB ASSY ,FRONT PILLAR ,UPPER LH	Serviceable	100.40 FL	*- FL
18	1		*FRONT FENDER EMBLEM LH	Necessary	54.60 FL	*54.60 FL
19	1		*PROTECTOR ,FRONT FENDER SIDE PANEL ,LH	Serviceable	93.90 FL	*- FL
20	1		*SEAL ,FENDER APRON MUDGUARD ,LH	Serviceable	51.90 FL	*- FL
21	1		*FRONT BONNET	Repair	983.10 FL	*- FL
22	1		*HINGE ASSY ,HOOD ,LH	Repair	58.90 FL	*- FL
23	1		*LEFT SIDE VIEW MIRROR	Serviceable	1,339.30 FL	*- FL
24	1		*MOULDING ASSY ,BODY ROCKER PANEL ,LH	Repair	594.80 FL	*- FL
25	1		*GRILLE SUB-ASSY ,RADIATOR	Serviceable	346.00 FL	*- FL
26	1		*EMBLEM ASSY ,RADIATOR GRILLE	Serviceable	90.80 FL	*- FL
27	1		*GRILLE ,RADIATOR LOWER NO.1	Serviceable	170.10 FL	*- FL
28	1		*PANEL SUB-ASSY ,FRONT DOOR ,LH	Repair	1,300.70 FL	*- FL
29	1		*TAPE, BLACK OUT ,NO.1 FRT LH	Not Necessary	13.30 FL	*- FL
30	1		*TAPE, BLACK OUT ,NO.2 FRT LH	Serviceable	43.50 FL	*- FL
31	1		*TAPE, BLACK OUT ,NO.3 FRT LH	Serviceable	26.30 FL	*- FL
32	1		*SUPPORT ,RADIATOR ,UPPER LH	Serviceable	78.90 FL	*- FL
33	1		*SUPPORT SUB-ASSY ,RADIATOR ,LH	Serviceable	245.10 FL	*- FL
34	1		*FRONT LH DRIVE SHAFT ASSY	Serviceable	1,251.70 FL	*- FL
35	1		*ARM SUB-ASSY ,FRONT SUSPENSION ,LOWER NO.1 LH	Serviceable	760.10 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*JOINT ASSY ,LOWER BALL ,FRONT LH	Serviceable	238.40 FL	*- FL
37	1		*KNUCKLE ,STEERING LH	Serviceable	663.40 FL	*- FL
38	1		*ABSORBER ASSY ,SHOCK FRONT LH	Serviceable	438.40 FL	*- FL
39	1		*GEAR ASSY ,STEERING	Serviceable	1,955.40 FL	*- FL
40	1		*COVER ,RADIATOR SUPPOT OPENING	Serviceable	235.30 FL	*- FL
41	1		*FRONT WHEEL RIM	Serviceable	1,879.40 FS	*- FS
42	1		*FRONT WHEEL RIM COVER	Serviceable	211.50 FS	*- FS
43	1		*FRONT TYRE 195/65/15	Serviceable	350.00 FS	*- FS
44	1		*SET CLIP ,FRONT FENDER LINER	Necessary	35.00 FS	*35.00 FS
45	1		*FRONT NUMBER PLATE WITH MOULDING	Serviceable	200.00 FS	*- FS
46	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
47	1		*SET FRONT BUMPER RETAINER CLIP	Not Necessary	35.00 FS	*- FS
48	1		*FRONT DOOR STICKER TRANS-CAB	Not Necessary	100.00 FS	*- FS
49	1		*FRONT WINDSCREEN MOULDING	Not Necessary	160.00 FS	*- FS
50	2		*WINDSCREEN SEALANT	Not Necessary	253.80 FS	*- FS
51	1		*FRONT WINDSCREEN INNER SPONGE SEAL	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>23,399.30</b>	<b>5,523.20</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	4,997.15	1,355.55
<b>Total Parts (\$\$)</b>	<b>18,402.15</b>	<b>4,167.65</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	6,000.00	400.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	440.00
3	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR	New	380.00	0.00
4	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
5	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO TRANSFER OF BONNET FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
8	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
9	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
10	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
11	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
12	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
13	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
14	TO DISMANTLE AND REFIT FRONT END SUSPENSION ,UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING	New	380.00	0.00
15	TO CHECK ABS AND BRAKE EFFICIENCY ,FINAL CHECKING AND TESTING	New	380.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>15,100.00</b>	<b>890.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >