

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20003771/APS3N2

Date: 20/07/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMJ6555U	Insured Vehicle No :	SHA3594H
Date of Loss: 01/03/2020	Nature of Claim: TP	Claim No: MCT20030036

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ6555U		
Make & Model:	MERCEDES-BENZ C200, 1.5 AMG (A)	Engine No:	26491530048050
Reg. Date:	18/03/2019 (Man. Year: 2018)	Chassis No:	WDD2054772F806904
Colour:	Red	Odometer:	23875 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,547.71	7,615.79	13,931.92	64.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	830.00	2,220.00	72.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	24,597.71	8,445.79	16,151.92	65.66
Approved Total (Overridden) (\$\$)		6,700.00		
Nett Amount (\$\$)	24,597.71	6,700.00	17,897.71	72.76
+ Car Rental (4.0 x S\$100.00/day) (\$\$)		400.00		
+ Doc/Search Fee (\$\$)		29.00		
Nett Liability (\$\$)		7,129.00		
Global Sum Settlement (\$\$)		7,120.00		

INSPECTION

Date of Assignment:	10/03/2020	
Date Inspected:	10/03/2020 Inspected At:	Cas Garage Pte Ltd (HQ)
		No.1, Kaki Bukit Ave 6, #02-22
		Autobay
		Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jun 2020)
Parts:	143	MERCEDES-BENZ C200 1.5 AMG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ6555U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,820.50 FL	*1,506.00 FL
2	1		*FRONT BUMPER INNER TOP RUBBER	Not Necessary	138.90 FL	*- FL
3	1		*FRONT BUMPER BRACKET	Not Necessary	138.90 FL	*- FL
4	2		*FRONT BUMPER RETAINER	Not Necessary	290.00 FL	*- FL
5	1		*FRONT BUMPER TOWING COVER	Not Necessary	85.80 FL	*- FL
6	1		*FRONT BUMPER LOWER GRILLE	Deformed	289.60 FL	*289.60 FL
7	1		*FRONT BUMPER UNDERCOVER	Not Necessary	325.60 FL	*- FL
8	2		*FRONT FOG LAMP OUTER MOULDING	Not Necessary	251.00 FL	*- FL
9	1		*FRONT GRILLE ASSY	Cracked	1,874.00 FL	*895.00 FL
10	2		*HEADLAMP	N/S Cracked	9,460.00 FL	*3,126.00 FL
11	2		*HEADLAMP BRACKET	Not Necessary	309.60 FL	*- FL
12	1		*HEADLAMP SUPPORT PANEL	Not Necessary	1,180.00 FL	*- FL
13	1		*AIRCON CONDENSOR	Not Necessary	1,382.00 FL	*- FL
14	1		*FRONT OIL COOLER	Bent	546.30 FL	*546.30 FL
15	1		*FRONT RADAR SENSOR	Damaged	1,199.20 FL	*1,199.20 FL
16	1		*RADIATOR	Not Necessary	985.20 FL	*- FL
17	2		*RADIATOR AIR GUIDES	Not Necessary	211.20 FL	*- FL
18	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	378.90 FL	*- FL
19	1		*FRONT BUMPER TOP BEAM	Not Necessary	289.60 FL	*- FL
20	1		*FRONT BUMPER INNER SPONGE	Cracked	165.80 FL	*165.80 FL
21	2		*FRT BUMPER REINFORCEMENT BRACKET	Not Necessary	339.40 FL	*- FL
22	1		*FRONT BUMPER NUMBER PLATE BASE	Deformed	145.20 FL	*145.20 FL
23	4		*FRONT SENSOR HOLDER	Not Necessary	279.60 FL	*- FL
24	4		*FRONT SENSORS	Not Necessary	905.60 FL	*- FL
25	1		*SET FRONT NUMBER PLATE	Cracked	145.00 FS	*100.00 FS
26	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
27	1		*SET FRONT BUMPER UNDERCOVER CLIPS	Not Necessary	30.00 FS	*- FS
28	1		*SET CAR WRAP ON FRT BUMPER AND GRILLE	Necessary	650.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	23,846.90	8,403.10
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,299.19	787.31
Total Parts (\$\$)	21,547.71	7,615.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAFED PARTS ,REPLACE ,BEAT ,WELD REALIGN	New	1,200.00	400.00
2	TO RESPRAY AFFECTED AREAS	New	1,200.00	250.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	0.00
4	TO REMOVE/REFIT WIRING CHECKS ON HEADLAMP	New	120.00	30.00
5	TO DIAGNOSED AND RESET FAULT CODE	New	180.00	100.00
6	TO REMOVE /REPLACE REVERSE SENSOR AND DISTANCE SETTLING	New	150.00	50.00
Gross Labour Cost (\$\$)			3,050.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >