

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20003780/EGA3Q2

**Date:** 11/12/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800063798

**Claimant**  
**Vehicle No :** SLA8988A **Insured Vehicle No :** SLV4283R

Date of Loss: 27/02/2020 Nature of Claim: TP Claim No: 4993537263SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLA8988A</b>		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK085637
Reg. Date:	30/07/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF59KA065119
Colour:	Black	Odometer:	14643 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	14,232.00	9,392.80	4,839.20	34.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,652.00	4,132.00	2,520.00	37.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>20,884.00</b>	<b>13,524.80</b>	<b>7,359.20</b>	<b>35.24</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	1,461.88	946.74	515.14	35.24
<b>Nett Amount (\$\$)</b>	<b>22,345.88</b>	<b>14,471.54</b>	<b>7,874.34</b>	<b>35.24</b>
<b>+ Car Rental (7.0 x S\$150.00/day) (\$\$)</b>		1,050.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>15,523.54</b>		

### INSPECTION

Date of Assignment: 09/03/2020

Date Inspected: 09/03/2020 Inspected At: 281 ALEXANDRA ROAD  
Repairer: Premium Automobiles Pte Ltd (UBI)

Estimated Period of Repair: 6.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	2,142.00 FS	*1,713.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	383.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	Necessary	34.00 FS	*27.20 FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	215.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE - RH	Not Necessary	59.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	446.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	34.00 FS	*- FS
8	1		*FRONT PARKING AID SENSOR - OUTER (NPA)	Not Necessary	0.00 FS	*- FS
9	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
10	1		*FRONT FENDER - RH	Dented	997.00 FS	*797.60 FS
11	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	50.00 FS	*- FS
12	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	70.00 FS	*- FS
13	1		*FRONT FENDER BRACKET - RH	Not Necessary	33.00 FS	*- FS
14	1		*FRONT FENDER BRACE - RH	Not Necessary	112.00 FS	*- FS
15	1		*DEFORMATION ELEMENT BRACKET - RH	Not Necessary	46.00 FS	*- FS
16	1		*WHEEL HOUSING LINER - RH	Not Necessary	259.00 FS	*- FS
17	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	86.00 FS	*- FS
18	1		*WHEEL SPOILER - RH	Cracked	69.00 FS	*55.20 FS
19	1		*WHEEL SPOILER TRIM - RH	Not Necessary	34.00 FS	*- FS
20	1		*STONE CHIP GUARD - RH	Necessary	48.00 FS	*38.40 FS
21	1		*FENDER LEDGE COVER - OUTER	Necessary	34.00 FS	*27.20 FS
22	1		*FENDER LEDGE COVER - RH FRONT	Necessary	15.00 FS	*12.00 FS
23	1		*LED HEADLIGHT - RH	Cut	7,438.00 FS	*5,950.40 FS
24	1		*LIFT CYLINDER - RH	Not Necessary	187.00 FS	*- FS
25	1		*FRONT ALUMINIUM RIM - RH	Cut	964.00 FS	*771.20 FS
26	4		*ALUMINIUM RIM RUBBER VALVE	Not Necessary	13.00 FS	*- FS
27	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
28	1		*FRONT FENDER CHROME TRIM RHS	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 14,232.00 9,392.80**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,500.00	1,650.00
4	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR COVER	New	400.00	280.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,652.00</b>	<b>4,132.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >