

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20003791/AEA3Q2**Date:** 23/06/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2000000402
Claimant
Vehicle No : SMC694C **Insured Vehicle No :** SMR6801S
Date of Loss: 07/03/2020 Nature of Claim: TP Claim No: 4422243557SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMC694C**
Make & Model: HONDA FIT, 1.3 GF CVT (A) Engine No: L13B1423452
Reg. Date: 26/06/2018 (Man. Year: 2018) Chassis No: GK31320040
Colour: Blue Odometer: 25796 km
Engine Capacity: 1317 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,560.98	4,737.20	5,823.78	55.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,090.00	2,270.00	1,820.00	44.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,650.98	7,007.20	7,643.78	52.17
+ GST 7.00/7.00% (S\$)	1,025.57	490.50	535.07	52.17
Nett Amount (S\$)	15,676.55	7,497.70	8,178.85	52.17
+ Car Rental (10.0 x S\$100.00/day + 7.00% GST) (S\$)		1,070.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,569.70		

INSPECTION

Date of Assignment: 09/03/2020
Date Inspected: 09/03/2020 Inspected At: SK Automobile Pte Ltd (HQ)
23 Kaki Bukit Avenue 4, #03-01 Vicom
Inspection Centre
Singapore 415933
Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Distorted	998.00 FL	*814.00 FL
2	1		*TAIL GATE STOPPER	Not Necessary	28.50 FL	*- FL
3	1		*TAIL GATE INNER LOCK	Damaged	289.00 FL	*198.00 FL
4	1		*TAIL GATE WIPER MOTOR	Not Necessary	589.00 FL	*- FL
5	2		*TAIL GATE ABSORBER	Not Necessary	272.40 FL	*- FL
6	2		*TAIL GATE HINGE	Not Necessary	62.00 FL	*- FL
7	1		*TAIL GATE DETECTOR	Cracked	154.00 FL	*85.00 FL
8	1		*TAIL GATE WEATHERSTRIP	Cut	154.00 FL	*154.00 FL
9	1		*TAIL GATE INNER TRIM	Cracked	258.00 FL	*258.00 FL
10	1		*TAIL GATE WINDSCREEN MOULDING	Necessary	110.00 FL	*110.00 FL
11	1		*TAIL GATE OUTER GARNISH	Not Necessary	184.00 FL	*- FL
12	1		*TAIL GATE OUTER GARNISH LOGO	Not Necessary	58.00 FL	*- FL
13	2		*TAIL GATE REFLECTOR	Not Necessary	622.00 FL	*- FL
14	1		*TAIL GATE EMBLEM FIT	Necessary	35.00 FL	*35.00 FL
15	1		*REAR BUMPER	Distorted	659.00 FL	*545.00 FL
16	2		*REAR BUMPER SIDE GARNISH	Cracked	242.00 FL	*242.00 FL
17	1		*REAR BUMPER CENTER GARNISH	Cracked	124.00 FL	*124.00 FL
18	2		*REAR BUMPER SIDE RETAINER	Necessary	90.00 FL	*90.00 FL
19	2		*TAIL LAMP	Cracked	978.00 FL	*610.00 FL
20	1		*REVERSE SIREN	Cracked	121.00 FL	*65.00 FL
21	2		*REAR FENDER INNER TRIM (LOWER)	Cracked	778.00 FL	*778.00 FL
22	2		*REAR FENDER INNER SHIELD	Not Necessary	179.20 FL	*- FL
23	1		*REAR END PANEL	Distorted	542.00 FL	*542.00 FL
24	1		*REAR FLOOR PANEL	Repair	985.00 FL	*- FL
25	1		*REAR FLOOR TOP BOARD	Deformed	415.00 FL	*298.00 FL
26	1		*REAR END PANEL TOP GARNISH	Cracked	101.00 FL	*101.00 FL
27	1		*REAR TOOLS TOOLS BOX COVER	Not Necessary	220.00 FL	*- FL
28	1		*REAR TOOLS TOOLS BOX COMPARTMENT	Cracked	421.00 FL	*285.00 FL
29	1		*REAR EXHAUST TAIL PIPE	Not Necessary	898.00 FL	*- FL
30	2		*REAR EXHAUST MOUNTING	Not Necessary	76.00 FL	*- FL
31	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
32	10		*REAR BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
33	4		*TAIL LAMP CLIP	Necessary	34.00 FS	*20.00 FS
34	2		*TAIL LAMP INNER PANEL SEALANT	Not Necessary	160.00 FS	*- FS
35	2		*TAIL LAMP PANEL SEALANT	Not Necessary	160.00 FS	*- FS
36	1		*TAIL GATE SEALANT	Not Necessary	80.00 FS	*- FS
37	12		*TAIL GATE INNER TRIM CLIP	Necessary	78.00 FS	*30.00 FS
38	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
39	1		*TAIL GATE WINDSCREEN INNER SEAL	Necessary	80.00 FS	*40.00 FS
40	2		*REAR FENDER SEALANT	Not Necessary	160.00 FS	*- FS
41	12		*REAR FENDER INNER SHIELD CLIP	Not Necessary	78.00 FS	*- FS
42	12		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	78.00 FS	*- FS
43	1		*REAR FENDER INNER TRIM CLIPS (19 PCS)	Necessary	123.50 FS	*50.00 FS
44	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
45	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
46	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,689.60	5,804.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,128.62	1,066.80
Total Parts (\$\$)	10,560.98	4,737.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPACING PARTS	New	1,500.00	1,000.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,300.00	800.00
3	TUFF COAT	New	180.00	60.00
4	WIRING CHECK	New	60.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	300.00	80.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	250.00	50.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	200.00	50.00
8	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
9	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
10	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
Gross Labour Cost (\$\$)			4,090.00	2,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >