

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20003796/ABA3Q2

Date: 03/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900161422

Claimant
Vehicle No : SLF2990E **Insured Vehicle No :** SMP1810J

Date of Loss: 08/03/2020 Nature of Claim: TP Claim No: 4752753584SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF2990E		
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Engine No:	L15B4037701
Reg. Date:	22/08/2016 (Man. Year: 2016)	Chassis No:	RU11117696
Colour:	White	Odometer:	72707 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	OTANI 6 mm	Rear Left Side:	OTANI 6 mm
Front Right Side:	OTANI 6 mm	Rear Right Side:	OTANI 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,813.70	4,361.92	5,451.78	55.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,180.00	1,130.00	1,050.00	48.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,993.70	5,491.92	6,501.78	54.21
Approved Total (Overridden) (S\$)		4,400.00		
(S\$)	11,993.70	4,400.00	7,593.70	63.31
+ GST 7.00/7.00% (S\$)	839.56	308.00	531.56	63.31
Nett Amount (S\$)	12,833.26	4,708.00	8,125.26	63.31
+ Car Rental (3.0 x S\$120.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,070.00		
Global Sum Settlement (S\$)		5,050.00		

INSPECTION

Date of Assignment: 09/03/2020

Date Inspected: 09/03/2020 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
1 Kaki Bukit Ave 6, Blk C #01-43
Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT R/H HEAD LAMP	Cut	1,820.90 F	*1,820.90 FL
2	1		*FRONT HEAD LAMP LOWER BRACKET	Cracked	45.00 F	*45.00 FL
3	1		*FRONT BUMPER	Deformed	495.80 F	*495.80 FL
4	1		*FRONT BUMPER LOWER LID	Cut	351.00 F	*351.00 FL
5	10		*FRONT BUMPER CLIP	Necessary	65.00 F	*30.00 FL
6	1		*FRONT R/H BUMPER SIDE RETAINER	Necessary	27.10 F	*27.10 FL
7	1		*FRONT R/H BUMPER FOG LAMP	Not Necessary	327.70 F	*- FL
8	1		*FRONT R/H BUMPER FOG LAMP COVER	Not Necessary	45.00 F	*- FL
9	1		*FRONT R/H FENDER	Dented	582.00 F	*582.00 FL
10	1		*FRONT R/H FENDER COWLING	Torn	130.00 F	*130.00 FL
11	6		*FRONT R/H FENDER COWLING CLIP	Necessary	39.00 F	*30.00 FL
12	1		*FRONT R/H PROTECTOR	Deformed	166.00 F	*166.00 FL
13	8		*FRONT R/H PROTECTOR CLIP	Necessary	52.00 F	*20.00 FL
14	1		*FRONT R/H RIM	Cut	758.60 FS	*480.00 FS
15	1		*FRONT R/H TYRE	Not Necessary	380.00 F	*- FL
16	1		*REAR R/H LOWER ARM	Bent	351.00 F	*351.00 FL
17	1		*REAR R/H KNUCKLE ARM	Damaged	238.00 F	*238.00 FL
18	1		*REAR R/H KNUCKLE ARM BEARING	Necessary	135.50 F	*135.50 FL
19	1		*FRONT R/H SHOCK ABSORBER	Bent	430.10 F	*430.10 FL
20	1		*FRONT R/H DRIVE SHAFT	Not Necessary	1,103.40 F	*- FL
21	1		*FRONT STEERING RACK	Not Necessary	2,270.60 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,813.70	5,332.40
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	970.48
Total Parts (\$\$)	9,813.70	4,361.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT FRONT UNDERCARRIAGE ,DRIVE SHAFT & STEERING RACK	New	380.00	220.00
2	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
3	TO CHECK WIRING	New	100.00	30.00
4	TUFF KOTE	New	150.00	0.00
5	PANEL BEATING	New	800.00	400.00
6	SPRAY PAINTING	New	600.00	400.00
Gross Labour Cost (\$\$)			2,180.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >