



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

QBE INSURANCE (SINGAPORE) PTE LTD
1 RAFFLES QUAY #29-10 SOUTH TOWER
SINGAPORE 048583

INV No. AC2006524
INV Date 22/09/2020
Reference CC6/QBE20003811/Aba3q2
Code QBE



PROFESSIONAL SERVICE FEE

Vehicle No. SKH 9110J
Insured Veh. GBA 7457R
Claim No. VC013508
Policy No. 8-V0014342-MVA-R003
Accident Date 21/02/2020
Inspection Date 02/03/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CC6/QBE20003811/Aba3q2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 22-09-2020



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 7457R	Veh. Inspected	SKH 9110J
Policy No.	8-V0014342-MVA-R003	Coverage (\$)	0.00
Claim No.	VC013508	Excess (\$)	0.00
Assign From		Assign Date	02/03/2020

2. Vehicle Particulars & Condition

Make & Model	KIA CERATO FORTE	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	KNAFU411LA5202644	Colour	WHITE
Odometer	171115	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	MICHELIN	6 mm
L/H Front Tyre	195/65 R15	MICHELIN	6 mm
R/H Rear Tyre	195/65 R15	MICHELIN	6 mm
L/H Rear Tyre	195/65 R15	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/02/2020	Inspection Date	02/03/2020
Survey held at	SW WERKZ PTE LTD BLK 25 KAKI BUKIT ROAD 4 #03-67/68 SYNERGY @ KB SINGAPORE 417800		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKH 9110J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BONNET	DENTED	752.00	752.00
2	FRONT BONNET HINGES (NPA)	NOT NECESSARY	-	-
1	FRONT BONNET LOCK	NOT NECESSARY	112.00	-
1	FRONT GRILLE	CUT	207.00	207.00
1	FRONT GRILLE EMBLE LOGO	NECESSARY	35.00	35.00
8	FRONT GRILLE CLIPS @\$6.50	NECESSARY	52.00	20.00
2	FRONT SUPPORT PANEL @\$495.00	NOT NECESSARY	990.00	-
1	FRONT HEADLAMP	CRACKED	454.80	454.80
1	FRONT HEADLAMP LOWER BRACKET	NOT NECESSARY	38.10	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	575.00	-
2	FRONT BUMPER SIDE BRACKET @\$58.20	NOT NECESSARY	116.40	-
10	FRONT BUMPER CLIPS @\$6.50	NOT NECESSARY	65.00	-
2	FRONT BUMPER FOG LAMP @\$165.20	NOT NECESSARY	330.40	-
2	FRONT BUMPER FOG LAMP COVER @\$86.20	NOT NECESSARY	172.40	-
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	205.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	373.00	-
1	FRONT BUMPER INNER SPONGE	NOT NECESSARY	125.30	-
	LESS 10% DISCOUNT		-	-146.88
			4,603.40	1,321.92
<u>LABOUR</u>				
	TO REMOVE & REFIX FRONT WINDSCREEN.	NOT NECESSARY	120.00	-
	GUM.	NOT NECESSARY	50.00	-
	TUFF KOTE.	NOT NECESSARY	120.00	-
	TO CHECK WIRING SYSTEM.		60.00	30.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BUMPER .		600.00	400.00
	SPRAY PAINTING.		600.00	400.00
			1,550.00	830.00
GRAND TOTAL			6,153.40	2,151.92



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,700.00
---	--	--	----------

Report Ref No. CC6/QBE20003811/Aba3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKH 9110J

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKH 9110J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

