

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20003813/UGS3Q2

Date: 09/07/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMJ2091S	Insured Vehicle No :	SHA3351S
Date of Loss: 03/03/2020	Nature of Claim: TP	Claim No: MCT20030055

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ2091S		
Make & Model:	MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A)	Engine No:	27491030359249
Reg. Date:	28/04/2015 (Man. Year: 2015)	Chassis No:	WDD2050402R057045
Colour:	Brown	Odometer:	27847 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,582.80	7,951.92	2,630.88	24.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,680.00	1,650.00	1,030.00	38.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,262.80	9,601.92	3,660.88	27.60
Approved Total (Overridden) (S\$)		7,650.00		
Nett Amount (S\$)	13,262.80	7,650.00	5,612.80	42.32
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
Nett Liability (S\$)		7,950.00		

INSPECTION

Date of Assignment:	10/03/2020	
Date Inspected:	10/03/2020 Inspected At:	Soc Leon Motor Works (Kaki Bukit) 1 Kaki Bukit Ave 6, #01-91, AutoBay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2020)
Parts:	143	MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ2091S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID LOGO	Necessary	65.00 FL	*65.00 FL
2	1		*C180 EMBLEM	Necessary	102.00 FL	*98.00 FL
3	1		*REAR BUMPER	Dented / Deformed	2,140.00 FL	*1,790.00 FL
4	2		*REAR BUMPER SIDE RETAINER	Not Necessary	150.00 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Dented / Bent	820.00 FL	*684.00 FL
6	1		*REAR BUMPER LOWER GARNISH	Torn	270.00 FL	*270.00 FL
7	1		*BUMPER CHROME CENTRE	Cracked	310.00 FL	*292.00 FL
8	4		*BUMPER CHROME REVERSE SENSOR	Shorted (2 PCS ONLY)	864.00 FL	*432.00 FL
9	1		*BUMPER CENTRE SENSOR SEAL	Necessary	25.00 FL	*25.00 FL
10	1		*TAILLAMP	Not Necessary	908.00 FL	*- FL
11	1		*HEADLAMP (RH)	Holder Cracked	2,980.00 FL	*2,980.00 FL
12	1		*FRONT BUMPER	Dented / Deformed	1,880.00 FL	*1,600.02 FL
13	1		*RADIATOR GRILLE	Cracked	165.00 FL	*165.00 FL
14	1		*RADIATOR CARRIER	Not Necessary	190.00 FL	*- FL
15	1		*LOGO	Cracked	160.00 FL	*160.00 FL
16	1		*LOGO INNER BASE	Cracked	95.00 FL	*95.00 FL
17	4		*RADIATOR CENTRE MOULDING	Not Necessary	408.00 FL	*- FL
18	1		*NO PLATE GARNISH	Deformed	160.00 FL	*135.00 FL
19	1		*SET NO PLATE & HOUSING FRT	Bent	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,752.00	8,831.02
- List Item Discount on L Items 10.00/10.00% (S\$)	1,169.20	879.10
Total Parts (S\$)	10,582.80	7,951.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & FIX REVERSE SENSOR	New	80.00	50.00
2	TO SPRAY ANTI-RUST	New	100.00	0.00
3	LABOUR CHARGES FOR KNOCKING & REPLACING PARTS	New	1,300.00	700.00
4	SPRAYPAINTING	New	1,200.00	900.00
Gross Labour Cost (\$\$)			2,680.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >