



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2006125  
INV Date 07/09/2020  
Reference CC4/LPC20003814/Eka3n2  
Code LPC2



### PROFESSIONAL SERVICE FEE

Vehicle No. SLS 566S  
Insured Veh. GBB 7417B  
Claim No. 19/20/20/VC00/023166  
Policy No. Z/19/VC00/105743  
Accident Date 05/03/2020  
Inspection Date 16/03/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC20003814/Eka3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 07-09-2020		
		Code : LPC2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBB 7417B	Veh. Inspected	SLS 566S	
Policy No.	Z/19/VC00/105743	Coverage (\$)	0.00	
Claim No.	19/20/20/VC00/023166	Excess (\$)	0.00	
Assign From	KENNY	Assign Date	09/03/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	B.M.W. M240I	c.c	2998	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	WBA2J520407E04071	Colour	ORANGE	
Odometer	6012	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	BRIDGESTONE	5 mm	
L/H Front Tyre	225/40 R18	BRIDGESTONE	5 mm	
R/H Rear Tyre	225/40 R18	BRIDGESTONE	5 mm	
L/H Rear Tyre	225/40 R18	BRIDGESTONE	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	05/03/2020	Inspection Date	16/03/2020	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 566S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT EMOSS NUMBER PLATE (SN)	BENT	83.00	83.00
1	SUNDRIES (SN)	NECESSARY	150.00	80.00
1	BONNET (SN)	DENTED	1,178.70	1,178.70
1	FRT BUMPER TOP MOUNT (SN)	NOT NECESSARY	380.00	-
1	FRT SHOCK ABSORBER (M) (SN)	BROKEN	46.95	46.95
1	FRT BUMPER PANEL PRIMED (M/PDC) (SN)	DENTED	1,118.50	1,118.50
1	LICENCE PLATE BASE (M) (SN)	CUT	83.50	83.50
1	FRT LH GRILLE (CERUM GREY) (SN)	CUT	281.50	281.50
1	GRILLE, FRON (RH)	CUT	281.50	281.50
1	AIR DUCT RADIATOR (SN)	BROKEN	105.35	105.35
1	PLAQUE 82MM (SN)	NECESSARY	71.60	71.60
1	FRONT PANEL V STRU (SN) (ADDITIONAL)	BENT	112.75	112.75
1	FRONT CROSSLINK (SN) (ADDITIONAL)	BENT	169.10	169.10
2	BLIND RIVET @\$1.35 (SN) (ADDITIONAL)	NECESSARY	2.70	2.70
1	FRT END SUPPORT (SN) (ADDITIONAL)	BENT	16.45	16.45
			4,081.60	3,631.60
<b><u>LABOUR</u></b>				
TO REPLACE FRONT BUMPER, AIR DUCT, BUMPER SUPPORT, BONNET AND ATTACHMENTS.			4,250.00	1,700.00
PAINTING FRONT BUMPER AND BONNET.			2,336.00	2,102.00
TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS.			177.00	150.00
TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.			177.00	150.00
TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)			118.00	100.00
XPEL FILM COATING FOR BUMPER AND BONNET.			1,700.00	1,700.00
			8,758.00	5,902.00
<b>GRAND TOTAL</b>			<b>12,839.60</b>	<b>9,533.60</b>



<b>RECOMMENDED COST OF REPAIRS</b>			<b>9,533.60</b>
------------------------------------	--	--	-----------------

Report Ref No. CC4/LPC20003814/Eka3n2

**CHEN TSUE YEE**

**Automotive Assessor**

**HO LEONG CHUAN**

**Automotive Assessor**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.