

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20003815/APA3Q2

**Date:** 31/08/2020

#### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SMD7674J	<b>Insured Vehicle No :</b>	SHC3715R
Date of Loss: 09/03/2020	Nature of Claim: TP	Claim No: MCT20030130

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD7674J		
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Engine No:	G4FGJU246293
Reg. Date:	03/09/2018 (Man. Year: 2018)	Chassis No:	KMHD841CMJU736976
Colour:	Blue	Odometer:	25896 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,405.90	4,435.78	2,970.12	40.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	1,930.00	970.00	33.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,305.90</b>	<b>6,365.78</b>	<b>3,940.12</b>	<b>38.23</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,305.90</b>	<b>5,100.00</b>	<b>5,205.90</b>	<b>50.51</b>
<b>+ Car Rental (8.0 x S\$100.00/day) (S\$)</b>		800.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>5,907.45</b>		

#### INSPECTION

Date of Assignment:	10/03/2020	
Date Inspected:	10/03/2020 Inspected At:	Fong Motors (HQ) 1 Kaki Bukit Ave 6 #01-45, Autobay@ Kaki Bukit Singapore 417883
Estimated Period of Repair:	6.0 days	

**Adjuster:** ADRIAN LING

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 08 Jul 2020)
<b>Parts:</b> 143	HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMD7674J)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	695.80 F	*695.80 FL
2	1		*REAR BUMPER SIDE RETAINER LH/RH	O/S Damaged	85.00 F	*42.50 FL
3	1		*REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
4	1		*EMBLEM ELANTRA	Not Necessary	46.80 F	*- FL
5	1		*HYUNDAI PLATE	Not Necessary	44.50 F	*- FL
6	1		*EMBLEM S	Not Necessary	38.50 F	*- FL
7	1		*REAR TAILGATE	Not Necessary	1,482.50 F	*- FL
8	1		*RH REAR FENDER	Dented	1,768.30 F	*1,768.30 FL
9	1		*RH REAR FENDER UNDERGARNISH FRONT	Not Necessary	88.50 F	*- FL
10	1		*RH REAR FENDER UNDERGARNISH REAR	Torn	46.50 F	*46.50 FL
11	1		*RH REAR ABSORBER	Bent	485.00 F	*485.00 FL
12	1		*RH REAR BEARING	Damaged	268.50 F	*268.50 FL
13	1		*REAR AXLE	Bent	1,388.70 F	*1,388.70 FL
14	1		*REAR RIM	Cut	730.00 FS	*500.00 FS
15	1		*RIM EMBLEM	Cut	38.80 F	*38.80 FL
16	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	108.50 FS	*108.50 FS
17	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>7,405.90</b>	<b>5,382.60</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$)</b>	0.00	946.82
<b>Total Parts (\$)</b>	<b>7,405.90</b>	<b>4,435.78</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	TO KNOCK AND CHANGE PARTS	New	1,200.00	800.00
3	TO SPRAY PAINT THE AFFECTED AREAS	New	950.00	600.00
4	TUFF KOTE	New	120.00	50.00
5	TO CHECK WIRING	New	80.00	30.00
6	COMPUTERSE WHEEL ALIGNMENT	New	180.00	80.00
7	TO REMOVE AND REPLACE REAR AXLE AND PARTS	New	250.00	250.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,900.00</b>	<b>1,930.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >