Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20003818/BES3Q2

Date: 13/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. 1900090783 Policy No: Claimant SMF539C Insured Vehicle No: SGH8080R Vehicle No:

Date of Loss: 03/03/2020 ΤP Nature of Claim: Claim No: 5637653718SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMF539C Reg No:

TOYOTA LEXUS, 2.5 ES250 4DR SEDAN (AUTO) Engine No: Make & Model: A25A0215126

LUXURY (A)

JTHB11B1302001325 Reg. Date: 26/10/2018 (Man. Year: 2018) Chassis No:

Colour: White Odometer: 18724 km

Engine Capacity: 2487 cc Market Value/New Car N/A

Price:

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45 R18 Rear Tyre Size: 235/45 R18 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm Front Right Side: Rear Right Side: Dunlop 6 mm Dunlop 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|--------------------|------------|------------|--------|
| Parts | 7,219.83 | 3,861.53 | 3,358.30 | 46.51 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,030.00 | 970.00 | 1,060.00 | 52.22 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 9,249.83 | 4,831.53 | 4,418.30 | 47.77 |
| Approved Total (Overridden) (S\$) | | 3,850.00 | | |
| (S\$) | 9,249.83 | 3,850.00 | 5,399.83 | 58.38 |
| + GST 7.00/7.00% (S\$) | 647.49 | 269.50 | 377.99 | 58.38 |
| Nett Amount (S\$) | 9,897.32 | 4,119.50 | 5,777.82 | 58.38 |
| + Loss of Use (6.0 x S\$100.00/day) (S\$) + Doc/Search Fee (S\$) | | 600.00 | | |
| | | 22.45 | | |
| Ne | tt Liability (S\$) | 4,741.95 | | |

INSPECTION

Date of Assignment: 10/03/2020

160 SIN MING DR #01-14 SIN MING Date Inspected: 13/03/2020 Inspected At:

Repairer: Team Autopro Pte Ltd - Sin

Ming (HQ)

Estimated Period of Repair: 3.0 days Adjuster Report Page 2 of 4

Adjuster: Lim Teow Guan Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No | . Particulars | Condition | Repairer's | Amount | |
|--|---|------------|---|------------------|-------------|--------------|--|
| 1 | 1 | | *HEADLAMP RH | Cut | 3,702.20 FL | *2,550.00 FL | |
| 2 | 1 | | *HEADLAMP LOWER BRACKET RH | No such part | 230.00 FL | *-FL | |
| 3 | 1 | | *FRONT BUMPER | Cut | 1,046.20 FL | *847.30 FL | |
| 4 | 2 | | *FRONT BUMPER RETAINER | Necessary | 172.60 FL | *127.26 FL | |
| 5 | 1 | | *FRONT BUMPER SIDE GARNISH RH | Cut | 222.70 FL | *222.70 FL | |
| 6 | 1 | | *FRONT BUMPER FOG SIDE CHROME MOULDING RH | l Cut | 210.00 FL | *210.00 FL | |
| 7 | 1 | | *FRONT BUMPER SENSOR RH | Dislodged | 488.00 FL | *300.00 FL | |
| 8 | 1 | | *FRONT FENDER RH | Not Damaged | 1,617.00 FL | *-FL | |
| 9 | 1 | | *SUNDRIES | Not Necessary | 80.00 FS | *-FS | |
| 10 | 1 | | *FRONT BUMPER CLIPS | Necessary | 60.00 FS | *30.00 FS | |
| 11 | 1 | | *FRONT FENDER SEALANT | Not Necessary | 100.00 FS | *-FS | |
| 12 | 1 | | *FRONT FENDER INNER SHIELD CLIPS | Not Necessary | 60.00 FS | *-FS | |
| F=Fra | nchise | part. S=Sp | cNett. L=ListItemDisc. | | • | | |
| | | | | Sub Total (S\$) | 7,988.70 | 4,287.26 | |
| - List Item Discount on L Items 10.00/10.00% (S\$) | | | | 768.87 | 425.73 | | |
| | | | ٦ | otal Parts (S\$) | 7,219.83 | 3,861.53 | |
| | Report was unsubmitted during this print-out. | | | | | | |

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount | | | | |
|-----|-------------------------------------|----------|------------|--------|--|--|--|--|
| Lab | <u>Labour Items</u> | | | | | | | |
| 1 | PANEL BEATING | New | 800.00 | 400.00 | | | | |
| 2 | SPRAY PAINTING | New | 800.00 | 400.00 | | | | |
| 3 | R&R FRONT BUMPER SENSOR | New | 150.00 | 60.00 | | | | |
| 4 | CHECK WIRING | New | 80.00 | 30.00 | | | | |
| 5 | TO RESET AND REPROGRAMME FAULT CODE | New | 200.00 | 80.00 | | | | |
| | Gross Labour Cost (S\$) | | 2,030.00 | 970.00 | | | | |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >