

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20003825/ABS3Q2

Date: 06/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070029112

Claimant
Vehicle No : SLF1819A **Insured Vehicle No :** SMS4063M

Date of Loss: 03/03/2020 Nature of Claim: TP Claim No: 7544451555SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF1819A**

Make & Model: MITSUBISHI ASX 2.0 6-CVT, 2.0 ABS D/AIRBAG SR 2WD (M) Engine No: 4B11RS8564

Reg. Date: 17/08/2016 (Man. Year: 2016) Chassis No: JMFXTGA2WFZC19621

Colour: White Odometer: 79346 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18

Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,255.27	1,255.27	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	440.00	760.00	63.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,455.27	1,695.27	760.00	30.95
+ GST 7.00/7.00% (S\$)	171.87	118.67	53.20	30.95
Nett Amount (S\$)	2,627.14	1,813.94	813.20	30.95
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,121.39		

INSPECTION

Date of Assignment: 11/03/2020

Date Inspected: 11/03/2020 Inspected At: Mg Solution Pte Ltd - Kaki Bukit (HQ)
25 Kaki Bukit Road 4 #04-01
Singapore 41800

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,150.30 FL	*1,150.30 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
3	1		*REVERSE SENSOR	Damaged	200.00 FS	*200.00 FS
					Sub Total (\$)	1,370.30
					- List Item Discount on L Items 10.00/10.00% (\$)	115.03
					Total Parts (\$)	1,255.27

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	400.00	200.00
2	TO SPRAY PAINT ON AFFECTED AREA	New	400.00	200.00
3	TUFF COAT	New	150.00	0.00
4	WIRING CHECK	New	150.00	0.00
5	TO REMOVE AND REFIX REVERSE SENSOR AND SETTING	New	100.00	40.00
Gross Labour Cost (\$\$)			1,200.00	440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >