



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. F 4281Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT HEADLAMP	CRACKED	700.00	285.00
1	HEADLAMP BRACKET	BENT	250.00	160.00
1	FRONT SIGNAL LAMP RH	CRACKED	155.00	45.00
1	FRONT SIGNAL LAMP LH	CRACKED	155.00	45.00
1	FRONT FENDER	DENTED	250.00	120.00
1	CLUTCH LEVER	NOT NECESSARY	180.00	-
1	BRAKE LEVER	DENTED	180.00	180.00
1	BALANCER	NOT NECESSARY	120.00	-
1	RH FOOTREST	BENT	150.00	150.00
1	RH FOOTREST BRACKET	NOT NECESSARY	170.00	-
1	WING MIRROR	BENT	210.00	160.00
1	BRAKE FLUID PUMP	NOT NECESSARY	210.00	-
1	BRAKE CABLE	DISTORTED	115.00	115.00
1	CLUTCH CABLE	NOT NECESSARY	115.00	-
1	METER ASSY	CRACKED	700.00	390.00
1	FUEL TANK	DENTED	900.00	400.00
1	FUEL TANK LOGO YAMAHA	MISSING	55.00	55.00
1	HANDLE BAR	BENT	450.00	250.00
1	HANDLE BAR GRIP	TORN	155.00	120.00
1	FRONT LH FORK ASSY	TO REPAIR SEE LABOUR	550.00	-
1	FRONT RH FORK ASSY	TO REPAIR SEE LABOUR	550.00	-
1	STEERING HEADCROWN	NOT NECESSARY	145.00	-
1	STEERING STEM UNDERBRACKET	NOT NECESSARY	80.00	-
1	STEERING STEM BEARING	NOT NECESSARY	120.00	-
1	REAR EXHAUST	DENTED	650.00	450.00
1	REAR RH SIGNAL LAMP	CRACKED	55.00	55.00
1	RH FOOTREST	DENTED	150.00	150.00
1	RH FOOTREST BRACKET	NOT NECESSARY	170.00	-

Report Ref No. CS/SMO20003831/T1tf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-769.00	-313.00
			6,921.00	2,817.00
	<u>SPECIAL NETT ITEMS</u>			
1	GEAR SHIFT SHAFT OIL SEAL (SN)	NOT NECESSARY	24.00	-
1	FORK OIL SEAL (SN)	NECESSARY	120.00	120.00
1	FORK OIL (SN)	NECESSARY	60.00	60.00
1	REAR BOX (SN)	CUT	550.00	200.00
			754.00	380.00
	<u>LABOUR</u>			
	REPLACE, REALIGN AND ADJUST ABOVE DAMAGE AND CHECK WIRING AND LIGHTNING SYSTEM. INCLUSIVE OF THE REPAIR OF FRONT LH FORK ASSY AND FRONT RH FORK ASSY.		600.00	300.00
	TO KNOCK, STRAIGHTEN CHASSIS AND BODY BAI.	NOT NECESSARY	380.00	-
	TO REMOVE / REFIT, REPLACE FRONT FORK TUDES.		180.00	120.00
	SPRAY PAINTING.		380.00	200.00
			1,540.00	620.00
GRAND TOTAL			9,215.00	3,817.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CS/SMO20003831/T1tf3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.