

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE

SINGAPORE 068877

INV No. AC2006114

INV Date 07/09/2020

Reference CC3/FCI20003862/Kba3q2

Code FCI2

## **PROFESSIONAL SERVICE FEE**

Vehicle No. SHD 9281E

Insured Veh. SHC 3590H

Claim No. D20/1405/CTPL/MC

Policy No. D-18088936MFSH

Accident Date 09/03/2020

Inspection Date 10/03/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 

LAM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile				
MS F	IRST CAPITAL INSURANCE LTD Ref: CC3/FCl20003862/Kba3q2				
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 07-09-2020 Code: FCI2			
1.		Policy Particulars :	- THIRD PARTY CLAIM		
	Insured Veh.	SHC 3590H	Veh. Inspected	SHD 9281E	
	Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
	Claim No.	D20/1405/CTPL/MC	Excess (\$)	0.00	
	Assign From	VIC	Assign Date	10/03/2020	
2.	•	Vehicle Partic	culars & Condition		
	Make & Model	TOYOTA PRIUS (A)	c.c	1798	
	Engine No.	HIDDEN	Year of Reg. 2019		
	Chassis No.	JTDKB3FU803081908	Colour	M. P. WHITE / RED	
	Odometer	66901	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.			ons of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	SAILUN	9 mm	
	L/H Front Tyre	195/65 R15	SAILUN	9 mm	
	R/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm	
	L/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm	
4.	I	•	on of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE O/S	FRONT PORTION.		
	DAMAGES SEE D				
5.	I		Information		
	Accident Date	09/03/2020	Inspection Date	10/03/2020	
	Survey held at	TRANS-CAB AUTO SERVICES I	PTE LTD		
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a.			emarks		
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W			
5b.		Estimate I	Days of Repair		
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	2.500 Working Da	ays	



## LKK Auto Consultants Pte L 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 **LKK Auto Consultants Pte Ltd**

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9281E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	TORN	516.00	516.00
1	FRONT BUMPER SIDE RETAINER RH	CRACKED	80.10	80.10
1	REINFORCEMENT ,FRONT BUMPER	TO REPAIR SEE LABOUR	716.60	-
1	REINFORCEMENT ,FRONT BUMPER .NO.2	SERVICEABLE	246.10	-
1	ABSORBER ,FRONT BUMPER ,LOWER	SERVICEABLE	132.70	-
1	ABSORBER ,FRONT BUMPER ,ENERGY	SERVICEABLE	79.60	-
1	COVER SUB-ASSY ,ENGINE UNDER ,NO.2	SERVICEABLE	241.90	-
1	COVER ,ENGINE UNDER NO.1	SERVICEABLE	472.40	-
1	EXTENSION ,FRONT BUMPER ,RH	SERVICEABLE	120.10	-
1	FRONT LED LAMP (LOWER )RH	CUT	951.40	951.40
1	FRONT HEADLAMP RH	CUT	2,637.60	2,637.60
1	COMPUTER SUB-ASSY ,HEADLAMP ,RH NO.1	SERVICEABLE	960.50	-
1	MOTOR ,HEADLAMP LEVELING ,RH	SERVICEABLE	487.50	-
1	FRONT FENDER RH	BENT	977.80	977.80
1	LINER ,FRONT FENDER ,RH	CRACKED	206.70	206.70
1	FRONT FENDER EMBLEM RH	NECESSARY	54.60	54.60
1	COVER SUB ASSY ,FRONT PILLAR ,UPPER RH	SERVICEABLE	100.40	-
1	FRONT BONNET	TO REPAIR SEE LABOUR	983.10	-
1	HINGE ASSY ,HOOD ,RH	TO REPAIR SEE LABOUR	58.90	-
1	INSULATOR HOOD	SERVICEABLE	410.90	-
1	GRILLE SUB-ASSY ,RADIATOR	SERVICEABLE	346.00	-
1	EMBLEM ASSY -RADIATOR GRILLE	SERVICEABLE	90.80	-
1	GRILLE ,RADIATOR ,LOWER NO .1	SERVICEABLE	170.10	-
1	JAR ASSY ,WINDSHIELD WASHER	DENTED	219.10	219.10
1	INLET SUB ASSY ,WASHER	SERVICEABLE	67.00	-
1	MOTOR AND PUMP ASSY WINDSHIELD WASHER	SERVICEABLE	292.40	-
1	INLET ,AIR CLEANER NO.3	SERVICEABLE	42.10	-
1	COVER ,RADIATOR SUPPORT OPENING	SERVICEABLE	235.30	-
1	MOULDING ASSY ,BODY ROCKER PANEL ,RH	SERVICEABLE	594.80	-

Report Ref No. CC3/FCI20003862/Kba3q2



## LKK Auto Consultante . 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 **LKK Auto Consultants Pte Ltd**

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	PANEL SUB-ASSY FRONT DOOR ,RH	TO REPAIR SEE LABOUR	1,300.70	-
1	TAPE,BLACK OUT,NO.2 FRT RH	NOT NECESSARY	43.50	-
1	TAPE,BLACK OUT,NO.3 FRT RH	NOT NECESSARY	26.30	-
1	MIRROR ASSY ,OUTER REAR VIEW ,RH	SERVICEABLE	1,436.60	-
	LESS 25% DISCOUNT		-3,824.90	-1,410.82
			11,474.70	4,232.48
	SPECIAL NETT ITEMS			
1	FRONT WHEEL RIM (SN)	TO REPAIR SEE LABOUR	1,879.40	-
1	FRONT WHEEL RIM COVER (SN)	SERVICEABLE	211.50	-
1	FRONT TYRE 195/65/15 (SN)	SERVICEABLE	350.00	-
1	SET CLIP ,FRONT FENDER LINER (SN)	NECESSARY	35.00	35.00
1	FRONT NUMBER PLATE WITH MOULDING (SN)	SERVICEABLE	200.00	-
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	SET FRONT BUMPER RETAINER CLIP (SN)	NOT NECESSARY	35.00	-
1	FRONT WINDSCREEN MOULDING (SN)	NOT NECESSARY	160.00	-
2	WINDSCREEN SEALANT (SN)	NOT NECESSARY	253.80	-
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	120.00	-
1	FRONT DOOR STICKER 'TRANS-CAB' (SN)	NECESSARY	100.00	60.00
1	SET ROCKER PANEL MOULDING CLIP (SN)	NOT NECESSARY	30.00	-
			3,440.70	161.00
	LABOUR			
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REINFORCEMENT ,FRONT BUMPER,FRONT BONNET,HINGE ASSY ,HOOD ,RH,PANEL SUB-ASSY ,FRONT DOOR ,RH AND FRONT WHEEL RIM .		6,000.00	400.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-

Report Ref No. CC3/FCI20003862/Kba3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

5,503.48

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		6,000.00	660.00
	TO TRANSFER OF BONNET FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	-
	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			14,340.00	1,110.00
	GRAND TOTAL		29,255.40	5,503.48

Report Ref No. CC3/FCI20003862/Kba3q2

KSE

KONG SENG CHEONG

**RECOMMENDED COST OF REPAIRS** 

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

# PHOTOGRAPHS FOR VEHICLE NO. SHD 9281E

















51 Ubi Ave 1 #01-25 Paya Ubi hdustrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi hdustrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R









