

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20003866/KEA3Q2

**Date:** 02/10/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070030766

**Claimant**  
**Vehicle No :** SHD5774B **Insured Vehicle No :** SMS5642K

Date of Loss: 06/03/2020 Nature of Claim: TP Claim No: 3819847278SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD5774B</b>		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2B58374
Reg. Date:	01/11/2018 (Man. Year: 2018)	Chassis No:	JTDKB3FU103074864
Colour:	Metallic Pearl White	Odometer:	120384 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,566.40	1,073.57	8,492.83	88.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,170.00	700.00	13,470.00	95.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>23,736.40</b>	<b>1,773.57</b>	<b>21,962.83</b>	<b>92.53</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	1,661.55	124.15	1,537.40	92.53
<b>Nett Amount (\$\$)</b>	<b>25,397.95</b>	<b>1,897.72</b>	<b>23,500.23</b>	<b>92.53</b>
<b>+ Car Rental (2.5 x S\$96.30/day) (\$\$)</b>		240.75		
<b>+ Doc/Search Fee (\$\$)</b>		7.49		
<b>Nett Liability (\$\$)</b>		<b>2,145.96</b>		

### INSPECTION

Date of Assignment: 10/03/2020

Date Inspected: 10/03/2020 Inspected At:

Trans Cab Auto Services Pte Ltd -  
Amk (HQ)  
No 2 Ang Mo Kio St 63  
Singapore 569111

Estimated Period of Repair: 2.5 days

**Adjuster:** KENNETH KONG

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Dented	442.60 FL	*442.60 FL
2	1		*REAR BUMPER REINFORCEMENT	Serviceable	332.70 FL	*- FL
3	1		*REAR BUMPER TOWING COVER	Serviceable	15.40 FL	*- FL
4	1		*GUARD ,REAR BUMPER ,CENTER	Dented / Cut	576.30 FL	*576.30 FL
5	1		*REAR BUMPER ,SIDE RETAINER LH	Serviceable	116.50 FL	*- FL
6	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	117.70 FL	*- FL
7	1		*REAR TAILGATE	Repair	1,147.80 FL	*- FL
8	1		*REAR TAILGATE OUTER GARNISH	Repair	925.60 FL	*- FL
9	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	372.30 FL	*- FL
10	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	650.30 FL	*- FL
11	1		*TAILLAMP LOWER RH	Serviceable	502.00 FL	*- FL
12	1		*TAILLAMP UPPER RH	Serviceable	451.80 FL	*- FL
13	1		*REAR BUMPER SIDE RH	Serviceable	123.70 FL	*- FL
14	1		*REAR BUMPER SIDE LH	Serviceable	123.70 FL	*- FL
15	1		*TAILLAMP LOWER LH	Serviceable	502.00 FL	*- FL
16	1		*TAILLAMP UPPER LH	Serviceable	443.30 FL	*- FL
17	1		*COVER REAR COMBINATION LAMP ,LH	Serviceable	64.50 FL	*- FL
18	1		*COVER REAR COMBINATION LAMP ,RH	Serviceable	64.50 FL	*- FL
19	1		*COVER ,DECK TRIM ,REAR	Serviceable	126.70 FL	*- FL
20	1		*COVER FLOOR UNDER NO 1	Serviceable	175.10 FL	*- FL
21	1		*COVER FLOOR UNDER NO.2	Serviceable	241.90 FL	*- FL
22	1		*COVER REAR FLOOR	Serviceable	229.90 FL	*- FL
23	1		*SEAL ,REAR BUMPER SIDE ,LH	Serviceable	88.50 FL	*- FL
24	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
25	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
26	1		*REAR TAILGATE TOYOTA LOGO	Necessary	47.00 FS	*47.00 FS
27	1		*REAR TAILGATE WORDING PRIUS	Necessary	52.90 FS	*52.90 FS
28	1		*REAR TAILGATE WORDING HYBRID	Necessary	53.50 FS	*53.50 FS
29	1		*REAR TAILGATE STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
30	1		*REAR TAILGATE STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
31	1		*REAR BUMPER PROTECTOR	Necessary	100.00 FS	*30.00 FS
32	1		*REAR WHEEL RIM	Serviceable	1,879.40 FS	*- FS
33	1		*REAR TYRE 195/65 /15	Serviceable	350.00 FS	*- FS
34	1		*REAR WHEEL RIM COVER	Serviceable	211.50 FS	*- FS
35	1		*REAR RH BUMPER RETAINER CLIP	Not Necessary	35.00 FS	*- FS
36	1		*REAR LH BUMPER RETAINER CLIP	Not Necessary	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>11,525.10</b>	<b>1,328.30</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	1,958.70	254.73
<b>Total Parts (\$)</b>	<b>9,566.40</b>	<b>1,073.57</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
2	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
3	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	440.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
6	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
7	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
8	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
9	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
10	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
12	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	6,000.00	200.00
<b>Gross Labour Cost (\$\$)</b>			<b>14,170.00</b>	<b>700.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >