



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. BICYCLE

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRAME: NICOLAI MAIN FRAME	BENT	3,100.00	3,100.00
1	FORK: LYRIK ULT 2020	SCRATCHED / BENT	1,380.00	1,380.00
1	HEADSET	NECESSARY	160.00	160.00
1	HANDLEBAR: ATOMLAB CFR CARBON	BENT	250.00	250.00
1	GRIPS	CUT	40.00	40.00
1	BRAKE: FRONT / REAR	LEAKED / SCRATCHED / BROKEN	480.00	480.00
1	HEELSE: FRONT / REAR	BENT	180.00	180.00
1	RIM: ATOMLAB SL TRAIL 29"	BENT	140.00	140.00
32	SPOKES: BLADED CX RAY	NECESSARY	192.00	192.00
1	TUBE: TUBELESS SET UP	NECESSARY	30.00	30.00
1	TYRES: MAXXIS TIRE	NOT NECESSARY	90.00	-
			6,042.00	5,952.00
LABOUR				
WHEEL BUILDING LABOUR.			100.00	100.00
STRIP AND ASSEMBLY.			80.00	80.00
			180.00	180.00
GRAND TOTAL			6,222.00	6,132.00
RECOMMENDED COST OF REPAIRS				6,132.00

Report Ref No. CC4/FCI20003876/Fea3s2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.