



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCH 6988H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED / CRACKED	1,228.00	1,228.00
1	REAR BUMPER MOULDING CENTRE	NECESSARY	158.00	158.00
2	REAR BUMPER MOULDING SIDE	NECESSARY	116.00	116.00
1	REAR FENDER RIGHT	TO REPAIR SEE LABOUR	2,301.00	-
1	REAR FENDER INNER GARNISH	SERVICEABLE	182.00	-
1	REAR FENDER PROTECTOR	DENTED / CUT	118.00	118.00
1	REAR FENDER PROTECTOR CHROME	NECESSARY	111.00	111.00
1	WHEEL RIM SPORT	DENTED	950.00	950.00
1	REAR WHEEL TYRE	SERVICEABLE	350.00	-
1	KNUCKLE ARM	SERVICEABLE	690.00	-
1	BEARING	JAMMED	354.00	304.00
1	UPPER ARM	SERVICEABLE	560.00	-
1	DRIVE SHAFT	TO REPAIR SEE LABOUR	1,230.00	-
1	REAR SHOCK ABSORBER	SERVICEABLE	650.00	-
1	STAY BAR LINK	SERVICEABLE	340.00	-
	LESS 10% DISCOUNT		-	-298.50
			9,338.00	2,686.50
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR FENDER RIGHT AND DRIVE SHAFT.		1,200.00	500.00
	SPRAY PAINTING.		1,000.00	550.00
	UNDER CARRIAGES N WHEEL ALIGNMENT.		650.00	50.00
			-	-
			-	-
			-	-
			2,850.00	1,100.00
	GRAND TOTAL		12,188.00	3,786.50



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,000.00
---	--	--	----------

Report Ref No. CC4/FCI20003878/Kda3s2

A handwritten signature in black ink, appearing to be 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.