

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20003880/R1GA3Q2

Date: 14/08/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: MCOM0015

Claimant
Vehicle No : SKX2192J

Insured Vehicle No : SHC8782M

Date of Loss: 06/03/2020

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX2192J**

Make & Model: MAZDA 3, 1.4 SEDAN 1.5L SP.6EAT (A)

Engine No: P520328091

Reg. Date: 30/11/2015 (Man. Year: 2015)

Chassis No: JM6BM42A8G0323222

Colour: Black

Odometer: 102545 km

Engine Capacity: 1496 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side: Toyo 6 mm

Rear Left Side:

Toyo 6 mm

Front Right Side: Toyo 6 mm

Rear Right Side:

Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,223.10	1,239.40	983.70	44.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,720.00	1,950.00	2,770.00	58.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,943.10	3,189.40	3,753.70	54.06
+ GST 7.00/7.00% (S\$)	486.02	223.26	262.76	54.06
Nett Amount (S\$)	7,429.12	3,412.66	4,016.46	54.06
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
Nett Liability (S\$)		3,592.66		

INSPECTION

Date of Assignment: 10/03/2020

Date Inspected: 12/03/2020 Inspected At:

Trans Eurokars Pte Ltd - Tanjong

Penjuru (HQ)

27A Tanjong Penjuru

Singapore 609042

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jul 2020)
Parts:	143	MAZDA 3 1.4 SEDAN 1.5L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX2192J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,128.60 F	*1,128.60 F
2	1		*BRACKET CENTER	Serviceable	5.40 F	*- F
3	1		*REAR REINFORCEMENT	Serviceable	564.20 F	*- F
4	4		*GROMMET ,REAR BUMPER	Necessary	10.80 F	*10.80 F
5	2		*GROMMET ,REAR BUMPER	Necessary	6.00 F	*6.00 F
6	4		*FASTENER ,REAR BUMPER	Necessary	12.00 F	*12.00 F
7	4		*RIVET ,REAR BUMPER	Necessary	18.00 F	*18.00 F
8	1		*ORNAMENT ,MAZDA	Not Necessary	56.10 F	*- F
9	1		*MASCOT ,REAR	Not Necessary	78.20 F	*- F
10	1		*ORNAMENT ,SKYACTIVE	Not Necessary	66.80 F	*- F
11	2		*FASTENER ,BOOTLID	Not Necessary	12.40 F	*- F
12	2		*GROMMET ,BOOTLID	Not Necessary	6.60 F	*- F
13	1		*GASKET LHS ,BOOTLID LAMP	Not Necessary	22.00 F	*- F
14	1		*GASKET RHS ,BOOTLID LAMP	Not Necessary	22.00 F	*- F
15	1		*GASKET LHS ,TAILLAMP	Necessary	22.00 F	*22.00 F
16	1		*GASKET RHS ,TAILLAMP	Necessary	22.00 F	*22.00 F
17	1		*NUMBER PLATE	Serviceable	70.00 FS	*- FS
18	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **2,223.10** **1,239.40**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT .TO REPAIR BOOTLID AND ALL AREAS AFFECTED BY THE ACCIDENT	New	1,650.00	660.00
2	TO RESPRAY REAR BUMPER ,REAR REINFORCEMENT AND BOOT LID	New	1,890.00	630.00
3	TO TRANSFER REVERSE SENSORS	New	330.00	330.00
4	TO CARRY OUT BODY CAVITY PRESERVATION	New	250.00	0.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
Gross Labour Cost (S\$)			4,720.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >