

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20003887/KDS3Q2**Date:** 03/11/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900093669
Claimant
Vehicle No : SLN17L **Insured Vehicle No :** SMK9802G
Date of Loss: 08/03/2020 Nature of Claim: TP Claim No: 3345542445SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN17L**
Make & Model: HONDA VEZEL, 1.5 (A) Engine No: 19389939B58B30A
Reg. Date: 01/08/2017 (Man. Year: 2017) Chassis No: WBA7E22080G764272
Colour: Metallic Grey Odometer: 47992 km
Engine Capacity: 2998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/40Z R20 Rear Tyre Size: 275/35Z R20
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 7 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	800.00	400.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,200.00	800.00	400.00	33.33
+ GST 7.00/7.00% (S\$)	84.00	56.00	28.00	33.33
Nett Amount (S\$)	1,284.00	856.00	428.00	33.33
+ Loss of Use (3.0 x S\$120.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,223.45		

INSPECTION

Date of Assignment: 11/03/2020
Date Inspected: 11/03/2020 Inspected At: COMPLETE VMS PTE LTD (HQ)
176 Sin Ming Drive #03-14 Sin Ming
Autocare Complex
Singapore 575721
Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	KNOCK OUT DENT ON L/H REAR DOOR ,L/H REAR FENDER AND SPRAY PAINT	New	1,200.00	800.00
			Gross Labour Cost (\$\$)	1,200.00
				800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >