

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



PRESTIGE APPRAISER SERVICES

Insurance Loss Adjusters and Licensed Appraisers Regn.52868584L
Blk 131 Rivervale Street #05-872 S'pore 540131 Tel:65528323
Fax:64574321

No.

23422

INVOICE

Customer

To M/s Prestige Leasing Pte Ltd
c/o 53 Ubi Ave 1, Paya Ubi Industrial Park
#05-44
Singapore 408934

Date 02-Mar-20
Our ref PS/029/02/20
Your Ref

VEHICLE REGISTRATION NO : SLC 3201 J

VEHICLE MAKE/MODEL : Toyota Vios

INSPECTION REPORT FEES
(inclusive of photographs & transport charges)

\$490.00

DOLLARS: Four Hundred And Ninety Only

○
E. & O. E.

for PRESTIGE APPRAISER SERVICES



PRESTIGE APPRAISER SERVICES

Insurance Loss Adjusters and Licensed Appraiser Regn. 652868584L

Blk 131 Rivervale Street #05-872 S'pore 540131 Tel:65528323 Fax:64574321

Our ref : PS/029/02/20

Date : 02nd March 2020

M/s Prestige Leasing Pte Ltd
c/o 53 Ubi Ave 1, Paya Ubi Industrial Park
#05-44
Singapore 408934

Dear Sir,

Re : **THIRD PARTY CLAIM**

We refer to your instruction to appraise the vehicle **SLC 3201 J** on 21st February 2020.

A static inspection was conducted during our survey and our report is enclosed for your perusal. The estimated repair cost submitted by **Messrs. Neo Automotive Pte Ltd** for **\$11,919.65** as per our attached schedule have been inspected thoroughly each and every item and revised by us against the actual damages found on the vehicle which have been recommended by us accordingly.

The repairer has agreed to undertake repairs at our revised amount of **\$6,700.00 lump sum** corresponding to supply of parts, labour charges and spray-painting. However, we have not given instruction to authorize the repairs.

Under normal circumstances, the estimated period of repairs would be **FIVE (5) days**. Photographs of the damaged vehicle taken by us during our inspection are enclosed.


We are reverting the matter to you for a decision.

Please do not hesitate to contact us if you need any clarification.

Assuring you of our best services.

Yours faithfully,

PRESTIGE APPRAISER SERVICES


LOUIS S C NG CAE AMIMI
Dip. MTM. Automotive Engineer
Licensed Appraiser

Encl.

PRESTIGE APPRAISER SERVICES

VEHICLE INSPECTION REPORT

To: M/s Prestige Leasing Pte Ltd
c/o 53 Ubi Ave 1, Paya Ubi Industrial Park
#05-44
Singapore 408934

Date : 02nd March 2020
Our Ref : PS/029/02/20
Policy No :
Sum Insured :
Excess : T/P Claim

Assigned By : M/s Prestige Leasing Pte Ltd
Assignment Date : 21st February 2020
Accident Date : 19th February 2020
Inspection Date : 21st February 2020
Workshop Name : Neo Automotive Pte Ltd
Survey Conducted At : 53 Ubi Ave 1, Paya Ubi Industrial Park
#05-44
Singapore 408934

PARTICULARS OF VEHICLE

Registration No	: SLC 3201 J	Mileage	: 280683km
Make/Model	: Toyota Vios	Engine No	: HIDDEN
Type Of Body	: Motorcar	Chassis No	: MHFBT9F3X06068426
Year Of Manu./Regn.	: 2015/2016	Passenger Cap.	: 4 Passengers
Colour	: Met. Silver	Others	: -

CONDITION OF TYRES

R/H SIDE

Front Tyre : 6mm 195/50R16 Grenlander
Rear Tyre : 6mm 195/50R16 Achilles

L/H SIDE

6mm 195/50R16 Grenlander
6mm 195/50R16 Achilles

The above represent the estimated remaining life of the tyre treads.

PRE-ACCIDENT CONDITION (Static tests only)

Handbrake	: Serviceable	Body Work	: Good
Footbrake	: Serviceable	Paint Work	: Good
Steering	: Serviceable	Others	: -

POINT OF IMPACT

The vehicle sustained an impact on the rear portion.

GENERAL DESCRIPTION OF DAMAGES

The rear body panel, bumper assy, floorboard panel, fenders, bootlid were dented/distorted.

For details of damages please refer to schedule attached.

REMARKS :

This survey was conducted strictly without prejudice.

PRESTIGE APPRAISER SERVICES

Vehicle No : SLC 3201 J

Our Ref :


PS/029/02/20

Qty	Descriptions	Conditions	Repairer's Est.	Our Revised.
	<u>LIST ITEMS</u>			
1	rear bumper	dented	\$ 929.50	\$ 929.50
1	rear bumper reinforcement	dented	420.50	420.50
2	rear bumper side retainer	necessary	97.80	97.80
2	rear bumper reflector	holder cracked	286.20	286.20
8	rear bumper clip	necessary	32.40	32.40
1	rear body panel	dented	518.10	518.10
1	rear body panel top garnish	dented	385.90	385.90
4	rear body panel top garnish clip	necessary	51.60	51.60
1	R/H taillamp	grazed/cut	785.90	785.90
1	R/H taillamp bracket	dented	35.10	35.10
1	L/H taillamp	broken	785.90	785.90
1	L/H taillamp bracket	dented	35.10	35.10
2	taillamp panel	dented - repair	184.80	-
1	bootlid	dented/distorted	1,090.15	1,090.15
1	bootlid weatherstrip	distorted	210.20	210.20
2	boot hinge	dented - repair	302.90	-
1	boot top lock	dented	190.60	190.60
1	boot lower lock	dented	53.90	53.90
1	boot outer moulding	holder cracked	281.20	281.20
1	boot emblem ' LOGO '	necessary	51.00	51.00
1	boot emblem ' E '	necessary	31.00	31.00
1	boot emblem ' VIOS '	necessary	32.80	32.80
1	L/H rear fender	dented - repair	1,113.60	-
1	L/H rear fender inner garnish	dented/distorted	381.75	381.75
1	R/H rear fender inner garnish	dented/distorted	381.75	381.75
			<u>8,669.65</u>	<u>7,068.35</u>
		Less 25%	-	<u>1,413.67</u>
			\$ <u>8,669.65</u>	\$ <u>5,654.68</u>
	<u>S/NETT ITEM</u>			
1set	reverse sensor	damaged	280.00	250.00
	<u>Labour Charges & Misc</u>			
	To dismantle & replace damaged parts, panel beat where necessary.		1,300.00	1,050.00
	To putty, apply primer & spray-paint on the affected portion.		1,300.00	1,100.00
	To apply rust-proofing on repaired, replaced panel.		150.00	120.00
	To remove/refit rear compartment garnish to facilitate repairs.		150.00	120.00
	To check wiring functions.		70.00	50.00
			\$ <u>11,919.65</u>	\$ <u>8,344.68</u>

Note: The repairer has agreed to undertake the repairs at our adjusted amount of **\$6,700.00 lump sum** corresponding to supply of parts, labour and spray-painting charges.

Under normal circumstances, the estimated repair period would be **FIVE (5)** days.
Pursuant to your instruction we have **not** authorised repairs on your behalf.

PRESTIGE APPRAISER SERVICES


LOUIS S C NG CAE AMIMI (UK)
Licensed Appraiser
Dip. MTM. Automotive Engineer

Summer Lee (LKK Auto)

From: Shelia (LKK Auto) <account@lkkauto.com>
Sent: Thursday, 12 March, 2020 9:30 AM
To: 'Nivitha (LKK Auto)'
Cc: 'Shelia (LKK Auto)'
Subject: RE: Report Send Back Alerts - SLC3201J (TP)

Dear Nivitha / Summer,

FYNA Please...

Pending for Survey Report-CS3/MSG20002973/HTF3S2

11 Mar 2020 18:54	Ins Send Back Adj Rpt	For paper survey	[I] Katherine Wong
11 Mar 2020 18:54	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/03/13	[I] Merimen Administrator
11 Mar 2020 18:54	Adj Mandate Set	Maintained.	[I] Merimen Administrator

Best Regards,

SuthaShelia (Shelia) | Accounts Dept.

LKK Auto Consultants Pte Ltd

Phone: 6841 1891 | email: account@lkkauto.com | fax: 6844-8805

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Do-Not-Reply <do-not-reply@merimen.com>

Sent: Wednesday, 11 March 2020 7:00 PM

To: account@lkkauto.com

Subject: Report Send Back Alerts - SLC3201J (TP)

Dear Sir / Madam,

Please login to Merimen Online at www.merimen.com.sg for more information.

Thanks,

The Merimen Team



This email has been checked for viruses by AVG antivirus software.
www.avg.com

PRESTIGE APPRAISER SERVICES

VEHICLE INSPECTION REPORT

To: M/s Prestige Leasing Pte Ltd
c/o 53 Ubi Ave 1, Paya Ubi Industrial Park
#05-44
Singapore 408934

Date : 02nd March 2020
Our Ref : PS/029/02/20
Policy No :
Sum Insured :
Excess : T/P Claim

Assigned By : M/s Prestige Leasing Pte Ltd
Assignment Date : 21st February 2020
Accident Date : 19th February 2020
Inspection Date : 21st February 2020
Workshop Name : Neo Automotive Pte Ltd
Survey Conducted At : 53 Ubi Ave 1, Paya Ubi Industrial Park
#05-44
Singapore 408934

PARTICULARS OF VEHICLE

Registration No	: SLC 3201 J	Mileage	: 280683km
Make/Model	: Toyota Vios	Engine No	: HIDDEN
Type Of Body	: Motorcar	Chassis No	: MHFBT9F3X06068426
Year Of Manu./Regn.	: 2015/2016	Passenger Cap.	: 4 Passengers
Colour	: Met. Silver	Others	: -

CONDITION OF TYRES

R/H SIDE

Front Tyre : 6mm 195/50R16 Grenlander
Rear Tyre : 6mm 195/50R16 Achilles

L/H SIDE

6mm 195/50R16 Grenlander
6mm 195/50R16 Achilles

The above represent the estimated remaining life of the tyre treads.

PRE-ACCIDENT CONDITION (Static tests only)

Handbrake	: Serviceable	Body Work	: Good
Footbrake	: Serviceable	Paint Work	: Good
Steering	: Serviceable	Others	: -

POINT OF IMPACT

The vehicle sustained an impact on the rear portion.

GENERAL DESCRIPTION OF DAMAGES

The rear body panel, bumper assy, floorboard panel, fenders, bootlid were dented/distorted.

For details of damages please refer to schedule attached.

REMARKS :

This survey was conducted strictly without prejudice.

PRESTIGE APPRAISER SERVICES

Insurance Loss Adjusters and Licensed Appraisers Regn.52868584L
Blk 131 Rivervale Street #05-872 S'pore 540131 Tel:65528323
Fax:64574321

No. 23422

INVOICE

Customer

To M/s Prestige Leasing Pte Ltd
c/o 53 Ubi Ave 1, Paya Ubi Industrial Park
#05-44
Singapore 408934

Date 02-Mar-20
Our ref PS/029/02/20
Your Ref

VEHICLE REGISTRATION NO : SLC 3201 J

VEHICLE MAKE/MODEL : Toyota Vios

INSPECTION REPORT FEES
(inclusive of photographs & transport charges)

\$490.00

DOLLARS: Four Hundred And Ninety Only

○
E. & O. E.

for PRESTIGE APPRAISER SERVICES



PRESTIGE APPRAISER SERVICES

Vehicle No : SLC 3201 J

Our Ref :

PS/029/02/20

Qty	Descriptions	Conditions	Repairer's Est.	Our Revised.
<u>LIST ITEMS</u>				
1	rear bumper ✓ <i>cpm</i>	dented	\$ 929.50	\$ 929.50 ✓ <i>432.40</i>
1	rear bumper reinforcement x (R) ✓ <i>cpm</i>	dented	420.50	420.50 ✓
2	rear bumper side retainer ✓ <i>cpm</i>	necessary	97.80	97.80 ✓ <i>73.40</i>
2	rear bumper reflector L/H ✓ <i>cpm</i>	holder cracked	286.20	286.20 ✓ <i>179.80</i>
8	rear bumper clip ✓ <i>cpm</i>	necessary	32.40	32.40 ✓ <i>20</i>
1	rear body panel x (R) ✓ <i>cpm</i>	dented	518.10	518.10 ✓
1	rear body panel top garnish ✓ <i>cpm</i>	dented	385.90	385.90 ✓ <i>245.20</i>
4	rear body panel top garnish clip ✓ <i>cpm</i>	necessary	51.60	51.60 ✓ <i>10</i>
1	R/H taillamp ✓ <i>cpm</i>	grazed/cut	785.90	785.90 ✓ <i>387.80</i>
1	R/H taillamp bracket x (R) ✓ <i>cpm</i>	dented	35.10	35.10 ✓
1	L/H taillamp ✓ <i>cpm</i>	broken	785.90	785.90 ✓ <i>387.80</i>
1	L/H taillamp bracket x (R) ✓ <i>cpm</i>	dented	35.10	35.10 ✓
2	taillamp panel x (R) ✓ <i>cpm</i>	dented - repair	184.80	-
1	bootlid x (R) ✓ <i>cpm</i>	dented/distorted	1,090.15	4,090.15 ✓
1	bootlid weatherstrip ✓ <i>cpm</i>	distorted	210.20	210.20 ✓
2	boot hinge x (R) ✓ <i>cpm</i>	dented - repair	302.90	-
1	boot top lock ✓ <i>cpm</i>	dented	190.60	190.60 ✓
1	boot lower lock x (SVC) ✓ <i>cpm</i>	dented	53.90	53.90 ✓
1	boot outer moulding x (SVC) ✓ <i>cpm</i>	holder cracked	281.20	281.20 ✓
1	boot emblem ' LOGO ' ✓ <i>cpm</i>	necessary	51.00	51.00 ✓
1	boot emblem ' E ' ✓ <i>cpm</i>	necessary	31.00	31.00 ✓
1	boot emblem ' VIOS ' ✓ <i>cpm</i>	necessary	32.80	32.80 ✓
1	L/H rear fender x (R) ✓ <i>cpm</i>	dented - repair	4,113.60	-
1	L/H rear fender inner garnish x (SVC) ✓ <i>cpm</i>	dented/distorted	381.75	381.75 ✓
1	R/H rear fender inner garnish x (SVC) ✓ <i>cpm</i>	dented/distorted	381.75	381.75 ✓
			8,669.65	7,068.35
			Less 25%	1,413.67
			\$ 8,669.65	\$ 5,654.68 ✓

<u>S/NETT ITEM</u>				
1set	reverse sensor ✓ <i>slant</i>	damaged	280.00	250.00 ✓ <i>200</i>

Labour Charges & Misc

To dismantle & replace damaged parts, panel beat where necessary.

1,300.00 1,050.00 ✓ *600*

To putty, apply primer & spray-paint on the affected portion.

1,300.00 1,100.00 ✓ *660*

To apply rust-proofing on repaired, replaced panel.

150.00 120.00 ✓ *40*

To remove/refit rear compartment garnish to facilitate repairs.

150.00 120.00 ✓

To check wiring functions.

70.00 50.00 ✓ *30*

\$ 11,919.65 \$ 8,344.68

Note: The repairer has agreed to undertake the repairs at our adjusted amount of **\$6,700.00 lump sum** corresponding to supply of parts, labour and spray-painting charges.

Under normal circumstances, the estimated repair period would be **FIVE (5)** days.

Pursuant to your instruction we have **not** authorised repairs on your behalf.

PRESTIGE APPRAISER SERVICES

LOUIS S C NG CAE AMIMI (UK)

Licensed Appraiser

Dip. MTM. Automotive Engineer

PRESTIGE APPRAISER SERVICES

Insurance Loss Adjusters and Licensed Appraiser Regn. 652868584L

Blk 131 Rivervale Street #05-872 S'pore 540131 Tel:65528323 Fax:64574321

Our ref : PS/029/02/20
Date : 02nd March 2020

M/s Prestige Leasing Pte Ltd
c/o 53 Ubi Ave 1, Paya Ubi Industrial Park
#05-44
Singapore 408934

Dear Sir,

Re : THIRD PARTY CLAIM

We refer to your instruction to appraise the vehicle **SLC 3201 J** on 21st February 2020.

A static inspection was conducted during our survey and our report is enclosed for your perusal. The estimated repair cost submitted by **Messrs. Neo Automotive Pte Ltd** for **\$11,919.65** as per our attached schedule have been inspected thoroughly each and every item and revised by us against the actual damages found on the vehicle which have been recommended by us accordingly.

The repairer has agreed to undertake repairs at our revised amount of **\$6,700.00 lump sum** corresponding to supply of parts, labour charges and spray-painting. However, we have not given instruction to authorize the repairs.

Under normal circumstances, the estimated period of repairs would be **FIVE (5) days**. Photographs of the damaged vehicle taken by us during our inspection are enclosed.

We are reverting the matter to you for a decision.

Please do not hesitate to contact us if you need any clarification.

Assuring you of our best services.

Yours faithfully,

PRESTIGE APPRAISER SERVICES

LOUIS S C NG CAE AMIMI
Dip. MTM. Automotive Engineer
Licensed Appraiser

Encl.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

parts	2312.40
parts here	25%
	1734.30
spec mnt	200
labour	1330
	3264.30
4/s sup	20%
	2611.44
total	↓
amount	\$ 2600

paper super
13/3/20 1.50pm
under paper
Range after part
H. ANN (HAW)
4/s repair
4 day

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Feb 2020		21 Feb 2020 09:57 Edit Adj Rpt	S\$2,600.00 Edit Estimates	S\$2,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CAMLYN TAN, ID: S7231523E								
Main Claimant:	PRESTIGE LEASING P/L, Co. Reg. No.: 201723326H								
Vehicle Reg. No.:	SLC3201J	Date of Loss:	19/01/2020 10:00 - :59 [44 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 620216	Policy/Cover Note No.:	29118376AVW (Comprehensive) Coverage: 28/02/2019 - 27/02/2020						
Vehicle Reg. No. (Insured):	SMJ3570U	Policy No. (Claimant):							
		Excess:							
Repairer:	Neo Automotive Pte Ltd (HQ) 53 UBI AVE 1, #05-44 PAYA UBI INDUSTRIAL PARK, 408934 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 13/03/2020]								
Driver/Custodian (Insured):	SIM TONG BENG (/ Male) , NRIC: S7032045B Email:								
Adj Asg. Remarks:	on WP, Liab: Clear. Car in as spoken with Mrs Neo Tks. WC.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (11/03/2020): Report Send Back Alerts - SLC3201J (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLC3201J (620216)

[SMJ3570U]

TP

PRESTIGE LEASING P/L




































Jan 19 2020 10:00AM







































[CAMLYN TAN]










Neo Automotive Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/02/20 10:10	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
2	24/02/20 10:10	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
3	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
4	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
5	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
6	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
7	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
8	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
9	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
10	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
11	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
12	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
13	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
14	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
15	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
16	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
17	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
18	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
19	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
20	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
21	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
22	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
23	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
24	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
25	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
26	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
27	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
28	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
29	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
30	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
31	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
32	24/02/20 10:11	General View	 Load JPG	<input checked="" type="checkbox"/>
33	24/02/20 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	24/02/20 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	24/02/20 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	24/02/20 10:11	Reinspection Photo	 Load JPG	✓
37	24/02/20 10:11	Reinspection Photo	 Load JPG	✓
38	24/02/20 10:11	Reinspection Photo	 Load JPG	✓
39	24/02/20 10:11	Reinspection Photo	 Load JPG	✓
40	24/02/20 10:11	Reinspection Photo	 Load JPG	✓
41	24/02/20 10:11	Reinspection Photo	 Load JPG	✓
42	24/02/20 10:11	Reinspection Photo	 Load JPG	✓
43	24/02/20 10:11	Reinspection Photo	 Load JPG	✓
44	24/02/20 10:11	Reinspection Photo	 Load JPG	✓
45	24/02/20 10:11	Reinspection Photo	 Load JPG	✓
46	24/02/20 10:11	Reinspection Photo	 Load JPG	✓
47	24/02/20 10:11	Reinspection Photo	 Load JPG	✓
48	24/02/20 10:11	Reinspection Photo	 Load JPG	✓
49	24/02/20 10:11	Reinspection Photo	 Load JPG	✓
50	24/02/20 10:11	Reinspection Photo	 Load JPG	✓
51	24/02/20 10:11	Reinspection Photo	 Load JPG	✓
52	24/02/20 10:11	Reinspection Photo	 Load JPG	✓
53	24/02/20 10:11	Reinspection Photo	 Load JPG	✓
54	24/02/20 10:11	Reinspection Photo	 Load JPG	✓
55	24/02/20 10:12	Reinspection Photo	 Load JPG	✓
56	24/02/20 10:12	Reinspection Photo	 Load JPG	✓
57	24/02/20 10:12	Reinspection Photo	 Load JPG	✓
58	24/02/20 10:12	Reinspection Photo	 Load JPG	✓
59	24/02/20 10:12	Reinspection Photo	 Load JPG	✓
60	24/02/20 10:12	Reinspection Photo	 Load JPG	✓
61	24/02/20 10:12	Reinspection Photo	 Load JPG	✓
62	24/02/20 10:12	Reinspection Photo	 Load JPG	✓
63	24/02/20 10:12	Reinspection Photo	 Load JPG	✓
64	24/02/20 10:12	Reinspection Photo	 Load JPG	✓
65	24/02/20 10:12	Reinspection Photo	 Load JPG	✓
66	24/02/20 10:12	Reinspection Photo	 Load JPG	✓
67	24/02/20 10:12	Reinspection Photo	 Load JPG	✓
68	27/02/20 08:47	After Repair Photo	 Load JPG	✓
69	27/02/20 08:47	After Repair Photo	 Load JPG	✓
70	27/02/20 08:47	After Repair Photo	 Load JPG	✓
71	27/02/20 08:47	After Repair Photo	 Load JPG	✓
72	27/02/20 08:47	After Repair Photo	 Load JPG	✓
73	27/02/20 08:47	After Repair Photo	 Load JPG	✓

Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/02/20 17:17	OI Gia Report	 Load PDF	
2	20/02/20 17:17	TP SLC3201J Gia Report	 Load PDF	
3	20/02/20 17:18	PRI from C Yogarajah LLC	 Load PDF	
4	20/02/20 17:22	Policy	 Load PDF	
5	20/02/20 17:33	email from opts	 Load PDF	
6	20/02/20 17:34	email to workshop	 Load PDF	
7	10/03/20 15:42	Survey Report & Invoice	 Load PDF	
8	10/03/20 15:42	Survey Report Photos 1	 Load PDF	
9	10/03/20 15:42	Survey Report Photos 2	 Load PDF	

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	16/03/20 09:17	PRS INVOICE	1	Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG20002973/HTF3S2-1
Date: 16/03/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29118376AVW

Claimant Vehicle No: SLC3201J

Insured Vehicle No: SMJ3570U

Date of Loss: 19/01/2020

Nature of Claim: TP Claim No: 620216

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLC3201J

Make & Model: TOYOTA VIOS, 1.5 E GRADE (A)

Engine No: 1NZZ325275

Reg. Date: 10/05/2016 (Man. Year: 2015)

Chassis No: MHFBT9F3X06068426

Colour: Silver

Odometer: 280682 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50 R15

Rear Tyre Size: 195/50 R15

Front Left Side: Grenlander 5 mm

Rear Left Side: Grenlander 5 mm

Front Right Side: Grenlander 5 mm

Rear Right Side: Grenlander 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,949.65	1,934.30	7,015.35	78.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,970.00	1,330.00	1,640.00	55.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,919.65	3,264.30	8,655.35	72.61
Approved Total (Overridden) (S\$)		2,600.00		
Nett Amount (S\$)	11,919.65	2,600.00	9,319.65	78.19

INSPECTION

Date of Assignment: 21/02/2020

Date Inspected: 21/02/2020 Inspected At:

Neo Automotive Pte Ltd (HQ)
53 UBI AVE 1, #05-44 PAYA UBI INDUSTRIAL PARK
Singapore 408934

Estimated Period of Repair: 4.0 days

Adjuster: LEE HOCK ANN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Mar 2020)
Parts:	143	TOYOTA VIOS 1.5 E GRADE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC3201J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Crushed	929.50 F	*492.80 FL
2	1		*REAR BUMPER REINFORCEMENT	Repair	420.50 F	*- FL
3	2		*REAR BUMPER SIDE RETAINER	Necessary	97.80 F	*73.40 FL
4	1		*REAR BUMPER REFLECTOR	N/s Cracked	286.20 F	*179.80 FL
5	8		*REAR BUMPER CILIP	Necessary	32.40 F	*20.00 FL
6	1		*REAR BODY PANEL	Repair	518.10 F	*- FL
7	1		*REAR BODY PANEL TOP GARNISH	Crushed	385.90 F	*245.20 FL
8	4		*REAR BODY PANEL TOP GARNISH CLIP	Necessary	51.60 F	*10.00 FL
9	1		*R/H TAILLAMP	Cracked	785.90 F	*387.80 FL
10	1		*R/H TAILLAMP BRACKET	Repair	35.10 F	*- FL
11	1		*L/H TAILLAMP	Cracked	785.90 F	*387.80 FL
12	1		*L/H TAILLAMP BRACKET	Repair	35.10 F	*- FL
13	2		*TAILLAMP PANEL	Repair	184.80 F	*- FL
14	1		*BOOTLID	Repair	1,090.15 F	*- FL
15	1		*BOOTLID WEATHERSTRIP	Crushed	210.20 F	*210.20 FL
16	2		*BOOT HINGE	Repair	302.90 F	*- FL
17	1		*BOOT TOP LOCK	Jammed	190.60 F	*190.60 FL
18	1		*BOOT LOWER LOCK	Serviceable	53.90 F	*- FL
19	1		*BOOT OUTER MOULDING	Serviceable	281.20 F	*- FL
20	1		*BOOT EMBLEM LOGO	Necessary	51.00 F	*51.00 FL
21	1		*BOOT EMBLEM E	Necessary	31.00 F	*31.00 FL
22	1		*BOOT EMBLEM VIOS	Necessary	32.80 F	*32.80 FL
23	1		*L/H REAR FENDER	Repair	1,113.60 F	*- FL
24	1		*L/H REAR FENDER INNER GARNISH	Serviceable	381.75 F	*- FL
25	1		*R/H REAR FENDER INNER GARNISH	Serviceable	381.75 F	*- FL
26	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,949.65	2,512.40
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	578.10
Total Parts (S\$)	8,949.65	1,934.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACE DAMAGE PARTS, PANEL BEAT WHERE NECESSARY.	New	1,300.00	600.00
2	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	New	1,300.00	660.00
3	TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL.	New	150.00	40.00
4	TO REMOVE / REFIT REAR COMPARTMENT GARNISH TO FACILITATE REPAIRS.	New	150.00	0.00
5	TO CHECK WIRING FUNCTIONS.	New	70.00	30.00
Gross Labour Cost (\$\$)			2,970.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >