

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20003894/R1YF3E2

Date: 26/08/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00008522003
Claimant Vehicle No :	SLU8447P	Insured Vehicle No :	GV5107U
Date of Loss:	08/03/2020	Nature of Claim:	TP
		Claim No:	SNM20D201204/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU8447P	Engine No:	CYV515044
Make & Model:	VOLKSWAGEN GOLF, 1.2 (A7) TSI (A)	Chassis No:	WVWZZZAUZHW120345
Reg. Date:	15/12/2017 (Man. Year: 2016)	Odometer:	47149 km
Colour:	Grey		
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,478.00	3,214.00	3,264.00	50.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,282.00	3,702.00	1,580.00	29.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,760.00	6,916.00	4,844.00	41.19
+ GST 7.00/7.00% (S\$)	823.20	484.12	339.08	41.19
Nett Amount (S\$)	12,583.20	7,400.12	5,183.08	41.19

INSPECTION

Date of Assignment:	12/03/2020	
Date Inspected:	13/03/2020 Inspected At:	Premium Automobiles Pte Ltd - Alexandra (HQ)
		281 Alexandra Pte Ltd, Level B2
		Singapore 159938
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,831.00 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Aug 2020)
Parts:	144	VOLKSWAGEN GOLF 1.2 (A7) TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU8447P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,394.00 FS	*1,394.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Necessary	102.00 FS	*102.00 FS
3	1		*FRONT BUMPER SUPPORT ELEMENT - RH	* Check	92.00 FS	*- FS
4	1		*SPOILER RETAINER	* Check	315.00 FS	*- FS
5	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	734.00 FS	*- FS
6	1		*FRONT BUMPER FOAM FILLER PIECE - CENTRE	Not Necessary	71.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE PROFILE - RH	* Check	35.00 FS	*- FS
8	1		*RADIATOR GRILLE	* Check	539.00 FS	*- FS
9	1		*VOLKSWAGEN EMBLEM - FRONT	* Check	176.00 FS	*- FS
10	1		*RADIATOR VENT GRILLE - CENTRE	Not Necessary	217.00 FS	*- FS
11	1		*BUMPER COVER PART - RH	* Check	47.00 FS	*- FS
12	1		*RADIATOR GUIDE GRILLE - RH	* Check	153.00 FS	*- FS
13	1		*FRONT FENDER - RH	Buckled	725.00 FS	*725.00 FS
14	1		*UNDERBODY PROTECTION	Not Necessary	77.00 FS	*- FS
15	1		*ANTI CORROSION WAX	Necessary	44.00 FS	*44.00 FS
16	1		*ADHESIVE SEALANT	Necessary	40.00 FS	*40.00 FS
17	1		*FRONT FENDER BRACE - RH	* Check	53.00 FS	*- FS
18	1		*FENDER SUPPORT - FRONT / REAR	Frt Not Necessary/Rear * Check	70.00 FS	*- FS
19	1		*WHEEL HOUSING LINER - RH	Not Necessary	197.00 FS	*- FS
20	1		*WHEEL HOUSING LINER - RH	Not Necessary	102.00 FS	*- FS
21	1		*FRONT FENDER ATTACHMENT PARTS	Necessary	50.00 FS	*50.00 FS
22	1		*HEADLIGHTS BRACKET - RH FRONT	* Check	14.00 FS	*- FS
23	1		*HEADLIGHT RETAINING PLATE - RH FRONT	* Check	72.00 FS	*- FS
24	1		*SUNDRIES	* Check	300.00 FS	*- FS
25	1		*HALOGEN TWIN HEADLIGHTS - RH	Scratched	859.00 FS	*859.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **6,478.00** **3,214.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,450.00	1,750.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	1,400.00
4	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,282.00	3,702.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >