

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20003904/HKS3Q2

Date: 15/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800151604

Claimant
Vehicle No : SML5729G **Insured Vehicle No :** SMG5479D

Date of Loss: 08/03/2020 Nature of Claim: TP Claim No: 0808548755SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|--|-------------|-------------------|
| Reg No: | SML5729G | | |
| Make & Model: | RENAULT GRAND SCENIC IV, 1.5 DCI EU6 (A) | Engine No: | K9KF649D059777 |
| Reg. Date: | 27/05/2019 (Man. Year: 2019) | Chassis No: | VF1RFA00762894733 |
| Colour: | Silver | Odometer: | 76125 km |
| Engine Capacity: | 1461 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 195/55 R20 | Rear Tyre Size: | 195/55 R20 |
| Front Left Side: | Goodyear 7 mm | Rear Left Side: | Goodyear 7 mm |
| Front Right Side: | Goodyear 7 mm | Rear Right Side: | Goodyear 7 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 8,060.67 | 3,869.91 | 4,190.76 | 51.99 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,700.00 | 930.00 | 770.00 | 45.29 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 9,760.67 | 4,799.91 | 4,960.76 | 50.82 |
| Approved Total (Overridden) (\$\$) | | 3,850.00 | | |
| (\$\$) | 9,760.67 | 3,850.00 | 5,910.67 | 60.56 |
| + GST 7.00/7.00% (\$\$) | 683.25 | 269.50 | 413.75 | 60.56 |
| Nett Amount (\$\$) | 10,443.92 | 4,119.50 | 6,324.42 | 60.56 |
| + Doc/Search Fee (\$\$) | | 2.00 | | |
| Nett Liability (\$\$) | | 4,121.50 | | |

INSPECTION

Date of Assignment: 10/03/2020

Date Inspected: 10/03/2020 Inspected At: Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Estimated Period of Repair: 3.0 days

Adjuster: LEE HOCK ANN**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|---------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER | Cracked | 1,550.00 FL | *1,250.50 FL |
| 2 | 1 | | *N/S FRONT BUMPER SIDE GARNISH L/H | Crumpled | 117.20 FL | *117.20 FL |
| 3 | 1 | | *FRONT BUMPER LOWER GRILLE | Serviceable | 427.40 FL | *- FL |
| 4 | 1 | | *FRONT BUMPER ABSORBER FOAM | Serviceable | 180.00 FL | *- FL |
| 5 | 1 | | *FRONT BUMPER REINFORCEMENT | Serviceable | 624.20 FL | *- FL |
| 6 | 4 | | *FRONT BUMPER LOWER AIR GUIDE CLIP | Serviceable | 14.00 FL | *- FL |
| 7 | 1 | | *FRONT BUMPER LOWER LIP | Scratched | 436.00 FL | *320.50 FL |
| 8 | 1 | | *N/S FRONT BUMPER FOG LAMP | Serviceable | 222.60 FL | *- FL |
| 9 | 1 | | *N/S FRONT BUMPER FOG LAMP OUTER CHROME L/H | Scratched | 234.10 FL | *172.40 FL |
| 10 | 1 | | *N/S FRONT BUMPER FOG LAMP COVER L/H | Scratched | 234.10 FL | *210.40 FL |
| 11 | 1 | | *N/S FRONT BUMPER PARKING SENSOR | N/S Shorted | 1,120.00 FL | *280.00 FL |
| 12 | 1 | | *N/S FRONT BUMPER BASE | Not Necessary | 363.30 FL | *- FL |
| 13 | 1 | | *RADIATOR GRILLE | Serviceable | 427.40 FL | *- FL |
| 14 | 1 | | *RADIATOR GRILLE OUTER CHROME | Scratched | 261.10 FL | *180.50 FL |
| 15 | 1 | | *RADIATOR GRILLE GARNISH | Serviceable | 266.40 FL | *- FL |
| 16 | 1 | | *RADIATOR GRILLE TOP BRACKET | Serviceable | 112.30 FL | *- FL |
| 17 | 1 | | *N/S HEADLAMP L/H | Cracked | 980.00 FL | *820.50 FL |
| 18 | 1 | | *N/S HEADLAMP L/H BRACKET L/H | Bent | 112.30 FL | *112.30 FL |
| 19 | 1 | | *N/S FRONT FENDER L/H | Cracked | 615.20 FL | *615.20 FL |
| 20 | 1 | | *N/S FRONT FENDER INNER COWLING L/H | Cracked | 250.40 FL | *210.40 FL |
| 21 | 1 | | *N/S FRONT FENDER INNER COWLING CLIP (3 PCS) | Necessary | 15.00 FL | *10.00 FL |
| 22 | 1 | | *FRONT SUPPORT PANEL TOP GARNISH | Serviceable | 393.30 FL | *- FL |

F=Franchise part. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$\$) | 8,956.30 | 4,299.90 |
| - List Item Discount on L Items 10.00/10.00% (\$\$) | 895.63 | 429.99 |
| Total Parts (\$\$) | 8,060.67 | 3,869.91 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|---------------|
| <u>Labour Items</u> | | | | |
| 1 | TO CHECK ELECTRICAL LIGHTING CONCERNED | New | 80.00 | 30.00 |
| 2 | TO RUST-PROOFING OF THE AFFECTED AREAS | New | 120.00 | 30.00 |
| 3 | TO REINSTALL OF FRONT BUMPER PARKING SENSOR | New | 50.00 | 20.00 |
| 4 | PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME | New | 750.00 | 400.00 |
| 5 | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION | New | 700.00 | 450.00 |
| Gross Labour Cost (\$\$) | | | 1,700.00 | 930.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >