Adjuster Report Page 1 of 4

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20003905/T1PS3Q2

**Date:** 08/03/2021

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100051613

Claimant SI B3795S Insured Vehicle No: SIA548M

Vehicle No: SLB3795S Insured Vehicle No: SJA548M

Date of Loss: 08/03/2020 Nature of Claim: TP Claim No: 9269472439SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SLB3795S

Make & Model: HONDA ODYSSEY, 2.4 EXV-S CVT SR (A) Engine No: K24W72011347

Reg. Date: 05/04/2016 (Man. Year: 2016) Chassis No: JHMRC1890GC203000

Colour: White Odometer: 0 km

Engine Capacity: 2356 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 235/45R18 Rear Tyre Size: 235/45R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,080.72	3,166.32	1,914.40	37.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,910.00	860.00	1,050.00	54.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,990.72	4,026.32	2,964.40	42.40
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	6,990.72	3,200.00	3,790.72	54.23
+ GST 7.00/7.00% (S\$)	489.35	224.00	265.35	54.22
Nett Amount (S\$)	7,480.07	3,424.00	4,056.07	54.23
+ Car Rental (3.0 x S\$15	50.00/day) (S\$)	450.00		
+ Doc/Se	36.45			
Net	3,910.45			
Global Sum S	3,900.00			

**INSPECTION** 

Date of Assignment: 10/03/2020

Date Inspected: 10/03/2020 Inspected At: Teamwork Garage Pte Ltd (HQ)

53 Ubi Ave 1 #01-24, Paya Ubi

Industrial Park Singapore 408934

Estimated Period of Repair: 3.0 days

Adjuster Report Page 2 of 4

Adjuster: MOHD TAUFIKH BIN HAMID Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT RH FENDER	Repair	617.55 FL	*-FL	
2	1		*FRONT RH FENDER INNER SHIELD	Cut	135.00 FL	*135.00 FL	
3	1		*FRONT GRILLE ASSY	Not Necessary	189.75 FL	*- FL	
4	1		*FRONT GRILLE MOULDING	Not Necessary	355.35 FL	*-FL	
5	1		*FRONT LOWER GRILLE	Not Necessary	247.25 FL	*- FL	
6	1		*FRONT LOWER GRILLE MOULDING	Not Necessary	288.60 FL	*-FL	
7	1		*FRONT BUMPER	Deformed	819.40 FL	*819.40 FL	
8	1		*FRONT BUMPER RETAINER	N/S Not Necessary/O/SNecessary	86.00 FL	*43.00 FL	
9	1		*FRONT BUMPER SIDE GRILLE RH	Cut	90.00 FL	*90.00 FL	
10	1		*FRONT BUMPER FOG LAMP RH	Cracked	300.15 FL	*182.30 FL	
11	1		*FRONT BUMPER LOWER GRILLE RH	Cut	89.70 FL	*89.70 FL	
12	1		*FRONT BUMPER REINFORCEMENT	Bent	299.00 FL	*299.00 FL	
13	1		*FRONT RH HEADLAMP	Cracked	2,572.55 FL	*2,237.00 FL	
14	1		*WIPER WASHER TANK	Not Necessary	173.10 FL	*-FL	
15	1		*SET FRONT BUMPER CLIP	Necessary	30.00 FS	*30.00 FS	
16	1		*SET FRONT GRILLE CLIP	Not Necessary	20.00 FS	*-FS	
17	1		*SET FRONT LH FENDER INNER TRIM CLIP	Necessary	20.00 FS	*20.00 FS	
F=Fra	nchise	part. S=S	SpcNett. L=ListItemDisc.				
Sub Total (S\$)				6,333.40	3,945.40		
- List Item Discount on L Items 20.00/20.00% (S\$)				1,252.68	779.08		
				Total Parts (S\$)	5,080.72	3,166.32	
	Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
CHECK FRONT WIRING AND LIGHTING SYSTEM	New	60.00	30.00
COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT	New	150.00	0.00
PANEL BEATING ON AFFECTED AREAS	New	800.00	400.00
SPRAY PAINTING ON AFFECTED AREAS	New	800.00	400.00
APPLY ANTI RUST ON AFFECTED AREAS	New	100.00	30.00
Gros	s Labour Cost (S\$)	1,910.00	860.00
	OUR Items  CHECK FRONT WIRING AND LIGHTING SYSTEM COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT  PANEL BEATING ON AFFECTED AREAS SPRAY PAINTING ON AFFECTED AREAS APPLY ANTI RUST ON AFFECTED AREAS	CHECK FRONT WIRING AND LIGHTING SYSTEM New COMPUTERISED AND CHECK FRONT WHEEL New ALIGNMENT PANEL BEATING ON AFFECTED AREAS New SPRAY PAINTING ON AFFECTED AREAS New	CHECK FRONT WIRING AND LIGHTING SYSTEM New 60.00 COMPUTERISED AND CHECK FRONT WHEEL New 150.00 ALIGNMENT PANEL BEATING ON AFFECTED AREAS New 800.00 SPRAY PAINTING ON AFFECTED AREAS New 100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >